Facility	Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Used	Number ar Component Delay of R Give Expla Wh
Diane Davis	39.304018, -80.822877	10/18/2017	11:00	12:00	N.Summerfield	FLIR Certified	39	Clear	0	FLIR GF320	None	level controller regulator threads stainless connection	10/31/2017 10/18/2017 10/18/2017 10/18/2017	FLIR GF320	Non
		3/14/2018	11:10	12:15	N.Summerfield	FLIR Certified	27	Clear	5	AVO	Camera away for repairs	NO LEAKS FOUND	3/14/2018	None	N/A
		5/16/2018	11:30	12:30	N.Summerfield	FLIR Certified	72	Cloudy	5	FLIR GF320	None	plug threads supply line connections supply line connections stainless fitting thief hatch	6/13/2018 5/21/2018 5/25/2018 8/15/2018 8/15/2018	FLIR GF320	None
		8/15/2018	11:55	12:20	N.Summerfield	FLIR Certified	77	Clear	3	FLIR GF320	None			FLIR GF320	None
Dotson Holland	39.273397, -80.873101	10/23/2017	9:00	12:30	N.Summerfield	FLIR Certified	59	Cloudy	5	FLIR GF320	None	solenoid regulaltor (2) quick exhaust	12/4/2017 10/24/2017 11/21/2017	FLIR GF320	None
		2/14/2018	2:30	2:50	N.Summerfield	FLIR Certified	54	Cloudy	5	AVO	Camera away for repairs	NO LEAKS FOUND	2/14/2018	N/A	N/A
		5/10/2018	11:00	1:00	N.Summerfield	FLIR Certified	74	Clear	5	FLIR GF320	None	regulator (2) valve stainless fitting	5/31/2018 8/15/2018 8/9/2018	FLIR GF320 FLIR GF320	None None
		8/9/2018	12:35	1:15	N.Summerfield	FLIR Certified	78	Clear	5	FLIR GF320	None				
Edna Monroe	39.422656, -80.873174	11/9/2017	11:40	2:00	N. Summerfield	FLIR Certified	46	Clear	5	FLIR GF320	None	emergency/ thief hatch emergency/ thief hatch stainless connection (2) hammer union regulator (3) suction line connection Vent Bolt threads (2)	12/14/2017 11/9/2017 11/9/2017 11/9/2017 11/9/2017 11/9/2017 11/9/2017	FLIR GF320	None
		3/26/2018	13:15	Not Recorded	A.Rafuse	FLIR Certified	52	Clear	5	AVO	Camera away for repairs	NO LEAKS FOUND	3/26/2018	None	None
		4/26/2018	8:00	9:30	N. Summerfield	FLIR Certified	40	Clear	5	FLIR GF320	None	hammer union threads level controller gauge stainless fitting regulator (2)	5/7/2018 5/1/2018 4/26/2018 4/26/2018 4/26/2018	FLIR GF320	None
		7/18/2018	7:50	9:30	N. Summerfield	FLIR Certified	7/18/2018	Clear	3	FLIR GF320	None	regulator thief hatch plug threads Enardo Valve emergency hatch (3)	7/18/2018 7/18/2018 7/18/2018 7/18/2018 7/18/2018	FLIR GF320	None
Edwin	39.23051, -80.903001	10/30/2017	12;15	1:30	N.Summerfield	FLIR Certified	45	Cloudy	10	FLIR GF320	None	stainless connections (2) Bleeder valve valve stainless connection threads (2)	11/27/2017 11/27/2017 11/27/2017 10/30/2017 10/30/2017	FLIR GF320	None
		3/22/2018	12:25	Not Recorded	N.Summerfield	FLIR Certified	33	Cloudy	3	AVO	Camera away for repairs	NO LEAKS FOUND	3/22/2018	N/A	N/A
		5/3/2018	11:15	2:30	N.Summerfield	FLIR Certified	75	Clear	15	FLIR GF320	None	Combustor smoking quick exhaust (3) hammer union	5/23/2018 8/2/2018 8/1/2018	FLIR GF320 FLIR GF320	None None
		8/1/2018	10:40	12:00	N.Summerfield	FLIR Certified	69	Cloudy	5	FLIR GF320	None				
Estlack	39.414027, -	11/10/2017	8:30	10:30	N.Summerfield	FLIR Certified	32	Clear	10	FLIR GF320	None	regulator (2) stainless (3) valve	11/20/2017 11/10/2017 [illegible]	FLIR GF320	[illegible]
		3/26/2018	1:40	Not Recorded	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]