4-19-85

From: Bob Holtz

To: File

An inspection of the BROS site on 4-19-85 revealed that Tank #69 had a small oil leak from a standpipe that extends from the pontoon at the N W corner. The leak stopped, however, about 4 hours after it was initially spotted. ERB was notified of the situation. This tank should be carefully inspected.

The lagoon water level seem to increase. It appeared to be 6 feet from the top.

227103



FIGURE 3-24

TANK AND DRUM LOCATION
BRIDGEPORT RENTAL & OIL SERVICES, LOGAN TWP., NJ

NUS CORPORATION
A Halliburton Company