SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00073

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Chrome
EPA NO. [illegible]
ADDRESS [illegible]
CITY, STATE, ZIP CODE Santa Fe Springs, Calif.
PHONE NO. [illegible]
ORDER PLACED BY [illegible] ORDER DATE [illegible]
P. O. / CONTRACT NO. [illegible]

③ DESIGNATED TSD FACILITY
(AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME Environmental Protection Corp.
EPA NO. [illegible]
ADDRESS Westside Disposal
CITY, STATE, ZIP CODE Fellows, Calif.
PHONE NO. (805) 327-4681

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE			60	[illegible]	DRUMS / BAGS / CARTONS / DUMP TRUCK
WASTE					TANK TRUCK / OTHER

⑥ WASTE CATEGORY 56
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS [illegible]

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS			CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS
A	Chromic Acid			5 %	PPM	E			% PPM
B	Water			95 %	PPM	F			% PPM
C				%	PPM	G			% PPM
D				%	PPM				

NONHAZARDOUS MATERIAL %

⑩ WASTE PROPERTIES: PH 1 ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☑ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☑ GLOVES ☑ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 7944
UNIT NO. [illegible]

⑮ PICK-UP DATE 2-18-81
TIME [illegible] ☐ AM ☒ PM

⑯ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME [illegible]
EPA NO. [illegible]

⑱ QUANTITY (IF MEASURED) [illegible]
⑲ STATE FEE (IF ANY) $

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☒ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — 2-19-81 DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stratford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period. (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00182

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Chrome
EPA NO. C A D 0 0 9 3 7 1 7 2 7
ADDRESS 22 9132 Dice Rd.
CITY, STATE, ZIP CODE Santa Fe Springs, Calif.
PHONE NO. 698 9791
ORDER PLACED BY John ORDER DATE 9/13
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)

NAME Environmental Protection Corp.
EPA NO. C A D 0 0 0 0 0 0 0 0 0 0 0 0
ADDRESS Vanderlie Disposal
CITY, STATE, ZIP CODE Bakersfield, Calif.
PHONE NO. 805-327-9669

④ ALTERNATE TSD FACILITY

NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Hydrochloric Acid	Corrosive			5 Drums	☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☐ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY

⑦ EX. HAZ. WASTE PERMIT NO.

⑧ GENERATING PROCESS Acid

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	Hydrochloric Acid			☐	☐
B	Water			☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 8052
UNIT NO. 1

⑮ PICK-UP DATE 9/13/83
TIME 8:00 ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME Bakersfield Recycling
EPA NO. C A D 0 9 9 0 0 1 0 2 9 3

⑱ QUANTITY (IF MEASURED) 4 drums

⑲ STATE FEE (IF ANY) $ 40.00

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 9-21-83

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1.	Acid sludge	14.	Bilge water	27.	FCC waste	40.	Ink wastewater	53.	Phenolic waste	65.	Solvent, oxygenated
2.	Acid solution	15.	Blasting sand	28.	Filter cake	41.	Laboratory chemicals	54.	Photoprocessing waste	66.	Solvent, mixed
3.	Adhesive	16.	Capacitors, PCB	29.	Filters, spent	42.	Lime sludge	55.	Plating sludge	67.	Spill cleanup residue
4.	Alkaline sludge	17.	Catalyst	30.	Flux	43.	Machine tool coolant	56.	Plating solution, acid	68.	Stretford solution
5.	Alkaline solution	18.	Chemicals, unused	31.	Fly ash	44.	Machining waste	57.	Plating solution, alkaline	69.	Sulfide sludge
6.	Alkali solids	19.	Containers, empty	32.	Gasoline and water	45.	Metal dust	58.	Polychlorinated biphenyls (PCB)	70.	Sump or lagoon sediment
7.	Alum sludge	20.	Contaminated equipment	33.	Glaze sludge	46.	Oil	59.	Resin waste	71.	Tank bottom sediment
8.	API separator sludge	21.	Contaminated oil	34.	Glue	47.	Oil sludge	60.	Scrubber sludge	72.	Tanning sludge
9.	Asbestos solids	22.	Cyanides	35.	Hair pulp	48.	Oil and water	61.	Scrubber solution	73.	Tetraethyl lead sludge
10.	Asbestos sludge	23.	Detergent	36.	Heavy metal solution	49.	Paint sludge	62.	Soap	74.	Transformers, PCB
11.	Ashes	24.	Distillation bottoms	37.	Heavy metal sludge	50.	Pesticides	63.	Solvent, chlorinated	75.	Waste water treatment sludge
12.	ASD filter cake	25.	Drilling mud	38.	Ink and solvent	51.	Pesticide containers	64.	Solvent, hydrocarbon		
13.	Baghouse waste	26.	Drugs								

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00223

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electroplate Chrome
EPA NO. C A D 0 0 8 2 7 9 2 7
ADDRESS 913 Pine St.
CITY, STATE, ZIP CODE Santa Fe Springs, Calif.
PHONE NO. 213-868-0781
ORDER PLACED BY Order Desk ORDER DATE 7/15/81
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME PPI
EPA NO.
ADDRESS Westside Disposal
CITY, STATE, ZIP CODE Bellflower, Calif.
PHONE NO. 805-327-0581

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Chromic acid			50 gals		DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK ☐
WASTE					TANK TRUCK ☒ OTHER ☐

⑥ WASTE CATEGORY 2
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	Chromic acid		10	☒	☐
B	Water		90	☒	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH 2 ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☒ GLOVES ☒ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802.

⑬ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 8-14-81

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 1 0146
UNIT NO. 1

⑮ PICK-UP DATE 8/14/81
TIME 8:00 ☒ AM ☐ PM

⑯ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME Westside Disposal Bellflower CA
EPA NO. C A D 0 0 8 2 7 9 2 7

⑱ QUANTITY (IF MEASURED) 50 gal
⑲ STATE FEE (IF ANY) $

⑳ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☒ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉑ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 8-16-81

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformer, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 183 - 00245

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Unique
EPA NO.
ADDRESS 2132 Wagner Way
CITY, STATE, ZIP CODE Santa Fe Springs, Calif.
PHONE NO. 213-698-0791
ORDER PLACED BY John ORDER DATE 7/8/79
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)

NAME
EPA NO.
ADDRESS Montebello Division
CITY, STATE, ZIP CODE Bellflower, Calif.
PHONE NO. 805-327-0533

④ ALTERNATE TSD FACILITY

NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Corrosive Acid			1 Drum		☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☒ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY Inorganic Acid
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS Etching

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	LOWER	UNITS %	PPM
A	Inorganic Acid			☒	☐
B	Water			☒	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH 2 ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☒ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802.

⑬ [illegible] — SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 7-16-79

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO. 2

⑮ PICK-UP DATE 7-16-79
TIME ____ ☐ AM ☒ PM

⑯ [illegible] — SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME E.P.C. Westside Disp.
EPA NO.

⑱ QUANTITY (IF MEASURED) 18 Drums
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☒ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ [illegible] — SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 7/16/79

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00285

GENERATOR (GENERATOR MUST COMPLETE)

② NAME [illegible]
EPA NO. [illegible]
ADDRESS [illegible]
CITY, STATE, ZIP CODE [illegible]
PHONE NO. [illegible]
ORDER PLACED BY [illegible] ORDER DATE [illegible]
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME [illegible]
EPA NO. [illegible]
ADDRESS [illegible]
CITY, STATE, ZIP CODE [illegible]
PHONE NO. [illegible]

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE [illegible]			[illegible]		☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☒ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY [illegible]
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS [illegible]

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	[illegible]			☒	☐
B	[illegible]		[illegible]	☒	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL [illegible] %

⑩ WASTE PROPERTIES: PH [illegible] ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN
⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER
⑫ SPECIAL HANDLING INSTRUCTIONS: ☒ GLOVES ☒ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802.

⑬ [illegible] — SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED [illegible]

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. CAD056421779
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. [illegible]
UNIT NO. [illegible]

⑮ PICK-UP DATE [illegible]
TIME [illegible] ☐ AM ☒ PM

⑯ [illegible]
SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME [illegible]
EPA NO.
⑱ QUANTITY (IF MEASURED) [illegible]
⑲ STATE FEE (IF ANY) $

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉑ [illegible] — SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED [illegible]

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API seperator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetracthyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00306

GENERATOR (GENERATOR MUST COMPLETE)

② NAME ELECTRONIC CHROME
EPA NO. C A D 0 0 8 2 0 1 0 0 7
ADDRESS 8100 [illegible] RD
CITY, STATE, ZIP CODE SANTA FE SPRINGS
PHONE NO. 947-7929
ORDER PLACED BY [illegible] ORDER DATE [illegible]
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME CDS
EPA NO. C A D 0 0 4 8 0 1 0 0 7
ADDRESS W. [illegible] AVENUE
CITY, STATE, ZIP CODE DELANO CA
PHONE NO. [illegible]

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE CHROMIC ACID	CORROSIVE			BOBLS	DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE	NOS				TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY CL
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS PLATING

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	LOWER	UNITS %	PPM
A	CHROMIC ACID	[illegible]		☐	☐
B	WATER	97		☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH [illegible] ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN
⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER
⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 10-27-81

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. [illegible]
UNIT NO. [illegible]

⑮ PICK-UP DATE 10-27-81
TIME [illegible] ☒ AM ☐ PM

⑯ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME [illegible]
EPA NO.

⑱ QUANTITY (IF MEASURED) [illegible]
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glass sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 122 - 01378

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Mechanic Chrome
EPA NO. C A D 0 [illegible]
ADDRESS 9120 Dice Rd.
CITY, STATE, ZIP CODE Santa Fe Springs, Calif. 90670
PHONE NO. 698 9907
ORDER PLACED BY John ORDER DATE 10/26
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME BTC
EPA NO. C A [illegible]
ADDRESS Westside Highway
CITY, STATE, ZIP CODE Bakersfield, Ca.
PHONE NO. (805) 392-2021

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Chromic Acid	Corrosive (UN)		10		DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☒ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY 55
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS Plating

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	Chromic Acid	5		☒	☐
B	Water	95		☒	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☒ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ [signature] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 10-27-91

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 5360
UNIT NO. 5

⑮ PICK-UP DATE 10/27/91
TIME 2:30 ☐ AM ☒ PM

⑯ [signature] SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME Elk Hills Oil Recovery
EPA NO. C A [illegible]

⑱ QUANTITY (IF MEASURED) 10 m³
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☒ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ [signature] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 10-27-91

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetracthyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00337

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Chemicals
EPA NO. CAD005974027
ADDRESS 9132 Dice St.
CITY, STATE, ZIP CODE Santa Fe Springs
PHONE NO.
ORDER PLACED BY ORDER DATE
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME SRC
EPA NO. CAT080010203
ADDRESS Chestnut Avenue
CITY, STATE, ZIP CODE Fellows Cal.
PHONE NO. 805-327-7681

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Hydrochloric Acid	Corrosive		1000		☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE "	Acid				☒ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY 2
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS Etching

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	LOWER	UNITS %	PPM
A	Hydrochloric Acid			☒	☐
B	DI Water			☒	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH 1 ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN
⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER
⑫ SPECIAL HANDLING INSTRUCTIONS: ☒ GLOVES ☒ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ [signature] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 12-2-81

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. CAD056421779
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 8451
UNIT NO. 6

⑮ PICK-UP DATE 12-2-81
TIME 1:00 ☐ AM ☒ PM

⑯ [signature] Driver
SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME ECC Chestnut Ave Fellows Cal
EPA NO. CAT080010203
⑱ QUANTITY (IF MEASURED) 1000 L
⑲ STATE FEE (IF ANY) $
⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☒ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

Pit Cap

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ [signature] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 12-6-81

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stratford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API seperator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetrethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASO filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 00338

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Chrome
EPA NO. CAD008291427
ADDRESS 9132 Dice Rd.
CITY, STATE, ZIP CODE Santa Fe Springs
PHONE NO. 312-698-9791
ORDER PLACED BY John ORDER DATE
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY
(AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME EPC
EPA NO. CAD008041423
ADDRESS West Side Disposal
CITY, STATE, ZIP CODE Fellows Calif
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Chromic Acid	Corrosive		40 Bbls		DRUMS / BAGS / CARTONS / DUMP TRUCK
WASTE	NOS				X TANK TRUCK / OTHER

⑥ WASTE CATEGORY 2
⑦ EX. HAZ. WASTE PERMIT NO. 182
⑧ GENERATING PROCESS Plating

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	Chromic				
B	Water				
C					
D					
E					
F					
G					

NONHAZARDOUS MATERIAL %

⑩ WASTE PROPERTIES: PH 2 ☐ TOXIC ☐ FLAMMABLE ☒ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☒ GLOVES ☒ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ John Allenworth — SIGNATURE OF AUTHORIZED AGENT & TITLE — 12-16-81 DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. CAD056421779
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 8456
UNIT NO. 25

⑮ PICK-UP DATE 12-16-81
TIME 7:00 ☒ AM ☐ PM

⑯ [signature] Driver
SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

PH 0.0 F-92 EPC# 17814

⑰ NAME EPC Westside Disp.
EPA NO. CAD008041423

⑱ QUANTITY (IF MEASURED) 40 bbls
⑲ STATE FEE (IF ANY) $

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☒ TREATMENT (SPECIFY) Neutralization
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ [signature] — SIGNATURE OF AUTHORIZED AGENT & TITLE — 12-18-81 DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stratford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986)

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY ORDER DATE
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					DRUMS / BAGS / CARTONS / DUMP TRUCK
WASTE					TANK TRUCK / OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A					
B					
C					
D					
E					
F					
G					

NONHAZARDOUS MATERIAL %

⑩ WASTE PROPERTIES: PH ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK UP DATE
TIME ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6)

1	Acid sludge	14	Bilge water	27	FCC waste	40	Ink wastewater	53	Phenolic waste	65	Solvent, oxygenated
2	Acid solution	15	Blasting sand	28	Filter cake	41	Laboratory chemicals	54	Photoprocessing waste	66	Solvent, mixed
3	Adhesive	16	Capacitors, PCB	29	Filters, spent	42	Lime sludge	55	Plating sludge	67	Spill cleanup residue
4	Alkaline sludge	17	Catalyst	30	Flux	43	Machine tool coolant	56	Plating solution, acid	68	Stretford solution
5	Alkaline solution	18	Chemicals, unused	31	Fly ash	44	Machining waste	57	Plating solution, alkaline	69	Sulfide sludge
6	Alkali solids	19	Containers, empty	32	Gasoline and water	45	Metal dust	58	Polychlorinated biphenyls (PCB)	70	Sump or lagoon sediment
7	Alum sludge	20	Contaminated equipment	33	Glaze sludge	46	Oil	59	Resin waste	71	Tankbottom sediment
8	API separator sludge	21	Contaminated oil	34	Glue	47	Oil sludge	60	Scrubber sludge	72	Tanning sludge
9	Asbestos solids	22	Cyanides	35	Hair pulp	48	Oil and water	61	Scrubber solution	73	Tetraethyl lead sludge
10	Asbestos sludge	23	Detergent	36	Heavy metal solution	49	Paint sludge	62	Soap	74	Transformers, PCB
11	Ashes	24	Distillation bottoms	37	Heavy metal sludge	50	Pesticides	63	Solvent, chlorinated	75	Waste water treatment sludge
12	ASD filter cake	25	Drilling mud	38	Ink and solvent	51	Pesticide containers	64	Solvent, hydrocarbon		
13	Baghouse waste	26	Drugs								

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY
ORDER DATE
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					DRUMS / BAGS / CARTONS / DUMP TRUCK
WASTE					TANK TRUCK / OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A					
B					
C					
D					
E					
F					
G					

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D O 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated oil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
40. Ink wastewater
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls (PCB)
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stratford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching)

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies	
Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
Copy Number 2	To Transporter after signed by TSDF
Copy Number 3	To Generator from TSDF
Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY ORDER DATE
P. O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					DRUMS / BAGS / CARTONS / DUMP TRUCK
WASTE					TANK TRUCK / OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A					
B					
C					
D					
E					
F					
G					

NONHAZARDOUS MATERIAL %

⑩ WASTE PROPERTIES: PH ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK UP DATE
TIME ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated oil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink wastewater
40. Ink wastewater
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Phenolic waste
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls (PCB)
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawfull for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986)

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY — ORDER DATE
P. O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☐ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY
⑦ EX-HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A				☐	☐
B				☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D O 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME ____ ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glues	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASO filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: aircraft/aerospace [illegible] contaminated reactor cleaning, DDT production, alkylation, printed circuit board etching)

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981 it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and the found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to or instead of land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY — ORDER DATE
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☐ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A				☐	☐
B				☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste category in Item 6)

1. Acid sludge	14. Bilge water	27. [illegible]	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. [illegible]	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Grease sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Resin	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Kraft pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Lime/metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching)

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period. (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986)

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or, as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies:		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY — ORDER DATE
P.O./CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☐ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A				☐	☐
B				☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D O 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME ____ ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below).

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY
ORDER DATE
P. O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK
WASTE					☐ TANK TRUCK ☐ OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	LOWER	UNITS %	PPM
A				☐	☐
B				☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL ____ %

⑩ WASTE PROPERTIES: PH ____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME ☐ AM ☐ PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1. Acid sludge	14. Bilge water	27. FCC waste	40. Ink wastewater	53. Phenolic waste	65. Solvent, oxygenated
2. Acid solution	15. Blasting sand	28. Filter cake	41. Laboratory chemicals	54. Photoprocessing waste	66. Solvent, mixed
3. Adhesive	16. Capacitors, PCB	29. Filters, spent	42. Lime sludge	55. Plating sludge	67. Spill cleanup residue
4. Alkaline sludge	17. Catalyst	30. Flux	43. Machine tool coolant	56. Plating solution, acid	68. Stretford solution
5. Alkaline solution	18. Chemicals, unused	31. Fly ash	44. Machining waste	57. Plating solution, alkaline	69. Sulfide sludge
6. Alkali solids	19. Containers, empty	32. Gasoline and water	45. Metal dust	58. Polychlorinated biphenyls (PCB)	70. Sump or lagoon sediment
7. Alum sludge	20. Contaminated equipment	33. Glaze sludge	46. Oil	59. Resin waste	71. Tank bottom sediment
8. API separator sludge	21. Contaminated oil	34. Glue	47. Oil sludge	60. Scrubber sludge	72. Tanning sludge
9. Asbestos solids	22. Cyanides	35. Hair pulp	48. Oil and water	61. Scrubber solution	73. Tetraethyl lead sludge
10. Asbestos sludge	23. Detergent	36. Heavy metal solution	49. Paint sludge	62. Soap	74. Transformers, PCB
11. Ashes	24. Distillation bottoms	37. Heavy metal sludge	50. Pesticides	63. Solvent, chlorinated	75. Waste water treatment sludge
12. ASD filter cake	25. Drilling mud	38. Ink and solvent	51. Pesticide containers	64. Solvent, hydrocarbon	
13. Baghouse waste	26. Drugs				

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste. (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER 182 - 01337

GENERATOR (GENERATOR MUST COMPLETE)

② NAME Electronic Chrome
EPA NO. C A D 0 0 5 9 9 1 1 1 1 1
ADDRESS 1532 Rose St.
CITY, STATE, ZIP CODE Santa Fe Springs
PHONE NO.
ORDER PLACED BY ORDER DATE
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)

NAME Chemical Waste Management
EPA NO. C A D 0 0 7 3 7 0 1 1 1 1
ADDRESS Chemical Waste Management
CITY, STATE, ZIP CODE Kettleman City, Calif.
PHONE NO. 209 386-9711

④ ALTERNATE TSD FACILITY

NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE Hydroxide Acid	Corr.		1000		☐ DRUMS ☐ BAGS ☐ CARTONS ☐ DUMP TRUCK ☐ TANK TRUCK ☐ OTHER
WASTE	Liq.				

⑥ WASTE CATEGORY 5 ⑦ EX. HAZ. WASTE PERMIT NO. ⑧ GENERATING PROCESS Plating

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A	Chromic Acid			☐	☐
B	Water			☐	☐
C				☐	☐
D				☐	☐
E				☐	☐
F				☐	☐
G				☐	☐

NONHAZARDOUS MATERIAL % ⑩ WASTE PROPERTIES: PH 1 ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

⑪ PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER

⑫ SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802.

⑬ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED 12-2-81

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D 0 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO. 8451
UNIT NO. 6

⑮ PICK-UP DATE 12-2-81
TIME 7:00 ☐ AM ☐ PM

⑯ [illegible] Driver SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME Chemical Waste Management
EPA NO.

⑱ QUANTITY (IF MEASURED) 1000 Gals
⑲ STATE FEE (IF ANY) $

㉑ HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE ☐ STORAGE/TRANSFER

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ [illegible] SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED 12-4-81

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1.	Acid sludge	14.	Bilge water	27.	FCC waste	40.	Ink wastewater	53.	Phenolic waste	65.	Solvent: oxygenated
2.	Acid solution	15.	Blasting sand	28.	Filter cake	41.	Laboratory chemicals	54.	Photoprocessing waste	66.	Solvent: mixed
3.	Adhesive	16.	Capacitors, PCB	29.	Filters, spent	42.	Lime sludge	55.	Plating sludge	67.	Spill cleanup residue
4.	Alkaline sludge	17.	Catalyst	30.	Flux	43.	Machine tool coolant	56.	Plating solution, acid	68.	Stretford solution
5.	Alkaline solution	18.	Chemicals, unused	31.	Fly ash	44.	Machining waste	57.	Plating solution, alkaline	69.	Sulfide sludge
6.	Alkali solids	19.	Containers, empty	32.	Gasoline and water	45.	Metal dust	58.	Polychlorinated biphenyl (PCB)	70.	Sump or lagoon sediment
7.	Alum sludge	20.	Contaminated equipment	33.	Glaze sludge	46.	Oil	59.	Resin waste	71.	Tank bottom sediment
8.	API separator sludge	21.	Contaminated oil	34.	Glue	47.	Oil sludge	60.	Scrubber sludge	72.	Tanning sludge
9.	Asbestos solids	22.	Cyanides	35.	Hair pulp	48.	Oil and water	61.	Scrubber solution	73.	Tetraethyl lead sludge
10.	Asbestos sludge	23.	Detergent	36.	Heavy metal solution	49.	Paint sludge	62.	Soap	74.	Transformers, PCB
11.	Ashes	24.	Distillation bottoms	37.	Heavy metal sludge	50.	Pesticides	63.	Solvent: chlorinated	75.	Waste water treatment sludge
12.	ASD filter cake	25.	Drilling mud	38.	Ink and solvent	51.	Pesticide containers	64.	Solvent: hydrocarbon		
13.	Baghouse waste	26.	Drugs								

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899-001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

SEE REVERSE SIDES FOR INSTRUCTIONS. PLEASE TYPE, OR PRINT CLEARLY.

PRESS HARD

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

① MANIFEST NUMBER

GENERATOR (GENERATOR MUST COMPLETE)

② NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.
ORDER PLACED BY ORDER DATE
P.O. / CONTRACT NO.

③ DESIGNATED TSD FACILITY (AUTHORIZED TO OPERATE UNDER AN APPROVED STATE OR FEDERAL PROGRAM)
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

④ ALTERNATE TSD FACILITY
NAME
EPA NO.
ADDRESS
CITY, STATE, ZIP CODE
PHONE NO.

⑤ U. S. DOT PROPER SHIPPING NAME	U. S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS	CONTAINERS: NUMBER
WASTE					DRUMS, BAGS, CARTONS, DUMP TRUCK
WASTE					TANK TRUCK, OTHER

⑥ WASTE CATEGORY
⑦ EX. HAZ. WASTE PERMIT NO.
⑧ GENERATING PROCESS

⑨ LIST COMPONENTS:

		CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
A				%	PPM
B				%	PPM
C				%	PPM
D				%	PPM
E				%	PPM
F				%	PPM
G				%	PPM

NONHAZARDOUS MATERIAL %

⑩ WASTE PROPERTIES: PH TOXIC FLAMMABLE CORROSIVE/IRRITANT REACTIVE SENSITIZER CARCINOGEN/MUTAGEN
⑪ PHYSICAL STATE: SOLID LIQUID SLUDGE SLURRY GAS OTHER
⑫ SPECIAL HANDLING INSTRUCTIONS: GLOVES GOGGLES RESPIRATOR OTHER

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED & LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND THE EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U. S. COAST GUARD 1-800-424-8802.

⑬ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE SHIPPED

TRANSPORTER (HAULER MUST COMPLETE)

⑭ NAME J & M FILTERING
EPA NO. C A D O 5 6 4 2 1 7 7 9
ADDRESS 12524 TELEGRAPH ROAD
CITY, STATE ZIP CODE SANTA FE SPRINGS, CA 90670
PHONE NO (213) 944-1011

JOB NO.
UNIT NO.

⑮ PICK-UP DATE
TIME AM PM

⑯ SIGNATURE OF AUTHORIZED AGENT & TITLE

TSD FACILITY (OPERATOR MUST COMPLETE)

⑰ NAME
EPA NO.

⑱ QUANTITY (IF MEASURED)
⑲ STATE FEE (IF ANY) $

⑳ INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT

㉑ HANDLING OR DISPOSAL METHOD:
SURFACE IMPOUNDMENT
LANDFILL
INJECTION WELL
LAND TREATMENT
TREATMENT (SPECIFY)
RECOVERY OR REUSE
STORAGE/TRANSFER

㉒ IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
NAME
EPA NO.

㉓ SIGNATURE OF AUTHORIZED AGENT & TITLE — DATE ACCEPTED

REVISED 11/80

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR

Item 1. Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER Item 1 below)

Item 2-4. Provide the complete names, EPA I.D. numbers, addresses, and telephone numbers of the generator and designated TSD facilities.

Item 5. Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

Item 6. Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately described your waste, write the waste's category in Item 6).

1.	Acid sludge	14.	Bilge water	27.	FCC waste	40.	Ink wastewater	53.	Phenolic waste	65.	Solvent, oxygenated
2.	Acid solution	15.	Blasting sand	28.	Filter cake	41.	Laboratory chemicals	54.	Photoprocessing waste	66.	Solvent, mixed
3.	Adhesive	16.	Capacitors, PCB	29.	Filters, spent	42.	Lime sludge	55.	Plating sludge	67.	Spill cleanup residue
4.	Alkaline sludge	17.	Catalyst	30.	Flux	43.	Machine tool coolant	56.	Plating solution, acid	68.	Stretford solution
5.	Alkaline solution	18.	Chemicals, unused	31.	Fly ash	44.	Machining waste	57.	Plating solution, alkaline	69.	Sulfide sludge
6.	Alkali solids	19.	Containers, empty	32.	Gasoline and water	45.	Metal dust	58.	Polychlorinated biphenyls (PCB)	70.	Sump or lagoon sediment
7.	Alum sludge	20.	Contaminated equipment	33.	Glaze sludge	46.	Oil	59.	Resin waste	71.	Tank bottom sediment
8.	API separator sludge	21.	Contaminated oil	34.	Glue	47.	Oil sludge	60.	Scrubber sludge	72.	Tanning sludge
9.	Asbestos solids	22.	Cyanides	35.	Hair pulp	48.	Oil and water	61.	Scrubber solution	73.	Tetraethyl lead sludge
10.	Asbestos sludge	23.	Detergent	36.	Heavy metal solution	49.	Paint sludge	62.	Soap	74.	Transformers, PCB
11.	Ashes	24.	Distillation bottoms	37.	Heavy metal sludge	50.	Pesticides	63.	Solvent, chlorinated	75.	Waste water treatment sludge
12.	ASO filter cake	25.	Drilling mud	38.	Ink and solvent	51.	Pesticide containers	64.	Solvent, hydrocarbon		
13.	Baghouse waste	26.	Drugs								

Item 7. If the waste is extremely hazardous, provide the State extremely hazardous permit number.

Item 8. Indicate the process, activity, or operation which generated the waste (Examples: air craft cleaning, insulation stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

Item 9. Information must be provided in Item 9. Do not leave blank. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

Item 10-11. Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive), check all appropriate properties. If the waste is an aqueous liquid, the pH must be reported in Item 11.

Item 12. Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

Item 13. Sign the manifest, provide your title and the date that the waste was removed from your facility. The persons signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. It is unlawful for a transporter who is not the generator to sign Item 13.

TRANSPORTER

Item 1. Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The last six digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899 001000. The complete nine digit manifest number shall be unique for any 5 year period (Example: If you use manifest number 899 001000 on May 31, 1981, it should not be used on a manifest again before June 1, 1986).

Item 14. Enter company name, EPA I.D. number, address, and telephone number.

Item 15. Indicate the date and exact time the waste was removed from the generator's facility.

Item 16. Sign the manifest upon receipt of the shipment.

The driver shall carry a copy of the manifest in a location prescribed in 49CFR 177.817(e).

TSD FACILITY OPERATOR

Item 17. Provide the TSD facility name and EPA I.D. number.

Item 18. If the quantity of waste is measured or estimated at the TSD facility (e.g. weighed), indicate the quantity.

Item 19. If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

Item 20. Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, vehicle type). Some significant discrepancies are described in 40CFR 264.72.

Item 21. Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

Item 22. If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility, and its EPA I.D. number. In such cases, you, as the facility (transfer station) operator, shall fill out a new master manifest indicating your facility as the generator of the waste and describing all wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

Item 23. Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS on a monthly basis or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send a copy of each master manifest to DOHS with copies of all original manifests stapled to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

Distribution of Manifest Copies		
	Copy Number 1 (original)	TSDF keeps (send photocopy to DOHS)
	Copy Number 2	To Transporter after signed by TSDF
	Copy Number 3	To Generator from TSDF
	Copy Number 4	Generator keeps after signed by Transporter (send photocopy to DOHS)

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.