ORIGINAL
(Red)
SDMS DocID 2205030

For Correspondence

See Next File

(Includes Trip Report)

ORIGINAL (Red)

(301-355-6400) 5/30/80

Daryl Palmer called on FMC to discuss three questions left unresolved at our May 15, 1980 meeting.

1.) 39,000 tons of the 45,000 tons listed were incinerated on site. This material did not go directly to the fill area.

2.) most of the waste was in drums, some sealed, some not. Mostly polymerized tars & resins - hardened sludges. Very few liquids if any were disposed of in the fill. In earlier years the common practice was to dump liquids into the sewers.

3.) trace heavy metals may exist in the fill area. Small amounts probably from cooling tower sludges, probably less than 0.10% Chrome.

? NPDES § 308 CWA

33 USC 1318

~~ORIGINAL~~
(Red)

RCRA

§ 3007

42 USC 6927

make us get an
admin. search warrant

Tony

Fuscaldo

Fuscaldo

Dr. Tony

ORIGINAL
(Red)

Intermediate organic chemicals manufacture
& pesticides
plasticizers
Contracted
~~Stesco~~ Secos - SCA BFI
manifested - state regs complied with
(DHS as an incinerator now)
3 yr files maintained
≈ 80 plants nationally
Salley Rd - trash, etc.
(early 70's Robb Tyler) some H.W.
Rollins Envir.

USI 1914 (Molasses)(Gun powder; alcohol)
National Distillers
FMC (1956)
Majority of organics

the plant has a french drain system (surface water)
all ground water drain to plant sewer system
regulated by NPDES.
adequacy of collection system?
DNR may require monitoring
(dirt)
(capped site) (asbestos - demolition)

ORIGINAL
(Red)

Daryl will review Eckhardt listing
and send info to Reg III

~~testing~~ of landfill flow from ~~land~~ surface leach

Dick Sabrowski

Chuck?

ORIGINAL (Red)

Sites to Visit

WRA - ask about Cumberland Field office address & phone #

(3) A-023

MD-17 FMC - 1701 Patapsco Ave. Baltimore

MD-14 (3) OLIN CORPORATION Curtis Bay Plant (Remington Ave.) Balt.

MD-21 (2) KOPPERS - Foot of Childs St. FAIRFIELD } NPDES

(Ernie Relinck)

Thurs. 1:00 (FMC)

Fri: 9:00 (OLIN) 1:00 KOPPERS

Frank Henderson

EHA

Paul Stoner

Jim Curtis

355-6400 - ext 263

Thurs. 11:00 FMC

set up to meet there

Daryl Palmer - Envi Eng. (269-3823)

Lou Martino } WRA
Paul Stoner }

355-1770

Olin John Erickson
Mr. Warren

Koppers Datum Lot (leased)
outside the tunnel on Right

678 No longer

736 - 4781

Ken Weiss

ORIGINAL (Red)

MD - 10

17

51

70

71

72

15 ?

X 3123

P.2-4 ¶3 line 4 Ponce to Reance

add 3RD FMC letter

P.3.2 & 3.3 How to handle #13

what confidence level could we say 1 ppb 2 ppb

FMC Report

① P.1-2 ¶4 results to results line 1

② line 2 1,2 to 12

MD-02-13 is being redone

③ P.1-2 last sentence ☆ How do we handle this. See P.3-2 (3.2.1.2) Qualifier & Findings

④ P.2-5, ¶2 line 4 basis to basin

ORIGINAL (Red)

don't know how high [illegible] see indicator No value limits

⑤ P.2-8 ¶4 line 2 CERCCA to CERCLA

⑥ P.2-9 line 2 surfact to surface

⑦ P.2-10, ¶2, line 3 chain-of-custody to chain-of-custody

Envirodyne will do 14 days

⑧ P.2-9 I believe sample M-02-12 and M-02-13 are reversed. M-02-12 was SE corner of Bldg 34 & M-02-13 was under stairs.

call if want faster = would

⑨ P.2-10, ¶2, line 5, protocals to protocols

⑩ Appendix A = line 17 change is to if

⑪ Duplicate results not

ORIGINAL
(Red)

NO OTHER INFO

- hydrazine in 75 for USAF

8201-05-06