3/21/83

(1) ~~Douglas Co. PUD~~

(b) (6) [redacted]

~~Re: A new Process for eliminating PCB oil~~

Public Affairs Consultants

(2) (b) (6) [redacted]

Re: Jorgenson Steel – Seattle
Baghouse dust @ plant
is EP Toxic for lead
(only recently became aware ?!)

Call → (b) (6) [redacted]

Find out details
- where has it gone in past
- how long
- when did they find out it failed EP Tox
- What are they doing w/it now
- how much per month
- how is it packaged
- Who have they notified
- etc.
- etc.

Don Krueger
John ~~Connelly~~ Conroy

USEPA RCRA
3014017

Jorgensen Steel

Burning steel balls
(mud balls)
use to be picked
up & taken away.
Recently pick-up
was stopped &
(b) (6) [redacted] was
told to throw the
waste into furnance
(b) (6) [redacted]
– wa[redacted]isko
that this substance
should not be burned

WAD000602813
– gives off bad smell