7-30-82

6

EPA Unc. Sites Position on Litton

1. Need gw monitoring

2. If baseline EP TOXICITY level is at ~~0.5~~ what MONR proposed ppm need total samples sampling throughout pond for ~~Pb & Cr.~~ metals of concern. Don't go overboard on number of samples just get a reasonable number (5-10?)

3. background level Pb ≈ 30 ppm
check other metals (MGS)
acceptable total level of Pb
maybe. Each site is different. 500 ppm or less

4. depth of samples 4"-6"
if first layer (surface) samples indicate l.t. baseline levels ok no further samples at greater depth are needed.
If above baseline levels, need to sample 1½ - 2 ft at 4"-6" intervals ~~deeper~~ & check levels of contamination

R00337327
RCRA RECORDS CENTER