SEMS DocID 2343199

ARCO petroleum products

R1P8

F3 8807-17

PA-781

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO Petroleum
Products
F3 8807-17
PA-781

RIP10

Pan of impoundment

8/4/88
11:09

[redacted]

Not responsive due to revised scope

ARCO petroleum products

F3 8807-17

PA-781

RIP10

Pan of impoundment

8/4/88

11:09

[redacted]

Not responsive due to revised scope

ARCO petroleum
products
F3 8807-17
PA-781

R1P10

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88
11:09

ARCO Petroleum products

RIPIO

F3 8807-17

PA 781

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

Arco petroleum Products

F3 8807-17

PA 781

RIP10

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO PETROLEUM PRODUCTS

R1P9

F3 8807-17

PA 781

PAN OF IMPOUNDMENT

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO petroleum products

F3 8807-17

PA-781

R1P9

PAN OF impoundment

8/4/88

11:09

Not responsive due to revised scope

[redacted]

ARCO petroleum products

F3 8807-17

PA-781

R1P9

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

R1P9

F3 88.07-17

PA-781.

ARCO petroleum products

Pan of impoundment

8/4/88

11:09

Not responsive due to revised scope



ARCO petroleum products

R109

F3 8807-17

PA-781

Plan of improvement

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO petroleum products
F3 8807-17
PA-781

RIP11
PHOTO NO. 4

Looking South at
monitoring well # 4

Not responsive due to revised scope

8/4/88
11:30

ARCO petroleum products
F3 8807-17
PA-781

RIP1
PHOTO NO. 3

Looking South South West
AT monitoring well #3

Not responsive due to revised scope

[redacted]

8/4/88
10:32

ARCO petroleum products
F3 8807-17
PA-781

RIP 4
PHOTO NO. 2

Looking northwest at
monitoring well #2

Not responsive due to revised scope

[redacted]

8/4/88
10:42

b

ARCO PETROLEUM PRODUCTS
F3 8807-17
PA-781

RIP5
PHOTO NO. 1

Looking west at
monitoring well # 1

Not responsive due to revised scope

[redacted]

8/4/88
11:00

ARCO petroleum products
F3 8807-17
PA-781

RIP3
PHOTO NO. 5

Looking South, southwest
at overflow
Marcus Hook creek
in background

Not responsive due to revised scope

[redacted]

8/4/88
10:42

ARCO petroleum products

F3 8807-17

PA-781

RIP2

PHOTO NO. 6

Closeup of overflow area looking northwest

Not responsive due to revised scope

[redacted]

8/4/88

10:42

ARCO petroleum Products

F3 8807-17

PA-781

RIP7

PHoto No. 7

Pan of impoundment
Looking south

Not responsive due to revised scope

[redacted]

8/4/88
11:09

ARCO petroleum products
F3 8807-17
PA-781

RIPL
PHOTO NO. 8

Pan of impoundment
looking south

Not responsive due to revised scope

[redacted]

8/4/88
11:09

ARCO Petroleum Products

RIP8

F3 8807-17

PA-781

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/PF

11:09

ARCO petroleum products

F3 8807-17

PA 781

R1P8

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO Petroleum products

F3 8807-17

PA 781

RIP8

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09

ARCO Petroleum products

F3 8807-17

PA-781

RIP8

Pan of impoundment

Not responsive due to revised scope

[redacted]

8/4/88

11:09