From:	Meer, Daniel
To:	Nixon, Donald
Cc:	Lawrence, Kathryn
Subject:	FW: Valero Refinery Flaring Incident
Date:	Friday, May 05, 2017 12:07:55 PM
Attachments:	Airosol Inc Spot Report and CIIP.DOCX

One more example

Daniel A. Meer, Assistant Director
Superfund Division
Emergency Response, Preparedness and Prevention Branch
415.972.3132 (O)
415.971.6792 (C)

From: Eoc, Epahq
Sent: Friday, May 05, 2017 11:40 AM
To: Meer, Daniel <Meer.Daniel@epa.gov>
Cc: Lee, Eugene <Lee.Eugene@epa.gov>; Eoc, Epahq <Eoc.Epahq@epa.gov>
Subject: RE: Valero Refinery Flaring Incident

Hi Dan,
Thanks so much for this information. We'll be preparing an EOC Spot Report out of HQ. OEM Management has requested a CIIP from Region 9 for this incident. I am attaching an example CIIP from Region 7 for reference. The CIIP begins on page 3. Please let me know if you have any questions.

Pete Oh, Sr. Watch Officer
U.S. Environmental Protection Agency
Headquarters Emergency Operations Center
1200 Pennsylvania Ave
Washington, DC 20004
202-564-3850 (24hrs)
eoc.epahq@epa.gov

From: Meer, Daniel
Sent: Friday, May 05, 2017 1:53 PM
To: R9_ER List <R9_ER_List@epa.gov>
Subject: Valero Refinery Flaring Incident

Overview:

- At approximately 0615 hours Pacific Time, a power outage at the Valero Refinery in Benicia, CA caused a large, unplanned flaring incident. The

power outage was apparently due to activity by the local utility, Pacific Gas & Electric. The refinery continues to be without power.

- The heavy smoke from the flaring caused local authorities to order and implement small scale evacuations and shelter-in-place in Benicia, in the immediate vicinity and downwind of the facility. An unknown number of people were evacuated from a nearby industrial park at 0745 hours. The shelter-in-place orders continue, including two elementary schools (Roberts Temple and Mathew Turner) to the north of the facility. Evacuation advisories, however, have been lifted.

- Steady westerly winds appear to be dissipating the thickest plumes of smoke and the smoke and flaring activity appear to be decreasing. However air quality is described as 'bad' with heavy to a severe smell of sulfur dioxide in neighborhoods downwind of the refinery. Ground level fence line monitors at the refinery are showing 5 ppb SO2. No sampling has occurred as of 1030 hours.

- The Valero Refinery is reporting their initial estimates that 9,403 pounds of material have been released by the flaring.

Federal, State and Local Authority Actions:

- Multiple state and local authorities responded immediately to the incident.
- They include the **Bay Area Air Quality Management District** that deployed a mobile monitoring van with real time SO2 monitoring capability and personnel to take summa canister samples;
- the **California Air Resources Board** which has modeling staff on standby if needed and is deploying particulate monitors (EBAMS) for PM10 and PM2.5;
- the **Solano County Hazardous Materials Unit** responded at the request of the **Benicia Fire Department**;
- Solano County HazMat is maintaining contact with the Bay Area AQMD

and the neighboring Contra Costa County Community Warning System;

- the **California Occupational Safety and Health Administration** is sending staff to the refinery.
- Several roads and highways near the facility have been closed by the **City of Benicia** and the **California Highway Patrol**.

EPA Actions:

- Region 9 mobilized 2 OSCs - Maggie Waldon and Steve Calanog - and 3 technical assessment contractors to the Unified Command. EPA is deploying hand held monitors for SO2, H2S and particulates at the request of the Bay Area AQMD;
- The Region will maintain its close contact with local and state authorities that are responding.

Media Interest

Local media interest is high.

http://kron4.com/2017/05/05/flaring-at-valero-refinery-in-benicia/

Daniel A. Meer, Assistant Director
Superfund Division
Emergency Response, Preparedness and Prevention Branch
415.972.3132 (O)
415.971.6792 (C)