Don Summers 2/20/96

Bldg 36 Remediation Issue:

- Soils remediation will not be completed at the time of sale to Vestar
  - Tank that leaked is South of Bldg of 36
  - Likely that ~~not~~ vapor extraction well at the footprint of bldg
  - wells north of the fence line will not be designed to handle tractor-trailers

Bldg. 41 to stay in Place:

Procedural Issue:

Require Phase I to encompass Bldgs 36/33 and 29/58

Remedy Tank Proposal
Build 37

2 & 5 ft. increments unusual for samples and makes no sense

Summers suggests 5 increments to 20/25 below

Mobile Lab: Take samples 20/25 feet below the start point

Analyze @ 5/10 if clean if not keep going to 20/25