Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
1,1,1-trichloroethane	RQ, Waste 1,1,1-trichloroethane, 6.1, UN2831, PG III (F001)	741, 211	F001
111-trichloroethane and water	RQ, Hazardous waste liquid, n.o.s., 9, NA3082, PG III (F001)	741, 211	F001
Absorbent with jet fuel	Absorbent with jet fuel Non-RCRA hazardous waste solid	352	N/R
Absorbent with oil	Absorbent with oil Non-RCRA hazardous waste solid	352	N/R
Acid cont. solids	Waste corrosive solids, n.o.s.,(Tech name) 8, UN1759, PG II	181	N/R
Acid, acetic acid	RQ, Waste acetic acid solution, 8, UN2790, PG II (D002)	792†	D002
Acid, Chromic	RQ, Waste chromic acid solution, 8, UN1755, PG II (D002, D007)	792, 723	D002, D007
Acid, Chromic cont. solids	Waste corrosive solids, n.o.s.,(nitric acid, chromic acid) 8, UN1759, PG II (D007)	181	D007
Acid, hydrochloric acid	RQ, Waste hydrochloric acid, solution, 8, UN1789, PG II (D002)	792†	D002
Acid, nitric acid	RQ, Waste nitrating acid mixtures spent, 8, UN1826, PG II (D002)	792†	D002
Acid, phosphoric acid	RQ, Waste phosphoric acid, 8, UN1805, PG III (D002)	792†	D002
Acid, sulfuric acid	RQ, Waste sulfuric acid, spent, 8, UN1832, PG II (D002)	792†	D002

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.

Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
Acids, Mixed	RQ, Waste Corrosive liquids, n.o.s.,(nitric acid, chromic acid) 8, UN1760, PG II (D002, D007)	792, 723	D002, D007
Adhesives, resins and hardeners	RQ, Waste flammable liquids, n.o.s.,(epoxy resin) 3, UN1993, PG II (D001)	281,271	D001
Asbestos	RQ, Waste asbestos, 9, NA2212, PG III	151	N/R
Caustics, mixed	RQ, Waste caustic alkali liquids, n.o.s.,(sodium hydroxide) 8, UN1719, PG III (D002)	121††	D002
Cee Bee A276A	Paint stripper Non-RCRA hazardous waste liquid	343	N/R
Charcoal	Need analytical, Non-RCRA or Haz Waste solid	352	Need analytical
Chromium filter cake-DMJM	RQ, Hazardous waste solid, n.o.s.,9, NA3077, PG III (D007, F006, F019)	491	F006, F019, D007
Chromium filter cake-MEMTEK	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III (D007, F019)	491	F019, D007
Cut- up poly containers	Empty poly containers Non-RCRA hazardous waste solid	512, 513	N/R
Cyanide rinse water	RQ, waste cyanide solutions, 6.1, UN1935, PG III (D003)	711	D003, D006, D007
Dry Toner	Toner Non-RCRA hazardous waste solid	352	N/R
Empty Hydrofluoric acid bottles	Residue: last contained Waste Hydrofluoric acid, solution, 8, UN1790, PG II (D002)	791, 513	D002, U134

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.

Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
Empty Hydrofluoric acid drums	Residue: last contained Waste Hydrofluoric acid, solution, 8, UN1790, PG II (D002)	791, 512	D002, U134
Ferric chloride, solution	Waste ferric chloride, solution, 8, UN2582, PG III	181	N/R
Instapack A	Instapack A Non-RCRA hazardous waste liquid	331	N/R
Instapack B	Instapack B Non-RCRA hazardous waste liquid	331	N/R
Jet Fuel	RQ, Waste fuel, aviation, turbine engine, 3, UN1863, PG III (D001)	331	D001
Kolene	Waste corrosive solids, n.o.s., (potassium hydroxide) 8, UN1759, PG II	181	N/R
Kolene-Torrance Facility	Waste corrosive solids, n.o.s., (potassium hydroxide) 8, UN1759, PG II (D007)	181	D007
Kolene rinse water	RQ, Waste caustic alkali, liquids, n.o.s., (Potassium hydroxide) 8, UN1719, PG III (D002)	181	D002(If pH>12.5)
Kolene rinse water-Torrance Facility	RQ, Waste caustic alkali, liquids, n.o.s., (Potassium hydroxide) 8, UN1719, PG III (D002, D007)	181	D002, D007
Lab Packs	Various	551	Various
Liquid ink	RQ, Waste flammable liquids, n.o.s. (isopropanol), 3, UN1993, PG III (D001)	343	D001

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.

Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
Machine coolant, oil, and water	Machine coolant, oil, and water Non-RCRA hazardous waste liquid	223	N/R
Mercury cont. debris	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III (D009)	181	D009
Misc. sumps	Miscellaneous sumps Non-RCRA hazardous waste liquid	223	N/R
Oil and Water	Oil and water Non- RCRA hazardous waste liquid	223	N/R
Paint booth water	RQ, Hazardous waste liquid, n.o.s., 9, NA3082, PG III (D007)	723	D007
Paint filters	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III (D007)	352	D007
Paint in cans overpacked	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III (D007)	331	D007
Paint sludge	RQ, Paint related material, 3, UN1263, PG II, (F002, F003, F005, D001, D007)	461	F002, F003, F005, D001, D007
PCB Carcasses	RQ, Waste environmentally hazardous substance, solid, n.o.s., 9, UN3077, PG III, (Polychlorinated biphenyls)	261	PCB2
PCB Oil (Liquid)	RQ, Waste environmentally hazardous substance, liquid, n.o.s., 9, UN3082, PG III, (Polychlorinated biphenyls)	261	PCB1

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.

Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
PCB Light ballast	RQ, Waste environmentally hazardous substance, solid, n.o.s., 9, UN3077, PG III, (Polychlorinated biphenyls)	261	PCB1
Purge Water	RQ, Hazardous waste liquid, n.o.s., 9, NA3082, PG III	134	Call Scott Lattimore for analytical
Quench water, tank 619	Quench water Non-RCRA hazardous waste liquid	223	N/R
Rags	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III(F002, F003, F005, D007)	352	F002, F003, F005, D007
RO wash out	RQ, Hazardous waste liquid, n.o.s., 9, NA3082, PG III		Analytical required
Sealant tubes	RQ, Hazardous waste solid, n.o.s., 9, NA3077, PG III (D007,D008)	352	D007, D008
Sodium hydroxide cont. solids.	Waste corrosive solids, n.o.s., 8, UN1759, PG II	181	N/R
Sodium hydroxide liquid	RQ, Waste sodium hydroxide solution, 8, UN1824, PG II (D002)	121††	D002
Tank 505	RQ, Waste corrosive liquids, n.o.s.,(chromic acid) 8, UN1760, PG II (D002, D007)	792, 723	D002, D007
Tank 5DA-07 (Chromic acid)	RQ, Waste chromic acid solution, 8, UN1755, PG II (D002, D007)	792, 723	D002, D007
Tramp oil	Tramp oil Non-RCRA hazardous waste liquid	223	N/R

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.

Douglas Aircraft wastestreams

WASTE STREAM	BASIC DESCRIPTION (Exact name for box 11 on Haz Waste manifest)	CA CODES*	RCRA CODES*
Wash rack	Aircraft wash rack water Non-RCRA hazardous waste liquid	223	N/R

* First code is to be placed in box i of hazardous waste manifest. Add. codes are to be placed in box j. If there is no room to print the add. codes in box j, place in box 15.
† Use 791 if virgin product.
†† Use 122 if virgin product.