C6-700-82-OPC-0076
TANK 259
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023603

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd
City, State, Zip Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive	UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant Tank 259

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 80 %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-1-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #17-20005
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-1-82
TIME ☐ AM ☐ PM

(16) F Mijares driver — Signature of Authorized Agent and Title — 2-1-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME
EPA NO.
PHONE NO.

18 QUANTITY (If Measured) 16.99
19 STATE FEE (If Any) 16.99

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] — Signature of Authorized Agent and Title — 2/3/82 Date Accepted

TO GENERATOR

BOE-C6-0214021

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

SCANNED

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG. E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214022

C6-700-82-OPC-0075

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard. 46180

(1) Manifest Number 227-022269 1.22

GENERATOR (Generator Must Complete)

(2) Name (MC) DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190th & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S. CARTIERO AVE.
City, State, Zip MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name BKK CORPORATION
EPA NO. CAD067786749
Address 2210 S. AZUSA AVE
City, State, Zip WEST COVINA, CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON HAZARDOUS		~~[illegible]~~ XX	~~[illegible]~~
WASTE			1260	GALS

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS AIRCRAFT MFG. 2-PP-11

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. MUD		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher - Buyer — Signature of Authorized Agent and Title — 2-1-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #20307 #13
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-1-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 2-1-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 3.59 4.0
19 STATE FEE (If Any) 5.59

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] 69 — Signature of Authorized Agent and Title — 2-1-82 Date Accepted

TO GENERATOR

BOE-C6-0214023

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolants
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214024

C6-700-82-OPC-0076
TANK 259
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023601

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 90th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive	UN 1824	2800	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant Tank 259

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Sodium Hydroxide	14		☑ % ☐ ppm.
B.	Sulfur	1		☑ % ☐ ppm.
C.	Sodium Aluminate	5		☑ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title
2-1-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O.# 20254

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-1-82
TIME 1130 ☑ AM ☐ PM

(16) Toussaint Driver — Signature of Authorized Agent and Title
2-1-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 10.88
19 STATE FEE (If Any) 10.88

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) Signature of Authorized Agent and Title
2/13/82 — Date Accepted

BOE-C6-0214025

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214026

C6-700-82-OPC-0076
TANK 259
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023602

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD086510005
Address: 190th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD028748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive		1000	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: Spent Etchant Tank 259

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Sodium Hydroxide	14		☑ % ☐ ppm.
B.	Sulfur	1		☑ % ☐ ppm.
C.	Sodium Aluminate	5		☑ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other may cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Kotcher Buyer — Signature of Authorized Agent and Title
2-1-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 2-1-82
TIME: 330 ☐ AM ☑ PM

(16) J Tonsant, Driver — Signature of Authorized Agent and Title
2-1-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured): 3.49
19 STATE FEE (If Any): 3.49

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title (6C)
2 22 82 — Date Accepted

TO GENERATOR

BOE-C6-0214027

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo send photocopy to DOHS).

TO INSURE LEG . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214028

46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

TANK-1

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023248

GENERATOR (Generator Must Complete) C6-700-82-DPC-30075

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK CORPORATION
EPA NO. CAD007786749
Address 2210 S. AZUSA AVE.
City, State, Zip WEST COVINA, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON HAZARDOUS		4200	GALS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71

(7) EX. HAZ. WASTE PERMIT NO. 3-1804

(8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. MUD		2	☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	98		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 6 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title — 2-2-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #17-20044
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-2-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 2-2-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 1686
19 STATE FEE (If Any) Ø

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 2/2/82 Accepted

TO GENERATOR

BOE-C6-0214029

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LE... COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214030

4618 O PUMP TANK 1

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard C6-700-82-OPC-0075

(1) Manifest Number 227 - 023249

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD0865/0005
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK CORPORATION
EPA NO. CAD067786749
Address 2210 S. AZUSA AVE.
City, State, Zip WEST COVINA, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER.	NON HAZARDOUS		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS AIRCRAFT MFG.

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. MUD		2	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	98		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 6 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other GLOVES

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-2-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #17-20046
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-2-82
TIME ☐ AM ☐ PM

(16) F. Mijares DRIVER — Signature of Authorized Agent and Title — 2-2-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 14.79
19 STATE FEE (If Any) ~~8.0~~

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

) NAME

(23) [signature] 50 — Signature of Authorized Agent and Title — 2-2-82 Date Accepted

TO GENERATOR

BOE-C6-0214031

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214032

C6-700-82-OPC-0078

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-022763

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water			40 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft MFG

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	75		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	25		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-4-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 22-19385
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/4/82
TIME 7:15 ☒ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 2/4/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 4.38
19 STATE FEE (If Any) Ø

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (50) — Signature of Authorized Agent and Title — 2/6/82 Date Accepted

TO GENERATOR

BOE-C6-0214033

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LEG : COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214034

C6-700-82-OPC-00377
44180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023604

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD081511001
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Corp
EPA NO. CAD067786749
Address: 2210 S. Azusa
City, State, Zip: West Covina, Ca.

(4) Alternate TSD Facility
Name: Operating Ind.
EPA NO. CAT080012021
Address: 2425 Garfield
City, State, Zip: Monterey Park, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + water	N/A		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Stripper Slab

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Mud	5		☑ % ☐ ppm.
B. Water	95		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title
2-4-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #22-20352
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-11-82
TIME 8:00 ☑ AM ☐ PM

(16) A. Yoon Dong — Signature of Authorized Agent and Title
2-11-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 18.75
19 STATE FEE (If Any) Ø

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
2/4/82 — Date Accepted

TO GENERATOR

BOE-C6-0214035

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG : COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214036

46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 022993

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO.
EPA NO. CAD065710005
Address: 19001 S. NORMANDIE Phone No.
City, State, Zip: TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING INDUSTRIES
EPA NO. CAT080012024
Address: 2425 S. GARFIELD AVE.
City, State, Zip: MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON HAZARDOUS		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 71
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: AIRCRAFT MFG.

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	MUD	98	2	~~☐ %~~ ☐ ppm.
B.	WATER			~~☐ %~~ ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☒ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 2-5-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. #17-20261
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE 2-5-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 2-5-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: BKC
EPA NO. CAD066786749
PHONE NO.

18 QUANTITY (If Measured) SEE # 1581
19 STATE FEE (If Any) 17.00

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (60) Signature of Authorized Agent and Title — 2-15-82 Date Accepted

TO GENERATOR

BOE-C6-0214037

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility: If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG. . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214038

C6-700-82-OPA-0078

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023465

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD 0 8 3 5 1 0 6 0 5
Address 19 2 Macarthur Phone No. 533-1612
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD 0 6 7 7 8 6 7 4 9
Address 9210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water			60	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Mud	75		☒ % ☐ ppm.
B.	Water	25		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [illegible] Signature of Authorized Agent and Title — Date Shipped 2-5-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 10-20161
EPA NO. C A D 0 5 0 8 0 6 8 5 0
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/5/82
TIME 6:15 ☐ AM ☐ PM

(16) [illegible] Signature of Authorized Agent and Title — Date 2/5/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME
EPA NO.
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Accepted

GENERATOR

BOE-C6-0214039

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9; DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

BOE-C6-0214040

Tank 203
C6-700-82-OPC-0077

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023606

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD081651005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Kettleman Hills
EPA NO. CAD006646117
Address:
City, State, Zip: Bakersfield, Ca.

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, nos.	Corrosive	NA1760	7200	GALS
WASTE				

CONTAINERS NUMBER:
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: C1-2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: Alum. Etch Tank 203

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Nitric Acid	10		☑ % ☐ ppm.
B.	Chromic Acid	5		☑ % ☐ ppm.
C.	Hydrofluoric Acid	1		☑ % ☐ ppm.
D.				☑ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☑ % ☐ ppm.

Non Hazardous Material 84 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-5-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O.# 20207

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 2-5-82
TIME: 330 ☑ AM ☐ PM

(16) J Toussaint, Driver — Signature of Authorized Agent and Title — 2-5-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: CWM
EPA NO. CAT000646117
PHONE NO.

18 QUANTITY (If Measured) 200 gal
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — 2/15/82 Date Accepted

BOE-C6-0214041

C6-700-82-OPC-0076
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023512

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD 086510005
Address 190th x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water			60 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft MFG

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	75		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	25		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-8-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 21-20310
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/8/82
TIME 6:15 ☒ AM ☐ PM

(16) J Pietronico Driver — Signature of Authorized Agent and Title — 2/8/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 8.99
19 STATE FEE (If Any) 0

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA N

(23) [signature] (50) — Signature of Authorized Agent and Title — 2-8-82 Date Accepted

TO GENERATOR

BOE-C6-0214042

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214043

C6-700-82-OPC-00 46270

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023607

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. Garfield Ave
City, State, Zip Monterey Park, Ca.

(4) Alternate TSD Facility
Name BKK
EPA NO. CAD067786749
Address 2210 S. Azusa
City, State, Zip W. Covina CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	Non Hazard.		2500	GAL
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft MFG 2-PP11

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-8-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #13-20316
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-8-82
TIME ☐ AM ☐ PM

(16) A. York Dr[illegible] — Signature of Authorized Agent and Title — 2-8-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067726749
PHONE NO.

18 QUANTITY (If Measured) 10.25
19 STATE FEE (If Any) ~~10.25~~ 0

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (50) — Signature of Authorized Agent and Title — 2-8-82 Date Accepted

TO GENERATOR

BOE-C6-0214044

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214045

CHROMATE SYSTEM
C6-700-82-OPC-0077

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023608

GENERATOR (Generator Must Complete) 46180

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave
City, State, Zip West Covina, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	NOS		1400	60 LS
WASTE Aluminum	Corrosive			

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 3
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Clean Chrome Sludge

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other none

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Beyer — Signature of Authorized Agent and Title — 2-8-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

S.O# 19388
(15) PICK-UP DATE 2-8-82
TIME 2:30 ☐ AM ☑ PM

(16) J Tonasan / Driver — Signature of Authorized Agent and Title — 2-8-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.75
19 STATE FEE (If Any) 5.75

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) D Olin (60) — Signature of Authorized Agent and Title — 2-9-82 Date Accepted

TO GENERATOR

BOE-C6-0214046

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below).

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEG . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214047

C6-700-82-OPC-40980

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023609

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD 086510095
Address: 19004 Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge + Water	NON		~~4200~~	~~lbs~~
WASTE			30	bbls

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Paint Sludge Tank

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Paint Sludge	10		☑ % ☐ ppm.
B.	Water	90		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title
2-9-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 11-19783
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/9/82
TIME 2:30 ☐ AM ☑ PM

(16) [illegible] Driver — Signature of Authorized Agent and Title
2/9/82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) See # 023190
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT: 503 (49)

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [illegible] (50) — Signature of Authorized Agent and Title
2-11-82 — Date Accepted

TO GENERATOR

BOE-C6-0214048

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG : COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL , TRANSFER PAPER.

BOE-C6-0214049

TANK 206, 207 + 212

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions. C6-700-82-OPC-0079
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023610

GENERATOR (Generator Must Complete) 46180

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave
City, State, Zip West Covina, Ca 91763

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd.
City, State, Zip Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive	UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant 206, 207 + 212

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	10		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.	Non Hazardous Material 85 %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 20377

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-10-82
TIME 230 ☑ AM ☐ PM

(16) [signature], Driver — Signature of Authorized Agent and Title — 2-10-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 22.54
19 STATE FEE (If Any) 22.54

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] (60) — Signature of Authorized Agent and Title — 2-10-82 Date Accepted

BOE-C6-0214050

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214051

C6-700-82-OPC-0078

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard 46180

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023190

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 Th & Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	N/A		60 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Mud	75		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	25		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Betcher Buyer — Signature of Authorized Agent and Title — 2-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 11-18091
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/9/82
TIME 6:15 ☒ AM ☐ PM

(16) J Pietronico Driver — Signature of Authorized Agent and Title — 2/9/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 15.10
19 STATE FEE (If Any) 0

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

10:07

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (50) — Signature of Authorized Agent and Title — 2-11-82 Date Accepted

TO GENERATOR

BOE-C6-0214052

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transport [illegible] end photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLE[illegible] RANSFER PAPER.

BOE-C6-0214053

Tank 206, 207 + 212
C6-700-82-OPC-0079

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023611

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-2612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91763

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive	UN 1824	5000	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 3
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant 206, 207 + 212

(9) LIST COMPONENTS	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	10		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #17-20378
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-9-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 2-9-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.
18 QUANTITY (If Measured) 22.33
19 STATE FEE (If Any) 22.33

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] — Signature of Authorized Agent and Title — 2-10-82 Date Accepted

GENERATOR

BOE-C6-0214054

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214055

Tank 206, 207 + 212

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions. C6 700-82-OPC-0079
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023612

GENERATOR (Generator Must Complete) 46180

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91763

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd.
City, State, Zip Casmalia

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Alkaline Solution	Corrosive	UN 1824	1600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant 206, 207 + 212

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	10		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #13-20313
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-10-82
TIME ☐ AM ☐ PM

(16) A. Yarh Dennis — Signature of Authorized Agent and Title — 2-10-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.89
19 STATE FEE (If Any) 5.89

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) D. Olen (60) — Signature of Authorized Agent and Title — 2-10-82 Date Accepted

GENERATOR

BOE-C6-0214056

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214057

C6-700-83-ORI-0078 46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 022267

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190th Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water	n/a		20 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

(9)		CONC. UPPER	RANGE LOWER	UNITS
A.	Mud	75		☒ % ☐ ppm.
B.	Water	25		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Burger — Signature of Authorized Agent and Title — 2-10-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 13-20314
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/10/82
TIME 11:00 ☒ AM ☐ PM

(16) J Pretrance Driver — Signature of Authorized Agent and Title — 2/10/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) see
19 STATE FEE (If Any) #023514

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT: 3.12

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (60) — Signature of Authorized Agent and Title — 2-17-82 Date Accepted

TO GENERATOR

BOE-C6-0214058

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor 'send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214059

C6-700-82-CPC-00

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for instructions.
Please type or print clearly. Press Hard.

H6180 Steam Slab

(1) Manifest Number 227 - 023543

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aft
EPA NO.: CAD096510905
Address: 190th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO.: CAT080012024
Address: 900 Portrero grande
City, State, Zip: Monterey Park, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud, water	NON		4200	gals
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 71
(7) EX. HAZ. WASTE PERMIT NO.: 3-1804
(8) GENERATING PROCESS: Steam cleaning

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Mud	100	5	☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95	70	☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material	%		

(10) WASTE PROPERTIES: pH 14.0 ☐ Toxic ☒ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other none

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) JC Bailey — Signature of Authorized Agent and Title — Date Shipped: 2-10-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

50# 20380

(15) PICK-UP DATE: 2-10-82
TIME: 330 ☐ AM ☒ PM

(16) L Toussaint Driver — Signature of Authorized Agent and Title — Date: 2-10-82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO.: CAD067786749
PHONE NO.: 9650911

18 QUANTITY (If Measured): 16.41
19 STATE FEE (If Any): 16.41

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R Lopez 60 — Signature of Authorized Agent and Title — Date Accepted: 2-11-82

TO GENERATOR

BOE-C6-0214060

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal; select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three-digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214061

C6-700-81-0PM-0078

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard. 46180

(1) Manifest Number 227 - 022272

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 nd x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BNK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water	n/a		60 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

(9)		CONC. UPPER	RANGE LOWER	UNITS
A.	Mud	75		☒ % ☐ ppm.
B.	Water	25		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-11-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 22-19977
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/11/82
TIME 5:45 ☒ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 2/11/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BNK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 18.01
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (50) — Signature of Authorized Agent and Title — 2-12-82 Accepted

TO GENERATOR

BOE-C6-0214062

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpr (send photocopy to DOHS).

TO INSURE LE E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON , TRANSFER PAPER.

BOE-C6-0214063

Steam Slab
C6-700-82-OPC-0079

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023192

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK CORP
EPA NO. CAD067786749
Address 2210 S. AZUSA
City, State, Zip WEST COVINA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON		4200	GAL.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS EQUIP. WASH

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. MUD	5		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER		95	☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title — 2-11-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-19785
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/11/82
TIME 12:01 ☐ AM ☒ PM

(16) Andy Moren Driver — Signature of Authorized Agent and Title — 2/11/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 1879 16.79
19 STATE FEE (If Any) 1879

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] — Signature of Authorized Agent and Title — 2/11/82 Ac

BOE-C6-0214064

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp[illegible]er (send photocopy to DOHS).

[illegible]SURE LE[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible]S TRANSFER PAPER.

BOE-C6-0214065

C6-700-82-ORC-0079
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

e reverse side for Instructions.
ease type or print clearly. Press Hard.

(1) Manifest Number 227 - 023430

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO. CAD086510005
Address: 190th & Normandie Phone No.
City, State, Zip: Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK
EPA NO. CAD067786749
Address: 2210 S Azusa Ave
City, State, Zip: W Covina CA

(4) Alternate TSD Facility
Name: 125
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Biodegradable Coolant	n/a		100	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. (8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Biodegradable Coolant	3		☒ % ☐ ppm
B.	Water	97		☒ % ☐ ppm
C.				☐ % ☐ ppm
D.				☐ % ☐ ppm
E.				☐ % ☐ ppm
F.				☐ % ☐ ppm
G.				☐ % ☐ ppm

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

ENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to applicable regulations of the Department of Transportation and EPA.

N THE EVENT OF A SPILL, CONTACT THE NATIONAL ESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — Date Shipped 2-11-82

NSPORTER (HAULER MUST COMPLETE)

NAME OIL PROCESS CO. 17-20262
PA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/11/82
TIME 330 ☐ AM ☒ PM

(16) W Hyatt Turner — Signature of Authorized Agent and Title — Date 2/11/82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO. 965-0911

18 QUANTITY (If Measured) 2286 @ 18.43
19 STATE FEE (If Any) —

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Segur 50 — Signature of Authorized Agent and Title — Date Accepted 2-16-82

TO GENERATOR

BOE-C6-0214066

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g. sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Gener[illegible] from TSDF; Copy No. 4: Generator keeps after signed by Tran[illegible]er (send photocopy to DOHS).

TO INSURE L[illegible]LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible]S TRANSFER PAPER.

BOE-C6-0214067

06-700-82-OPC-0078 46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023194

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	n/a		10	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	75		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	25		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material ____ %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☒ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 2-12-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 11-19850
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/12/82
TIME 6:15 ☒ AM ☐ PM

(16) J Pietranco Driver — Signature of Authorized Agent and Title — 2/12/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) SEE# 23493
19 STATE FEE (If Any)

1.67

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) SGH (60) — Signature of Authorized Agent and Title — 2/13/82 Accepted

TO GENERATOR

BOE-C6-0214068

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp[illegible]r (send photocopy to DOHS).

TO INSURE LE[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible]S TRANSFER PAPER.

BOE-C6-0214069

Tank 30 + 24

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions. CG-700-82-OPC-0080
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023613

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 19th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Kettleman Hills
EPA NO. CAT000646117
Address:
City, State, Zip: Bakersfield, Ca

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Sludge + Solution	Corrosive	NA1760	1100	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 1 + 2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Passivation Tank 30+24

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Nitric Acid	20		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	80		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 80 %			

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS ~~[illegible]~~ Liquid. May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title
2-12-82 — Date Shipped
S.O. #20385

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE 2-12-82
TIME 1:30 ☐ AM ☑ PM

(16) Voussaint, Driver — Signature of Authorized Agent and Title
2-12-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME KHF
EPA NO. CAT000646117
PHONE NO.
(18) QUANTITY (If Measured) 1100 gal
(19) STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) Signature of Authorized Agent and Title
2/15/82 — Date Received

BOE-C6-0214070

CG-700-82-OPC-0080 46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023614

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 210th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + Water	NONE		1470	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS 2-PP-11

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	2		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	98		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Sizie Letcher Beyer — Signature of Authorized Agent and Title — 2-15-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE) #13

(14) NAME OIL PROCESS CO. S/O 20392
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/15/82
TIME 9:15 ☑ AM ☐ PM

(16) J. E. Cary driver — Signature of Authorized Agent and Title — 2/15/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 11.88 ~~6.00~~
19 STATE FEE (If Any) 0

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

6.00

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (50) — Signature of Authorized Agent and Title — 2-15-82 Date Accepted

TO GENERATOR

BOE-C6-0214071

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON[illegible] TRANSFER PAPER.

BOE-C6-0214072

46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

SALVAGE YARD

(1) Manifest Number 227 - 023615

GENERATOR (Generator Must Complete)

C6-700-82-OPC-0080

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190th & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S. GARFIELD
City, State, Zip MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name BKK CORP
EPA NO. CAD067786749
Address 2210 S. AZUSA
City, State, Zip WEST COVINA, CA.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIO DEGRADABLE COOLANT	NON HAZARDOUS		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO. 3-18041
(8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. BIO DEGRADABLE COOLANT		3	☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 2-17-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-20420
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-17-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 2-17-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 18.76
19 STATE FEE (If Any) ~~18.76~~ ∅

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 2/17/82 Date Accepted

BOE-C6-0214073

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor[illegible] (send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214074

C6-700-81-OPC-0080

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023431

GENERATOR (Generator Must Complete) 46180

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 190 TH & NORMANDIE Phone No.
City, State, Zip TORRANCE CALIF

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 So. AZUSA AVE
City, State, Zip WEST COVINA CALIF

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	N/A		100 BBLS	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS AIRCRAFT MFG.

LIST COMPONENTS: (9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. MUD	5		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	95		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other NONE

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 2-17-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-20272
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-17-82
TIME 2:00 ☐ AM ☐ PM

(16) Mike Wagner DRIVER — Signature of Authorized Agent and Title — 2-17-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO. 9650911

18 QUANTITY (If Measured) 20.57
19 STATE FEE (If Any) ~~0~~ 17.14

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) R Sager 50 — Signature of Authorized Agent and Title — 2-18-82 Date Accepted

TO GENERATOR

BOE-C6-0214075

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator [illegible] TSDF; Copy No. 4: Generator keeps after signed by Transport[illegible] [illegible]end photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLE[illegible] [illegible]RANSFER PAPER.

BOE-C6-0214076

C6-700-82-OPC-0080

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard. 46180

(1) Manifest Number 227 - 023432

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 190 S NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name B.K.K.
EPA NO. CAD067786749
Address 2210 So. AZUSA
City, State, Zip W. COVINA, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD + WATER	N/A		100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	MUD	5		☒ % ☐ ppm.
B.	WATER	95		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other NONE
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-18-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17 - 20274
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/18/82
TIME 9:15 ☒ AM ☐ PM

(16) [signature] Owner — Signature of Authorized Agent and Title — 2/18/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 17.09
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (SO) — Signature of Authorized Agent and Title — 2 18-8 Date Accepted

BOE-C6-0214077

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG. E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL , TRANSFER PAPER.

BOE-C6-0214078

C6-700-82-OPC-0081

46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023616

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD 086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca. 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	NOS		1660	GALS
WASTE Aluminum	Corrosive			

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: Cleaning Chrome Sludge

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Susie Letcher Buyer — Signature of Authorized Agent and Title
2-19-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE) 3-20 466

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 2-19-82
TIME: 8:45 ☐ AM ☐ PM

(16) Pat Ames Driver — Signature of Authorized Agent and Title
2-19-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO. HAZARDOUS

18 QUANTITY (If Measured): 559
19 STATE FEE (If Any): 5.59

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
7/19/82 — Date Accepted

BOE-C6-0214079

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor 'send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214080

C6-700-82-OPC-008, 46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023435

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO. CAD008651005
Address: 19077 Normandie Phone No.
City, State, Zip: Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK
EPA NO. CAD067786749
Address: 2210 S Azusa Ave
City, State, Zip: W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + Water	n/a		30	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft MFG

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	0		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	98		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other Nonis

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Berger — Signature of Authorized Agent and Title — Date Shipped 2-22-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-20292
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/22/82
TIME 6:15 ☑ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — Date 2/22/80

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 20.58 7.0
19 STATE FEE (If Any) 0

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] (50) — Signature of Authorized Agent and Title — Date Accepted 2-22-82

BOE-C6-0214081

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214082

C6-700-82-OPC-0081

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

46180

(1) Manifest Number 227-023437

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 St x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Coolant	n/a		100 Bbls	
WASTE Mud & Water				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43-70 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

(9)		CONC. UPPER	RANGE LOWER	UNITS
A.	Coolant	3		☒ % ☐ ppm.
B.	Mud	3		☒ % ☐ ppm.
C.	Water	94		☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-22-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-20291
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/22/82
TIME 1:30 ☐ AM ☒ PM

(16) J Pietrowicz Driver — Signature of Authorized Agent and Title — 2/22/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 13.34
19 STATE FEE (If Any) 0.00

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(50) Signature of Authorized Agent and Title — 2-23-82 Date Accepted

TO GENERATOR

BOE-C6-0214083

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporte nd photocopy to DOHS).

TO INSURE LEGIB OPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLE RANSFER PAPER.

BOE-C6-0214084

C6-700-82-0081 2:52

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023519

46180

GENERATOR (Generator Must Complete)

(2) Name Douglas AIRCRAFT
EPA NO. CAD086510005
Address 190 TH & NORMANDIE Phone No. 533-7612
City, State, Zip TORRANCE CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	N.H		100	BB's
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. N.A (8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. MUD	2		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	98		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-22-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-20365
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-22-82
TIME ☐ AM ☐ PM

(16) A. [illegible] — Signature of Authorized Agent and Title — 2-22-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME B.KK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 1800
19 STATE FEE (If Any) ~~1800~~

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] (50) — Signature of Authorized Agent and Title — 2-22-82 Date Accepted

BOE-C6-0214085

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity of character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLL TRANSFER PAPER.

BOE-C6-0214086

C6-700-82-OPC-0082
Steam SLAB

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023751

GENERATOR (Generator Must Complete)

(2) Name Douglas Aft.
EPA NO. CAD086510003
Address 190th & Normandie Torrance, Ca 90502 Phone No. 533-7612
City, State, Zip

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Corp.
EPA NO. CAD067786749
Address 2210 S. Azusa
City, State, Zip W. Covina, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud, water	NON		4200	Gals.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71
(7) EX. HAZ. WASTE PERMIT NO. ~~N/A~~ 3-1804
(8) GENERATING PROCESS Steam cleaner

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	10	5	☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95	90	☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material ____ %			

(10) WASTE PROPERTIES: pH 7.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☒ Other none

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 2-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

S.O.# 20492

(15) PICK-UP DATE 2-23-82
TIME 2:00 ☐ AM ☒ PM

(16) Housaint Driver — Signature of Authorized Agent and Title — 2-23-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 18.93
19 STATE FEE (If Any) 18.93

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) [signature] (60) — Signature of Authorized Agent and Title — 2-23-82 Date Accepted

BOE-C6-0214087

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator [illegible] TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER PAPER.

BOE-C6-0214088

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023342

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 190 & NORMANDIE Phone No.
City, State, Zip TORRANCE

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD007786749
Address 2210 S. AZUSA
City, State, Zip WEST COVINA, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE OIL BASE PAINT SLUDGE	NON		2900	GAL.
WASTE MUD & WATER				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☒ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49, 70 (7) EX. HAZ. WASTE PERMIT NO. N/A (8) GENERATING PROCESS AIRCRAFT MANUFACTURE

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. OIL BASE PAINT SLUDGE	4		☒ % ☐ ppm.
B. MUD	10		☒ % ☐ ppm.
C. WATER		86	☒ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 10 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☒ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) R. S. Fleffman Tarman — Signature of Authorized Agent and Title — 2-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #22-19961
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2/23/82
TIME 2 ☐ AM ☒ PM

(16) Andy Moren-Duce — Signature of Authorized Agent and Title — 2/23/82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD007786749
PHONE NO.

18 QUANTITY (If Measured) 14.39
19 STATE FEE (If Any) 14.39

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) D. Chi (60) — Signature of Authorized Agent and Title — 2-24-82 Date Accepted

TO GENERATOR

BOE-C6-0214089

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpc (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214090

SEE REVERSE SIDE FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY. PRESS HARD. C6-700-82-VTS-

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

(1) MANIFEST NO. 222-001090

GENERATOR (GENERATOR MUST COMPLETE)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) DESIGNATED T.S.D. FACILITY AUTHORIZED TO OPERATE AS APPROVED STATE OR FEDERAL PROGRAM.
Name Kettleman Hills
EPA NO. CAT000646117
Address Phone No.
City, State, Zip BAKERSFIELD, CA

(4) ALTERNATE T.S.D. FACILITY
Name
EPA NO.
Address Phone No.
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS
WASTE NITRIC ACID, 40% or Less	Corrosive	NA 1760	1500	GALS
WASTE				

CONTAINER NO. 150/22V
TYPE ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 1+2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Passivation - Tn 24, 330, 332 + 338

(9) LIST COMPONENTS:	CONC. RANGE UPPER	LOWER	UNITS	LIST COMPONENTS:	CONC. RANGE UPPER	LOWER	UNITS
A. NITRIC ACID	10		☑ % ☐ PPM	E. Sulfuric Acid	10		☑ % ☐ PPM
B. Chromic Acid	2		☑ % ☐ PPM	F.			☐ % ☐ PPM
C. Hydroflouric Acid	1		☑ % ☐ PPM	G.			☐ % ☐ PPM
D. Phosphoric Acid	20		☑ % ☐ PPM	NON HAZARDOUS MATERIAL 58 %			

(10) WASTE PROPERTIES: pH 1.0 ☐ TOXIC ☐ FLAMMABLE ☑ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN
(11) PHYSICAL STATE: ☐ SOLID ☑ LIQUID ☑ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ GLOVES ☑ GOGGLES ☐ RESPIRATOR ☑ OTHER HAZARDOUS LIQUID. MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — SIGNATURE OF AUTHORIZED AGENT AND TITLE — DATE SHIPPED 2-24-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) TRANSPORTER NAME VTS TRUCKING EPA NO. CAD000604033
ADDRESS P.O. BOX 7978 CITY LONG BEACH STATE CAL ZIP 90807
(15) PICK-UP DATE 2-24-82 TIME 5:00 ☑ AM ☐ PM
(16) Thomas E. Ortega — SIGNATURE OF AUTHORIZED AGENT AND TITLE — DATE 2-24-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) Name CWM KETTLEMAN
EPA NO. CAT000646117
(18) QUANTITY (If Measured)
(19) STATE FEE (If Any) 6 —
Phone No.
(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:
(22) IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED T.S.D. FACILITY
NAME Al Young EPA NO.
(23) SIGNATURE OF AUTHORIZED AGENT AND TITLE — DATE 2/24/82

(21) HANDLING OR DISPOSAL METHOD:
☑ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY)
☐ RECOVERY OR REUSE
☐ STORAGE/TRANSFER
EPA WASTE CODE

WHITE - TSD FACILITY

BOE-C6-0214091

TANK 401 46180 63 C6-700-82-OPC-0082

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023617

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Methylene Chloride	ORM-A	UN1593	2100	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 63 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Paint Stripper Tank 401

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Methylene Chloride	35		☑ % ☐ ppm.
B. Formic Acid	5		☑ % ☐ ppm.
C. Phenol Cresol	5		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 55 %

(10) WASTE PROPERTIES: pH 3.7 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other POISON. MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher Berger — Signature of Authorized Agent and Title — Date Shipped 2-24-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #13-20402
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-24-82
TIME 4:10 ☐ AM ☑ PM

(16) A. [illegible] — Signature of Authorized Agent and Title — Date 2-24-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 10.88
19 STATE FEE (If Any) 10.88

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] 60 — Signature of Authorized Agent and Title — Date Accepted 2-24-82

TO GENERATOR

BOE-C6-0214092

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214093

CHROMATE SYSTEM
C6-700-82-OPC-0082
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023618

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	NOS			GALS
WASTE Aluminum	Corrosive		66	BBLS

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher Buyer — Signature of Authorized Agent and Title
2-24-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O. H 20537
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-24-82
TIME 2:00 ☐ AM ☑ PM

(16) Signature of Authorized Agent and Title
2-24-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 6.04
19 STATE FEE (If Any) 6.04

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
2-25-82 — Date Accepted

TO GENERATOR

BOE-C6-0214094

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214095

C6-700-82-UK-0070

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard. 46180

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023619

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD086510005
Address: 190th Normandie Phone No. 533-7674
City, State, Zip: Torrance Ca.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Corp
EPA NO. CAD067786749
Address: 2210 S Azusa
City, State, Zip: West Covina Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge	NH		40	B/s.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS Pump Paint Tank

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Paint Sludge	20		☑ % ☐ ppm.
B. Water	80		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Buyer — Signature of Authorized Agent and Title — Date Shipped 2-26-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O. #20537
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 2-26-82
TIME 1030 ☑ AM ☐ PM

(16) [signature] — Signature of Authorized Agent and Title — Date 2-26-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 3.29
19 STATE FEE (If Any) 3.29

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] 60 — Signature of Authorized Agent and Title — Date Accepted 2-26-82

GENERATOR

BOE-C6-0214096

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor[illegible] (send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] [illegible]RANSFER PAPER.

BOE-C6-0214097