C6-700-82-OPC-0087

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023971

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 1900 Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Corporation
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, CA.

(4) Alternate TSD Facility
Name Operating Industries
EPA NO. CAT080012024
Address Potrero Grande
City, State, Zip Montebello Park Cal

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge			100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Paint Sludge Tank

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Paint Sludge		5	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 95 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 4-1-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #9-203972
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-1-82
TIME ☐ AM ☐ PM

(16) F Myers Driver — Signature of Authorized Agent and Title — 4-1-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Tsd Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured) 100 BBL
19 STATE FEE (If Any) 1750

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA N

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 4-20-82 Date Accepted

BOE-C6-0214165

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink wastewater
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON[illegible] TRANSFER PAPER.

BOE-C6-0214166

C6-700-82-OPC-0087

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023650

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. Garfield Ave
City, State, Zip Monterey Park Ca.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + water	NON HAZARD			GALS
WASTE			40	GALS

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft Mfg 2 PP-11

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. Mud		3	☑ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 4-2-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O. H 20928
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-2-82
TIME 7:00 ☑ AM ☐ PM

(16) Mike Wagner [illegible] — Signature of Authorized Agent and Title — 4-2-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 4-7-82 Date Accepted

BOE-C6-0214167

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpc 'send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214168

CG 700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023855

GENERATOR (Generator Must Complete)

(2) Name: Douglas Acft.
EPA NO. CAD086571000
Address: 190th & Normandie Phone No.
City, State, Zip: Torrance, Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO. CAT080012024
Address: 900 Portrero Grande
City, State, Zip: Monterey Park, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Bio-degradable coolant	NON		1/4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS metal machining

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Bio-degradable coolant	3	1	☑ % ☐ ppm.
B. Water	99	97	☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 7.5 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher Buyer — Signature of Authorized Agent and Title
4-7-82 — Date Shipped
S.O.# 20914

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-7-82
TIME 2:30 ☐ AM ☑ PM

(16) Thomas T. Driver — Signature of Authorized Agent and Title
4-7-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING INDUS INC
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title
5-4-82 — Date Accepted

TO GENERATOR

BOE-C6-0214169

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214170

C6-700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023972

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th & Normandie Phone No.
City, State, Zip Torrance, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. Garfield Ave.
City, State, Zip Monterey Park, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	Non Hazardous		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft Mfg.

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud		2	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	98		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 4-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #9-20865
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-9-82
TIME ☐ AM ☐ PM

(16) F. Myers driver — Signature of Authorized Agent and Title — 4-9-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

(18) QUANTITY (If Measured) 100 BBL
(19) STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 4-9-82 Date Accepted

TO GENERATOR

BOE-C6-0214171

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEGI . COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214172

AOE6700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024284

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 x Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Ind
EPA NO. CAT080012024
Address 2425 Garfield Ave
City, State, Zip Monterey Park CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud x Water	n/a		100 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Aircraft MFG

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	10		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	90		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☐ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 4/12/82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 23-21068
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4/12/82
TIME 1 ☐ AM ☒ PM

(16) J Pietranica Driver — Signature of Authorized Agent and Title — 4/12/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ~~☐ Landfill~~
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 4/13-82 Date Accepted

TO GENERATOR

BOE-C6-0214173

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214174

C6-700-82-OPC-

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023291

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190th & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S. GARFIELD AVE.
City, State, Zip MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIO-DEGRADABLE COOLANT	NON HAZARDOUS		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS AIRCRAFT MFG.

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. BIO-DEGRADABLE COOLANT		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material ____ %			

(10) WASTE PROPERTIES: pH 8 ☑ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 4-16-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #9-21090
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-16-82
TIME 5:30 ☐ AM ☑ PM

(16) F. Mijares driver Signature of Authorized Agent and Title — 4-16-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING IN A INC
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] Signature of Authorized Agent and Title — 5-6-82 Date Accepted

BOE-C6-0214175

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214176

C6-700-82-OPC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023656

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD086511005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO. CAT080012024
Address: 2425 S Garfield Ave.
City, State, Zip: Monterey Park, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + water	NON HAZARD		1890	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Aircraft Mfg 2-PP-11

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Mud	3	3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☑ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — Date Shipped 4-16-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #13-21012
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-16-82
TIME ☐ AM ☐ PM

(16) [illegible] Driver — Signature of Authorized Agent and Title — Date 4-16-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.
(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☑ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
(22) NAME
EPA NO.

(23) [illegible] — Signature of Authorized Agent and Title — Date Accepted 4-16-82

TO GENERATOR

BOE-C6-0214177

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214178

CG-700-82-OPC

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023290

GENERATOR (Generator Must Complete)

(2) Name: Douglas Acft.
EPA NO.: CAD986710005
Address: 190th & Normandie Phone No.:
City, State, Zip: Torrence, Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO.: CAT080012024
Address: 900 Portrero Grande
City, State, Zip: Monterey Park, Ca

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Biodegradable coolant NOS			100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 43
(7) EX. HAZ. WASTE PERMIT NO.: 3-1804
(8) GENERATING PROCESS: metal machining

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Bio-coolant	3	1	☑ % ☐ ppm.
B.	water	99	97	☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☑ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 7.5 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 4-16-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

S# 21091

(15) PICK-UP DATE: 4-16-82
TIME: 530 ☐ AM ☑ PM

(16) J. Lomsant, Driver Signature of Authorized Agent and Title — 4-16-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: OPERATING Ind Inc
EPA NO.: CAT080012024
PHONE NO.:

(18) QUANTITY (If Measured):
19 STATE FEE (If Any):

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ ~~Landfill~~
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME:
EPA NO.:

(23) [signature] Signature of Authorized Agent and Title — 5-1-82 Date Accepted

BOE-C6-0214179

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214180

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023296

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address: MOL & NORMANDIE Phone No.
City, State, Zip: TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING INDUSTRIES
EPA NO. CAT080012024
Address: 2425 S. GARFIELD AVE.
City, State, Zip: MONTEREY PARK CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON HAZARDOUS		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-1884 (8) GENERATING PROCESS STEAM SCAB

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	MUD		3	☑ % ☐ ppm.
B.	WATER	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Timothy Hunt Boyer — Signature of Authorized Agent and Title — 4-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #1-21079
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-23-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 4-23-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING INDUSTRIES
EPA NO. CAT080012024
PHONE NO.

(18) QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — 4-23-82 Date Accepted

TO GENERATOR

BOE-C6-0214181

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM ① Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS ②③④ Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM ⑤ Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM ⑥ Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM ⑦ If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM ⑧ Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM ⑨ INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS ⑩ ⑪ Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM ⑫ Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM ⑬ Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM ① Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM ⑭ Enter company name, EPA I.D. number, address and telephone number.

ITEM ⑮ Indicate the date and exact time the waste was removed from the generator's facility.

ITEM ⑯ Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM ⑰ Provide the TSD facility name and EPA I.D. number.

ITEM ⑱ If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM ⑲ If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM ⑳ Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM ㉑ Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM ㉒ If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM ㉓ Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214182

C6700-82-OPC-00

See reverse side for instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 022867

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CA0086510005
Address 190th & Normandie Phone No.
City, State, Zip Torrance Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Ind
EPA NO. CAT080012004
Address 2405 Garfield Ave
City, State, Zip Monterey Park Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	n/a		30 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS Aircraft MFG

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	5		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 4/30/82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 23-21185
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4/30/82
TIME 8:45 ☒ AM ☐ PM

(16) J Patrones Driver — Signature of Authorized Agent and Title — 4/30/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind
EPA NO. CAT080012004
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] — Signature of Authorized Agent and Title — 5-1-82 Date Accepted

TO GENERATOR

BOE-C6-0214183

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM ① Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS ②③④ Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM ⑤ Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM ⑥ Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM ⑦ If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM ⑧ Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM ⑨ INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS ⑩ ⑪ Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM ⑫ Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM ⑬ Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM ① Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM ⑭ Enter company name, EPA I.D. number, address and telephone number.

ITEM ⑮ Indicate the date and exact time the waste was removed from the generator's facility.

ITEM ⑯ Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM ⑰ Provide the TSD facility name and EPA I.D. number.

ITEM ⑱ If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM ⑲ If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM ⑳ Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM ㉑ Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM ㉒ If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM ㉓ Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214184

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023725

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT COMPANY
EPA NO. CAD008378044
Address 190th & Normandie Ave Phone No. 533-7818
City, State, Zip Torrance, Calif. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name B.K.K. LANDFILL
EPA NO. CAD067786749
Address 2110 S. Azuaa AVENUE
City, State, Zip West Covina, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5)

U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE PAINT, SOLVENT	Flammable	F005	46	DR
WASTE SLUDGE	TOXIC			

CONTAINERS NUMBER: 46
TYPE: [X] DRUMS [ ] BAGS [ ] CARTONS [ ] TANK TRUCK [ ] DUMP TRUCK [ ] OTHER

(6) WASTE CATEGORY 49
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	PAINT	80	15	[X] % [ ] ppm.
B.	SOLVENT	25	2	[X] % [ ] ppm.
C.				[ ] % [ ] ppm.
D.				[ ] % [ ] ppm.
E.				[ ] % [ ] ppm.
F.				[ ] % [ ] ppm.
G.				[ ] % [ ] ppm.

Non Hazardous Material ___ %

(10) WASTE PROPERTIES: pH 7 [X] Toxic [X] Flammable [ ] Corrosive/Irritant [ ] Reactive [ ] Sensitizer [ ] Carcinogen/Mutagen
(11) PHYSICAL STATE: [ ] Solid [ ] Liquid [X] Sludge [ ] Slurry [ ] Gas [ ] Other
(12) SPECIAL HANDLING INSTRUCTIONS: [X] Gloves [ ] Goggles [ ] Respirator [ ] Other Keep away from heat and open flame

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) R.M. Pauly
Signature of Authorized Agent and Title
R.M. Pauly, C6-324 Supervisor Material
Date Shipped 4-28-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 22-21031
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-28-82
TIME ___ [ ] AM [ ] PM

(16) P Owens DRIVER
Signature of Authorized Agent and Title
4-28-82
Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 992
19 STATE FEE (If Any) 992

(21) HANDLING OR DISPOSAL METHOD:
[ ] Surface Impoundment [X] Landfill
[ ] Injection Well [ ] Land Treatment
[ ] Treatment (Specify)
[ ] Recovery or Reuse [ ] Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) 8GB (62)
Signature of Authorized Agent and Title
4-28-82
Date Accepted

BOE-C6-0214185

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpr - (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214186

C6-700-82-DPC-0087

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023668

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO. CAD 086510005
Address: 190 thd Normandie Phone No. 533-7612
City, State, Zip: Torrance Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO. CAT 080012024
Address: 2425 S. Garfield
City, State, Zip: Monterey Park Calif.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud	None		4200	Gals
WASTE Water				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Stripper slab

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Mud	5		☑ % ☐ ppm.
B. Water		95	☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) R. Espinoza Assist Foreman — Signature of Authorized Agent and Title — Date Shipped 4-30-82

S.O. #21145

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-30-82
TIME 400 ☐ AM ☐ PM

(16) Vincent Driver — Signature of Authorized Agent and Title — Date 4-30-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind. Inc.
EPA NO. CAT 080012024
PHONE NO.
(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title — Date Accepted 5-20-82

TO GENERATOR

BOE-C6-0214187

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON[illegible] TRANSFER PAPER.

BOE-C6-0214188

Tank 195 + 197
C6-700-82-OPC-0091

See reverse side for instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023667

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Acid Solu.	Corrosive	UN 1755	400C	GALS
WASTE Potassium Dichromate	ORM-A	NA 1479		

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Anodize (195) Anodic Seal (197)

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Acid	5		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Potassium Dichromate	5		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Water	90		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 90 %			

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other May Cause irritation to skin & eyes

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 4-30-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-21142
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4/30/82
TIME 2 ☒ AM ☐ PM

(16) Andy Moren - Driver — Signature of Authorized Agent and Title — 4/30/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO. 9650911

18 QUANTITY (If Measured) 16.63
19 STATE FEE (If Any) 16.63

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R Sage 70 — Signature of Authorized Agent and Title — 4-30-82 Date Accepted

TO GENERATOR

BOE-C6-0214189

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor (send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214190

Tank 195 + 197
C6-700-82-OPC-0091

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023666

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave
City, State, Zip: West Covina, CA 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Acid Solu.	Corrosive	UN1755	4000	GALS
WASTE Potassium Dichromate	ORM-A	NA 1479		

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Anodize (195) Anodic Seal (197)

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Acid	5		☑ % ☐ ppm.
B. Potassium Dichromate	5		☑ % ☐ ppm.
C. Water	90		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 90 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other May Cause irritation to skin + eyes.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reave Buyer — Signature of Authorized Agent and Title
4-30-82 — Date Shipped

S.O. # 21140

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-30-82
TIME 2:30 ☑ AM ☐ PM

(16) Mousiant, Driver — Signature of Authorized Agent and Title
4-30-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO. 9650911

18 QUANTITY (If Measured) 19.64
19 STATE FEE (If Any) 19.64

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R Lugo 70 — Signature of Authorized Agent and Title
4-30-82 — Date Accepted

TO GENERATOR

BOE-C6-0214191

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214192

TANK 195 + 197
C6-200-82-OPC-0091

See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023665

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO.: CAD086510005
Address: 40th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO.: CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE CHROMIC ACID SOLU	corrosive	UN1755	60	Bbl/~~GALS~~
WASTE POTASSIUM DICHROMATE	ORM-A	NA1479		LBS

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS ANODIZE (Tank 195) ANODIC Seal (197)

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Chromic Acid	5		☑ % ☐ ppm.
B. Potassium Dichromate	5		☑ % ☐ ppm.
C. Water	90		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 90 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other MAY CAUSE IRRITATION TO SKIN + EYES.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Susie Reave Buyer — Signature of Authorized Agent and Title
4-30-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 23-21141
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4/30/82
TIME 1445 ☑ AM ☐ PM

(16) [illegible] Driver — Signature of Authorized Agent and Title
4/30/82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

(18) QUANTITY (If Measured) 9.18
(19) STATE FEE (If Any) 9.18

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [illegible] C60 — Signature of Authorized Agent and Title
4/30/82 — Date Accepted

RECEIVED JUN 16 1982 FACILITIES TECHNICAL SERVICES

TO GENERATOR

BOE-C6-0214193

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and what found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS). Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp [illegible] (send photocopy to DOHS).

TO INSURE LE[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON [illegible]S TRA[illegible]FER P[illegible]R.

BOE-C6-0214194

Chrome District System
C6-700-82-0RC-0091

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023664

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		1500	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☐ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title
4-29-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. H9-21110
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-29-82
TIME 10:30 ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title
4-29-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.42
19 STATE FEE (If Any) 5.42

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) Signature of Authorized Agent and Title
1/29/82 — Date Accepted

BOE-C6-0214195

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp (send photocopy to DOHS).

TO INSURE LEG E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON , TRANSFER PAPER.

BOE-C6-0214196

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023663

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO. CAd086510005
Address: 190th + Normandie Phone No.
City, State, Zip: Torrance Calif

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAd067786749
Address: 2210 S Azusa Ave
City, State, Zip: West Covina

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		45	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: Cleanchrome Slude

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Chromic Hydroxide	25	25	☒ % ☐ ppm.
B. Aluminum	17.5		☒ % ☐ ppm.
C. Water	57.5	58	☒ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 0 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) x Dorothy Hart Buyer — Signature of Authorized Agent and Title
4-23-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 21050 - 23
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 4-23-82
TIME ☐ AM ☐ PM

(16) P. Owens DRIVER — Signature of Authorized Agent and Title
4-23-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured): 498
19 STATE FEE (If Any): 498

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title (60)
4/24/82 — Date Accepted

TO GENERATOR

BOE-C6-0214197

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6:)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator f[illegible] TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON[illegible] TRANSFER PAPER.

BOE-C6-0214198

Tanks 7 + 330
C6-700-82-OPC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

reverse side for Instructions.
se type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023662

GENERATOR (Generator Must Complete)

) Name Douglas Aircraft Co.
PA NO. CAD086510005
ddress 190th + Normandie Phone No. 533-7612
ty, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Kettleman Hills
EPA NO. CAT000646117
Address
City, State, Zip Bakersfield, Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S.	Corrosive	NA1760	3400	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS A1, Etchant Tank 7 + 330

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
) A. Nitric Acid	10		☑ % ☐ ppm.
B. Chromic Acid	6		☑ % ☐ ppm.
C. Sulfuric Acid	3		☑ % ☐ ppm.
D. Hydroflouric Acid	1		☑ % ☐ ppm.
E. Hamplex	0.5		☑ % ☐ ppm.
F. Potassium Ferricyanide	0.001		☑ % ☐ ppm.
G. Potassium Ferrocyanide	0.001		☑ % ☐ ppm.

Non Hazardous Material 80 %

0) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

1) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

2) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other Hazardous material. May Cause Severe Burns.

ENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to e applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reave Buyer — Signature of Authorized Agent and Title — 4-23-82 Date Shipped

RANSPORTER (HAULER MUST COMPLETE)

4) NAME OIL PROCESS CO. 21-21134
PA NO. CAD050806850
DDRESS 5756 Alba Street PHONE NO. (213) 585-5063
TY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4/23/82
TIME 1:45 ☑ AM ☐ PM

(16) L. Peterson Driver — Signature of Authorized Agent and Title — 4/23/82 Date

SD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

7) NAME CWMK
PA NO. CAT000646117
IONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND HIPMENT:

WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

2) NAME
PA NO.

(23) Signature of Authorized Agent and Title — 4/23/82 Accepted

BOE-C6-0214199

TANK 206+207
C6-200-82-0RC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227- 023660

GENERATOR (Generator Must Complete)

7:17

(2) Name Douglas Aircraft Co
EPA NO. CAD086511005
Address 19th & Normandie Phone No. 538-7612
City, State, Zip Torrance Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S Azusa Ave.
City, State, Zip West Covina Ca 91763

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd
City, State, Zip Casmalia Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu	Corrosive	UN 1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS Chemical M.U. 206 + 207

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	10		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.	Non Hazardous Material 85 %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☑ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher Berger — Signature of Authorized Agent and Title — 4-21-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 21131

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-21-82
TIME 600 ☐ AM ☑ PM

(16) Hazmat Driver — Signature of Authorized Agent and Title — 4-21-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 1802
19 STATE FEE (If Any) 1802

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) RGB (60) — Signature of Authorized Agent and Title — 4-22-82 Date Accepted

BOE-C6-0214200

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214201

Tank 206+207
C6-700-82-OPC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227-023659

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91763

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd
City, State, Zip Casmalia, Ca

7-21

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu	Corrosive	~~[illegible]~~ UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Chemical Mill Tank 206+207

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide Solu	10		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.	Non Hazardous Material 85 %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Susie Fletcher Buyer — Signature of Authorized Agent and Title — 4-21-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 21129

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-21-82
TIME 600 ☐ AM ☑ PM

(16) Hanssen T Driver — Signature of Authorized Agent and Title — 4-21-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 22.70
19 STATE FEE (If Any) 22.70

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA N

(23) RGB (60) — Signature of Authorized Agent and Title — 4-22-82 Date Accepted

BOE-C6-0214202

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Pheholic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214203

TANK 206 + 207
C6-700-82-OPC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023658

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 19Dth + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN1824	1300	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: Chemical Mill Tank 206+207

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	10		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.	Non Hazardous Material	85 %		

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other may Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letaker Buyer — Signature of Authorized Agent and Title
4-21-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

S.O.# 21130

(15) PICK-UP DATE: 4-21-82
TIME: 600 ☐ AM ☑ PM

(16) Pat Owens — Signature of Authorized Agent and Title
4-21-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.
18 QUANTITY (If Measured): 514
19 STATE FEE (If Any): 514

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
4-22-82 — Date Accepted

BOE-C6-0214204

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214205

TANK 320
C6-700-82-OPC-0090

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023657

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sulfuric Acid Solu.	Corrosive	NA1760	260	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Anodize Tank 320

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. Sulfuric Acid	10		☑ % ☐ ppm.
B. Water	90		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 90 %

(10) WASTE PROPERTIES: pH 1 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title — 4-20-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. #21127

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-20-82
TIME 3:00 ☐ AM ☑ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 4-20-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 2.40
19 STATE FEE (If Any) 2.40

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (70+) — Signature of Authorized Agent and Title — 4/21/82 Date Accepted

TO GENERATOR

BOE-C6-0214206

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpc 'send photocopy to DOHS).

TO INSURE LEGI COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214207

C6-700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023655

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca. 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	NOS		1700	GALS
WASTE Aluminum	Corrosive			

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS: Clean Chrome Sludge

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Chromic Hydroxide	25	25	☒ % ☐ ppm.
B.	Aluminum	17.5	17.5	☒ % ☐ ppm.
C.	Water	57.5	57.5	☒ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☒ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☒ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☒ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Fletcher Breyer — Signature of Authorized Agent and Title
4-14-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 20884

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 4-14-82
TIME: 12:30 ☐ AM ☒ PM

(16) V Tomasani, Driver — Signature of Authorized Agent and Title
4-14-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured): 575
19 STATE FEE (If Any): 575

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
4/14/82 — Date Accepted

BOE-C6-0214208

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214209

C6-700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023654

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510095
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210. S. Azusa Ave.
City, State, Zip: West Covina, Ca. 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Ammonium Nitrate Solv.	Oxidizer	NA2426	6	Drums
WASTE				

CONTAINERS NUMBER: 6
TYPE: ☑ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☒ OTHER

(6) WASTE CATEGORY: 2
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS: CAD Stripper Tank 64

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Ammonium Nitrate	16		☑ % ☐ ppm.
B.	Cadmium	10		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 74 %

(10) WASTE PROPERTIES: pH 7 ☑ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☑ Respirator ☑ Other Avoid Prolonged or Repeated Breathing of Vapors

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Letcher Buyer — Signature of Authorized Agent and Title
4-14-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. #20-21011
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 4-15-82
TIME ☐ AM ☐ PM

(16) [signature] — Signature of Authorized Agent and Title
4-15-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 126 (71)
19 STATE FEE (If Any) 126

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☑ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (62) — Signature of Authorized Agent and Title
4/15/82 — Date Accepted

TO GENERATOR

BOE-C6-0214210

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214211

#259 C6700-82-OPC-089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023653

GENERATOR (Generator Must Complete)

(2) Name McDonald Douglas Corp
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7674
City, State, Zip Torrance Cal, 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address Azusa Ave
City, State, Zip Covina Cal.

(4) Alternate TSD Facility
Name Kettleman Hill
EPA NO. CAT006646117
Address Bakersfield, Cal
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide	~~UN1824~~	~~5~~	3,700	gal
WASTE Spent Etchant	Corrosive	UN1824		

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Spent Etchant

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	6-8 By wt		☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Sodium Aluminate	4-8 " "		☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	4-6 " "		☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water			☐ % ☐ ppm.	Non Hazardous Material ____ %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other May Cause Severe burns
(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☒ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 4-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. #20920

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-9-82
TIME 230 ☐ AM ☒ PM

(16) Toussaint, Driver — Signature of Authorized Agent and Title — 4-9-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 2151
19 STATE FEE (If Any) 2151

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) 60 — Signature of Authorized Agent and Title — 4/5/82 Date Accepted

BOE-C6-0214212

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE LEGI[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214213

C6-700-82-OPC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023652

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Cyanide Solu.	Poison B	UN1689	4	drums
WASTE				

CONTAINERS NUMBER: 4
TYPE: ☑ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER ☒

(6) WASTE CATEGORY 22
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS Copper Plate

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Cyanide	20		☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	80		☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 80 %			

(10) WASTE PROPERTIES: pH 13 ☑ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☑ Respirator ☑ Other Poisonous Gas-Avoid Breathing

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title — 4-8-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. SOLIDS
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-8-82
TIME 1:00 ☐ AM ☑ PM

(16) Mike Wagner — Signature of Authorized Agent and Title — 4-8-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) See 23651
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

.47

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) P Sager 72 — Signature of Authorized Agent and Title — 4-13-82 Date Accepted

TO GENERATOR

BOE-C6-0214214

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facility operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp[illegible] (send photocopy to DOHS).

TO INSURE LEG[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214215

C6-700-82-ORC-0089

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard. TANK 64

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023651

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086511005
Address 19000 Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina Ca 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD027481125
Address 429 San Ysidro Rd.
City, State, Zip Casmalia

D

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Ammonium Nitrate Soln.	Oxidizer	NA2426	8	Drums
WASTE Empty Contaminated	Drums	~~0~~	8	Drums

CONTAINERS NUMBER: 16
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-1804 (8) GENERATING PROCESS CAD STRIPPER TANK 64

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Ammonium Nitrate	16		☑ % ☐ ppm.
B. Cadmium	10		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 74 %

(10) WASTE PROPERTIES: pH 7 ☑ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☑ Respirator ☑ Other Avoid Prolonged or Repeated Breathing of Vapors

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Ketcher Buyer — Signature of Authorized Agent and Title — 4-8-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 20971
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 4-8-82
TIME 8:00 ☑ AM ☐ PM

(16) [signature] — Signature of Authorized Agent and Title — 4-8-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 2.35 (71)
19 STATE FEE (If Any) 2.35

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

1.88

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) R Logan 62 — Signature of Authorized Agent and Title — 4-8-82 Date Accepted

TO GENERATOR

BOE-C6-0214216

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transp (send photocopy to DOHS).

TO INSURE LE... E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON L... TRANSFER PAPER.

BOE-C6-0214217