PAINT BOOTH
C6-700-82-OPC-0095

See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023686

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name OPERATING IND
EPA NO. CAT080012024
Address 900 PROTRERO GR.
City, State, Zip MONTEREY PK. CA.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge	NON-HAZARD		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS Aircraft Mfg.

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Paint Sludge	1		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	99		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-1-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 9-21308
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6/1/82
TIME 4 ☐ AM ☒ PM

(16) J Pretronica Driver — Signature of Authorized Agent and Title — 6/1/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating TSD Inc
EPA NO. CAT080012024
PHONE NO.

(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 6-2-82 Date Accepted

TO GENERATOR

BOE-C6-0214270

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo 'send photocopy to DOHS).

TO INSURE LEG' COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214271

C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 022766

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. Garfield Ave.
City, State, Zip Monterey Park, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD + WATER	NON HAZ		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS Aircraft mfg. 2-PP-11

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	mud		3	☑ % ☐ ppm.
B.	Water	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Roeve Buyer — Signature of Authorized Agent and Title
6-4-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 21373

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE
TIME ☐ AM ☐ PM

(16) Bill Valoff Driver — Signature of Authorized Agent and Title
6-4-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind. Inc.
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title — 6-4-82 — Accepted

TO GENERATOR

BOE-C6-0214272

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge	16. Capacitors, PCB	31. Fly ash	46. Oil	61. Scrubber solution
2. Acid solution	17. Catalyst	32. Gasoline and water	47. Oil sludge	62. Soap
3. Adhesive	18. Chemicals, unused	33. Glaze sludge	48. Oil and water	63. Solvent, chlorinated
4. Alkaline sludge	19. Containers, empty	34. Glue	49. Paint sludge	64. Solvent, hydrocarbon
5. Alkaline solution	20. Contaminated equipment	35. Hair pulp	50. Pesticides	65. Solvent, oxygenated
6. Alkali solids	21. Contaminated soil	36. Heavy metal solution	51. Pesticide containers	66. Solvent, mixed
7. Alum sludge	22. Cyanides	37. Heavy metal sludge	52. Pesticide rinse water	67. Spill cleanup residue
8. API separator sludge	23. Detergent	38. Ink and solvent	53. Phenolic waste	68. Stretford solution
9. Asbestos solids	24. Distillation bottoms	39. Ink sludge	54. Photoprocessing waste	69. Sulfide sludge
10. Asbestos sludge	25. Drilling mud	40. Ink waste water	55. Plating sludge	70. Sump or lagoon sediment
11. Ashes	26. Drugs	41. Laboratory chemicals	56. Plating solution, acid	71. Tank bottom sediment
12. ASD filter cake	27. FCC waste	42. Lime sludge	57. Plating solution, alkaline	72. Tanning sludge
13. Baghouse waste	28. Filter cake	43. Machine tool coolant	58. Polychlorinated biphenyls	73. Tetraethyl lead sludge
14. Bilge water	29. Filters, spent	44. Machining waste	59. Resin waste	74. Transformers, PCB
15. Blasting sand	30. Flux	45. Metal dust	60. Scrubber sludge	75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON. TRANSFER PAPER.

BOE-C6-0214273

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023693

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086511005
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name CPERATING IND.
EPA NO. CAT080012024
Address 900 PROTRERO GRANDE
City, State, Zip MONTEREY PK. CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON		4200	GAL.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. N/A (8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. MUD	3		☒ % ☐ ppm.
B. WATER		97	☒ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) DC Kidder — Signature of Authorized Agent and Title — 6/10/82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #17-2159
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6/10/82
TIME 1145 ☒ AM ☐ PM

(16) Andy Moran - Driver — Signature of Authorized Agent and Title — 6/10/82 Date

TSD FACILITY (TSD FACILITY OPERATOR MUST COMPLETE)

(17) NAME CPERATING IND.
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — 6-10-82 Date Accepted

TO GENERAT

BOE-C6-0214274

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214275

C6-700-82-OPC-0094

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023694

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD065100005
Address 190th + Normantie Phone No. 533-7602
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. Garfield Ave
City, State, Zip Monterey Park, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + Water	NON		~~[illegible]~~	GALS
WASTE			1100	

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Aircraft Mfg 2-PP-11

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Mud		3	☑ % ☐ ppm.
B.	Water	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6-11-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O # 21599
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-11-82
TIME 7:50 ☑ AM ☐ PM

(16) A. Yack DRIVER — Signature of Authorized Agent and Title — Date 6-11-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind. Inc.
EPA NO. CAT080012024
PHONE NO.
(18) QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☑ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(22) NAME
EPA NO

(23) Signature of Authorized Agent and Title — Date Accepted 6-11-82

TO GENERATOR

BOE-C6-0214276

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution; alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo' (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214277

C6-700-82-OPC-0095

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023695

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: TORRANCE CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING INDUSTRIES
EPA NO. CAT080012024
Address: 2425 GARFIELD AVE.
City, State, Zip: MONTEREY PARK CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Biocoolant	N/A		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS TANK 1

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Biocoolant	3		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Roave Buyer — Signature of Authorized Agent and Title
6-14-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. Ag-21305
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6/14/82
TIME 10:45 ☒ AM ☐ PM

(16) Andy Moren-Driver — Signature of Authorized Agent and Title
6/14/82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING INC
EPA NO. CAT080012024
PHONE NO.

(18) QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ ~~Landfill~~
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title
6-14-82 — Date Accepted

TO GENERATOR

BOE-C6-0214278

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214279

C6-700-82-OPC-0095
TANK #1

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024736

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO.
EPA NO.: CAD065710005
Address: 190TH & NORMANDIE Phone No.:
City, State, Zip: TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING INDUSTRIES
EPA NO.: CAT080012024
Address: 900 PORTRERO GRANDE
City, State, Zip: MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE: BIO-DEGRADABLE COOLANT	NON HAZARDOUS		100	BBLS.
WASTE:				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 43
(7) EX. HAZ. WASTE PERMIT NO.:
(8) GENERATING PROCESS: MACHINING PROCESS

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. BIO DEGRADABLE COOLANT		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material	100 %		

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-14-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. S/O# 21497
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058
TRUCK NO.: 21 TLR. NO.: 21
(15) PICK-UP DATE: 6-14-82
TIME: ☐ AM ☐ PM
(16) F. Mijares driver — Signature of Authorized Agent and Title — 6-14-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: OPERATING Ind Inc
EPA NO.: CAT080012024
PHONE NO.:
(18) QUANTITY (If Measured):
(19) STATE FEE (If Any):
(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:
IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
(22) NAME:
EPA:
(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ ~~Landfill~~
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer
(23) Signature of Authorized Agent and Title — 6-14-85 Date Accepted

TO GENERATOR

BOE-C6-0214280

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LE[illegible]LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON[illegible]S TRANSFER PAPER.

BOE-C6-0214281

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024623

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510605
Address FIRING RANGE Phone No.
City, State, Zip FORRACK

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO.
Address 2625 SO GARFIELD
City, State, Zip MONTEREY PARK

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD + WATER		N/A	100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 71 (7) EX. HAZ. WASTE PERMIT NO. N/A (8) GENERATING PROCESS

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. MUD		10	☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER		90	☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☐ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Signature of Authorized Agent and Title — Date Shipped 6-16-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 50 6155-9
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 111

(15) PICK-UP DATE 6-16-82
TIME 5:00 ☐ AM ☐ PM

(16) Signature of Authorized Agent and Title — Date 6-16-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING INDUSTRIES
EPA NO. CAD080012027
PHONE NO.

(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Accepted 6-17-82

TO GENERATOR

BOE-C6-0214282

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE ' 'RLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON' TRANSFER PAPER.

BOE-C6-0214283

C6-700-87-OAC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024852

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO.: CAD 086510005
Address: 190 x Nbermandie Phone No.:
City, State, Zip: Torrance Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Inc
EPA NO.: CAT080012024
Address: 2425 Garfield Ave
City, State, Zip: Montebello Park Ca

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	n/a		100	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 70
(7) EX. HAZ. WASTE PERMIT NO.: 3-1804
(8) GENERATING PROCESS: Aircraft Mfg

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Mud	5		☒ % ☐ ppm.
B.	Water	95		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6/18/82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 21525
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17A
(15) PICK-UP DATE 6/18/82
TIME 7 ☒ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — Date 6/18/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: Operating Inc
EPA NO.: CAT080012024
PHONE NO.:

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — Date 6-18-82 Accepted

TO GENERATOR

BOE-C6-0214284

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE ' IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON S TRANSFER PAPER.

BOE-C6-0214285

SALVAGE TANK

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024741

GENERATOR (Generator Must Complete) C6-700-82-OPC-

(2) Name Douglas Aircraft Co
EPA NO. CA1086510005
Address 4101 Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 900 Potrero Grande
City, State, Zip Monterey Park CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Bio-degradable coolant	Non Hazardous		100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. (8) GENERATING PROCESS Metal Machining

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Bio degradable coolant		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Asst Foreman — Signature of Authorized Agent and Title — 6-21-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21533 TRUCK NO. 21 TLR. NO. 21
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-21-82
TIME ☐ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 6-21-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Inc Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY.

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 6-29-82 Date Accepted

TO GENERATOR

BOE-C6-0214286

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE ' ?IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO? S TRANSFER PAPER.

BOE-C6-0214287

C6-700-82-OPC-0094

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024814

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190th Normandie Phone No.
City, State, Zip Torrence Calif

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industry
EPA NO. CAT080012024
Address 2425 S Garfield
City, State, Zip Monterey Park Calif

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	None		4200	~~BBLS~~ GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 7D
(7) EX. HAZ. WASTE PERMIT NO. NA
(8) GENERATING PROCESS Air Craft Mfg 2PP11

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	3		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) X Dorothy Stout — Signature of Authorized Agent and Title — 6-25-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 9-21624
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. TLR. NO.

(15) PICK-UP DATE 6-25-82
TIME ☐ AM ☐ PM

(16) P. Owens Driver — Signature of Authorized Agent and Title — 6-25-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☑ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 6-25-82 Date Accepted

TO GENERATOR

BOE-C6-0214288

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON LESS TRANSFER PAPER.

BOE-C6-0214289

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023840

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD065710005
Address 19011 NORMANDIE
City, State, Zip TORRANCE, CA. Phone No.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012027
Address 900 POTRERO GRANDE
City, State, Zip MONTEREY PARK, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	HAZARDOUS		4200	GALS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 11
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS STEAM SLAB

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	MUD		3	☑ % ☐ ppm.
B.	WATER	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 6-29-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-21646
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-29-82
TIME ☐ AM ☐ PM

(16) J. Mjaes driver Signature of Authorized Agent and Title — 6-29-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME OPERATING INDUSTRIES
EPA NO. CAT080012027
PHONE NO.

(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] Signature of Authorized Agent and Title — 2-5-82 Accepted

BOE-C6-0214290

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it..

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] [illegible]end photocopy to DOHS).

TO INSURE LE[illegible]LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLE[illegible] TRANSFER PAPER.

BOE-C6-0214291

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-023841

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th & Normandie Phone No.
City, State, Zip Torrance, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 900 Potrero Grande
City, State, Zip Monterey Park, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Bio-degradable coolant	Non Hazardous		4200	Gals.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS Chip Compactor

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. MUD		2	☑ % ☐ ppm.
B. Bio degradable coolant		3	☑ % ☐ ppm.
C. Water	95		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) R. J. Fay Farman — Signature of Authorized Agent and Title — 6-29-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #11-21647
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-29-82
TIME ☐ AM ☐ PM

(16) F. Mijares Driver — Signature of Authorized Agent and Title — 6-29-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating TSD Fac
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 7-1-82 Date Accepted

TO GENERATOR

BOE-C6-0214292

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo send photocopy to DOHS).

TO INSURE L. .BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL. TRANSFER PAPER.

BOE-C6-0214293

Tank 206, 207+212
C6-700-82-OPC-0096
46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023688

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD065100005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysido Rd.
City, State, Zip: Casmalia, Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	85 Bbls	~~Gals~~
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS: CHEMICAL MILL. 206, 207+212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	16		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve [signature] — Signature of Authorized Agent and Title — Date Shipped: 6-2-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 17-21389
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 6/2/82
TIME: 5:15 ☐ AM ☑ PM

(16) [signature] — Signature of Authorized Agent and Title — Date: 6/2/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured): 2054
19 STATE FEE (If Any): 2054

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — Date Accepted: 6-5-82

TO GENERATOR

BOE-C6-0214294

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below).

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214295

Tank 206, 207 + 212
C6-700-82-OBC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023689

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086511005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S Azusa Ave.
City, State, Zip: West Covina, CA 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu	Corrosive	UN1824	3600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO.: 3-2728
(8) GENERATING PROCESS: CHEMICAL MILL - 206, 207 + 212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	10		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Beeyer — Signature of Authorized Agent and Title — Date Shipped: 6-2-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. Hg-21398
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 6/2/82
TIME: 6 ☐ AM ☑ PM

(16) Andy Moren - Driver — Signature of Authorized Agent and Title — Date: 6/2/82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.
18 QUANTITY (If Measured): 7.13
19 STATE FEE (If Any): 17.13

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] — Signature of Authorized Agent and Title — Date Accepted: 6/3/82

TO GENERATOR

BOE-C6-0214296

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214297

TANK 206, 207 + 212
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023690

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	3,000	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS: CHEMICAL MILL-206, 207 + 212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☑ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped: 6-2-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 22-21390
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 6-2-82
TIME ☐ AM ☐ PM

(16) P. Owens — Signature of Authorized Agent and Title — Date: 6-2-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured): 955
19 STATE FEE (If Any): 955

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) (60) — Signature of Authorized Agent and Title — Date Accepted: 6-3-82

TO GENERATOR

BOE-C6-0214298

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo (send photocopy to DOHS).

TO INSURE LEG COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL TRANSFER PAPER.

BOE-C6-0214299

CHROME DISTRUCT SYSTEM
C6-700-82-OPC-0094

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 023691

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		55	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-6-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #S.O #21410
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-7-82
TIME 12:45 ☐ AM ☑ PM

(16) A. [signature] DRIVER — Signature of Authorized Agent and Title — 6-7-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.64
19 STATE FEE (If Any) 5.64

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] 60 — Signature of Authorized Agent and Title — 6-7-82 Date Accepted

TO GENERATOR

BOE-C6-0214300

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Trans r (send photocopy to DOHS).

TO INSURE RLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON S TRANSFER PAPER.

BOE-C6-0214301

CHROME DISTRUCT SYSTEM
CL-700-82-OPC-0095

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023696

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 553-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		1600	GALS
WASTE				

CONTAINERS NUMBER:
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reave Buyer — Signature of Authorized Agent and Title
6-14-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O # 21606
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-14-82
TIME 3:30 ☐ AM ☑ PM

(16) A. [illegible] DRIVER — Signature of Authorized Agent and Title
6-14-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.98
19 STATE FEE (If Any) 5.98

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) [illegible] 60 — Signature of Authorized Agent and Title
6-15-82 — Accepted

GENERATOR

BOE-C6-0214302

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor[illegible] end photocopy to DOHS).

TO INSURE LL[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] [illegible]RANSFER PAPER.

BOE-C6-0214303

C6-700-82-OPC-0094
TANK 24 + 193

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023692

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: KETTLEMAN HILLS
EPA NO. CAT000664611 7
Address:
City, State, Zip: Bakersfield, Ca

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Nitric Acid Solution	Corrosive	NA1760	780	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 2
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS: Passivation (T/24) + AL Etch (T/193)

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Nitric Acid	8		☑ % ☐ ppm.
B. Chromic Acid	10		☑ % ☐ ppm.
C. Hydroflouric Acid	1		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material ~~81~~ %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS LIQUID. MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6-7-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 21-21448
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 6-8-82
TIME: ☐ AM ☐ PM

(16) P. Owens DRIVER — Signature of Authorized Agent and Title — Date 6-8-82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: CWM
EPA NO. CAT000664611 7
PHONE NO.

18 QUANTITY (If Measured): 780 gal
19 STATE FEE (If Any):

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Accepted 6/10/82

TO TRANSPORTER

BOE-C6-0214304

SEE REVERSE SIDE FOR INSTRUCTIONS. PLEASE TYPE OR PRINT CLEARLY. PRESS HARD.

CALIFORNIA HAZARDOUS WASTE MANIFEST

STATE DEPARTMENT OF HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P STREET, SACRAMENTO, CA 95814

(1) MANIFEST NO. 222 - 001092

GENERATOR (GENERATOR MUST COMPLETE)

(2) Name _____
EPA NO. [ ]
Address _____ Phone No. _____
City, State, Zip _____

(3) DESIGNATED T.S.D. FACILITY AUTHORIZED TO OPERATE AS APPROVED STATE OR FEDERAL PROGRAM.
Name _____
EPA NO. [ ]
Address _____ Phone No. _____
City, State, Zip _____

(4) ALTERNATE T.S.D. FACILITY
Name _____
EPA NO. [ ]
Address _____ Phone No. _____
City, State, Zip _____

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA I.D. NO.	WEIGHT OR VOLUME	UNITS
WASTE				
WASTE				

CONTAINER NO. _____
TYPE ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER _____

(6) WASTE CATEGORY _____ (7) EX. HAZ. WASTE PERMIT NO. _____ (8) GENERATING PROCESS _____

(9) LIST COMPONENTS:

	CONC. RANGE UPPER	LOWER	UNITS			CONC. RANGE UPPER	LOWER	UNITS	
A.			☐ %	☐ PPM	E.			☐ %	☐ PPM
B.			☐ %	☐ PPM	F.			☐ %	☐ PPM
C.			☐ %	☐ PPM	G.			☐ %	☐ PPM
D.			☐ %	☐ PPM	NON HAZARDOUS MATERIAL			%	

(10) WASTE PROPERTIES: pH _____ ☐ TOXIC ☐ FLAMMABLE ☐ CORROSIVE/IRRITANT ☐ REACTIVE ☐ SENSITIZER ☐ CARCINOGEN/MUTAGEN

(11) PHYSICAL STATE: ☐ SOLID ☐ LIQUID ☐ SLUDGE ☐ SLURRY ☐ GAS ☐ OTHER _____

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ GLOVES ☐ GOGGLES ☐ RESPIRATOR ☐ OTHER _____

GENERATOR CERTIFICATION: THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED, AND ARE IN PROPER CONDITION FOR TRANSPORTATION ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION AND EPA.

IN THE EVENT OF A SPILL CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) SIGNATURE OF AUTHORIZED AGENT AND TITLE _____ DATE SHIPPED _____

TRANSPORTER (HAULER MUST COMPLETE)

(14) TRANSPORTER NAME VTS TRUCKING EPA NO. CAD000604033
ADDRESS P.O. BOX 7978 CITY LONG BEACH STATE CAL ZIP 90807

(15) PICK-UP DATE _____ TIME _____ ☐ AM ☐ PM

(16) SIGNATURE OF AUTHORIZED AGENT AND TITLE _____ DATE _____

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) Name _____
EPA NO. [ ]
(18) QUANTITY (If Measured) _____
(19) STATE FEE (If Any) _____ Phone No. _____
(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT: _____
(21) HANDLING OR DISPOSAL METHOD:
☐ SURFACE IMPOUNDMENT ☐ LANDFILL
☐ INJECTION WELL ☐ LAND TREATMENT
☐ TREATMENT (SPECIFY) _____
☐ RECOVERY OR REUSE
☐ STORAGE/TRANSFER
(22) IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED T.S.D. FACILITY
NAME _____ EPA NO. [ ]
EPA WASTE CODE _____
(23) SIGNATURE OF AUTHORIZED AGENT AND TITLE _____ DATE ACCEPTED _____

PINK - GENERATOR BILLING

BOE-C6-0214305

INSTRUCTIONS FOR COMPLETING MANIFEST

TYPE OR PRINT CLEARLY. ILLEGIBLE OR INCOMPLETE MANIFESTS WILL BE RETURNED TO YOU BY THE STATE FOR CLARIFICATION.

GENERATOR:

ITEM 1: BEFORE FILLING OUT THE MANIFEST, A UNIQUE MANIFEST SERIAL NUMBER SHALL BE WRITTEN OR PRINTED ON THE MANIFEST. (REFER TO THE TRANSPORTER ITEM 1 BELOW)

ITEM 2 – 4: PROVIDE THE COMPLETE NAME, EPA I.D. NUMBER, ADDRESS AND PHONE NUMBER OF THE GENERATOR AND DESIGNATED TSD FACILITIES.

ITEM 5: PROVIDE ALL U.S. DOT REQUIRED INFORMATION. REFER TO 49 CFR 172 FOR ASSISTANCE. (IF NOT APPLICABLE, WRITE "NONE" IN ITEM 5).

ITEM 6: PROVIDE THE MOST APPLICABLE INDUSTRIAL WASTE CATEGORY NUMBER FROM THE FOLLOWING LIST. IF NOT APPLICABLE, WRITE "NONE" IN ITEM 6. IN CASES WHERE A WASTE COULD BE DESCRIBED BY MORE THAN ONE CATEGORY, SELECT THE MOST SPECIFIC. (EXAMPLE: IF YOU GENERATE A WASTE ACID PLATING SOLUTION CONTAINING DISSOLVED METAL, SELECT THE CATEGORY "PLATING SOLUTION, ACID" RATHER THAN "ACID SOLUTION" OR "HEAVY METAL SOLUTION"). IF NONE OF THE LISTED CATEGORIES ADEQUATELY DESCRIBE YOUR WASTE, WRITE THE WASTE'S CATEGORY IN ITEM 6.

1. ACID SLUDGE
2. ACID SOLUTION
3. ADHESIVE
4. ALKALINE SLUDGE
5. ALKALINE SOLUTION
6. ALKALI SOLIDS
7. ALUM SLUDGE
8. API SEPARATOR SLUDGE
9. ASBESTOS SOLIDS
10. ASBESTOS SLUDGE
11. ASHES
12. ASD FILTER CAKE
13. BAGHOUSE WASTE
14. BILGE WATER
15. BLASTING SAND
16. CAPACITORS, PCD
17. CATALYST
18. CHEMICALS, UNUSED
19. CONTAINERS, EMPTY
20. CONTAMINATED EQUIP.
21. CONTAMINATED SOIL
22. CYANIDES
23. DETERGENT
24. DISTILLATION BOTTOMS
25. DRILLING MUD
26. DRUGS
27. FCC WASTE
28. FILTER CAKE
29. FILTERS, SPENT
30. FLUX
31. FLY ASH
32. GASOLINE AND WATER
33. GLAZE SLUDGE
34. GLUE
35. HAIR PULP
36. HEAVY METAL SOLUT.
37. HEAVY METAL SLUDGE
38. INK & SOLVENT
39. INK SLUDGE
40. INK WASTEWATER
41. LAB. CHEMICALS
42. LIME SLUDGE
43. MACH. TOOL COOLANT
44. MACHINING WASTE
45. METAL DUST
46. OIL
47. OIL SLUDGE
48. OIL AND WATER
49 PAINT SLUDGE
50. PESTICIDES
51. PESTICIDE CONTAINER
52. PESTICIDE RINSE WATER
53. PHENOLIC WASTE
54. PHOTOPROCESS. WASTE
55. PLATING SLUDGE
56. PLATING SOLUT., ACID
57. PLATING SOLUT., ALKAL.
58. POYCHLORINATED BIPHENYLS
59. RESIN WASTE
60. SCRUBBER SLUDGE
61. SCRUBBER SOLUTION
62. SOAP
63. SOLVENT, CHLORINATED
64. SOLVENT, HYDROCARBON
65. SOLVENT OXYGENATED
66. SOLVENT, MIXED
67. SPILL CLEANUP RESID.
58. STRETFORD SOLUTION
69. SULFIDE SLUDGE
70. SUMP OR LAGOON SED.
71. TANK BOTTOM SED.
72. TANNING SLUDGE
73. TETRAETHYL LEAD SLUDGE
74. TRANSFORMERS, PCB
75. WASTE WATER TREATMENT SLUDGE

ITEM 7: IF THE WASTE IS EXTREMELY HAZARDOUS, PROVIDE THE STATE EXTREMELY HAZARDOUS PERMIT NUMBER.

ITEM 8: INDICATE THE PROCESS, ACTIVITY, OR OPERATION WHICH GENERATED THE WASTE (EXAMPLES: AIRCRAFT CLEANING, INSULATION STRIPPING, REACTOR CLEANING DDT PRODUCTION, ALKYLATION, PRINTED CIRCUIT BOARD ETCHING).

ITEM 9: INFORMATION MUST BE PROVIDED IN ITEM 9. DO NOT LEAVE BLANK. IDENTIFY THE MAJOR HAZARDOUS CONSTITUENTS IN THE WASTE ALONG WITH THE PROBABLE UPPER AND LOWER CONCENTRATIONS. (EXAMPLE: HYDROCHLORIC ACID, LEAD OXIDE, PHENOL, PCB, CYANIDE, DDT SODIUM HYDROXIDE). PROVIDE THE APPROXIMATE CONCENTRATION OF NONHAZARDOUS MATERIAL.

ITEM 10-11: CHECK THE APPROPRIATE PROPERTIES TO SHOW THE HAZARDOUS PROPERTIES AND PHYSICAL STATE OF THE WASTE. IF A WASTE HAS MORE THAN ONE HAZARDOUS PROPERTY (E.G., TOXIC AND CORROSIVE) CHECK ALL APPROPRIATE BOXES (E.G., TOXIC AND CORROSIVE BOXES). IF THE WASTE IS AN AQUEOUS LIQUID, THE pH MUST BE REPORTED IN ITEM 11.

ITEM 12: INDICATE BY CHECKING THE APPROPRIATE BOXES WHETHER GLOVES, GOGGLES, OR RESPERATORS SHOULD BE WORN BY PERSONS HANDLING THE WASTE. ANY SPECIAL EQUIPMENT, PRECAUTIONS, OR HAZARDS SHOULD BE NOTED (EXAMPLE: SULFIDE SOLUTION WILL GENERATE TOXIC GAS IF MIXED WITH ACIDS).

ITEM 13: SIGN THE MANIFEST AND PROVIDE YOUR TITLE AND THE DATE THE WASTE WAS REMOVED FROM YOUR FACILITY. THE PERSON SIGNING THE ITEM 13 SHALL BE KNOWLEDGEABLE ABOUT THE CHEMICAL AND PHYSICAL PROPERTIES OF THE WASTE AND SHALL BE AUTHORIZED BY THE MANAGEMENT OF THE GENERATING ESTABLISHMENT TO SIGN THE MANIFEST. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM 1: PROVIDE THE SERIAL NUMBER OF THE MANIFEST. THE FIRST THREE DIGITS SHALL BE YOUR STATE HAZARDOUS WASTE HAULER NUMBER, THE LAST SIX DIGITS MAY BE ANY CONVENIENT COMBINATION OF DIGITS (E.G., SEQUENTIAL OR CHRONOLOGICAL). FOR EXAMPLE, IF YOUR REGISTRATION NUMBER IS 899, THE NUMBER OF YOUR ONE THOUSANDTH LOAD WOULD BE 899-001000. THE COMPLETE NINE DIGIT MANIFEST NUMBER SHALL BE UNIQUE FOR ANY FIVE YEAR PERIOD. (EXAMPLE: IF YOU USE MANIFEST NUMBER 899-001000 ON MAY 31, 1981, IT SHALL NOT BE USED ON A MANIFEST AGAIN BEFORE JUNE 1, 1986).

ITEM 14: ENTER COMPANY NAME, EPA I.D. NUMBER, ADDRESS, TELEPHONE NUMBER.

ITEM 15: INDICATE THE DATE AND THE EXACT TIME THE WASTE WAS REMOVED FROM THE GENERATOR'S FACILITY.

ITEM 16: SIGN THE MANIFEST UPON RECEIPT OF THE SHIPMENT AND INDICATE THE DATE SIGNED. THE DRIVER SHALL CARRY THE MANIFEST IN A LOCATION PRESCRIBED IN 49CFR 177.817(E).

TSD FACILITY OPERATOR:

ITEM 17: PROVIDE THE TSD FACILITY NAME, AND EPA I.D. NUMBER, AND THE TELEPHONE NUMBER.

ITEM 18: IF THE QUANTITY OF WASTE IS MEASURED OR ESTIMATED AT THE TSD FACILITY (E.G. WEIGHED), INDICATE THE QUANTITY.

ITEM 19: IF THE WASTE IS APPLIED TO THE LAND (E.G. SURFACE IMPOUNDMENT, LANDFILL, INJECTION WELL, OR LAND TREATMENT AREA), THE STATE HAZARDOUS WASTE FEE MUST BE SENT TO THE DOHS. INDICATE THE FEE IN ITEM 19.

ITEM 20: WRITE IN ANY DISCREPANCIES NOTED BETWEEN THE MANIFEST INFORMATION PROVIDED BY THE GENERATOR OR TRANSPORTER AND THAT FOUND WHEN THE SHIPMENT WAS DELIVERED TO THE FACILITY. (EXAMPLES: DIFFERENCES IN THE QUANTITY OR CHARACTER OF THE WASTE, CONTAINER TYPE, VEHICLE TYPE). SOME SIGNIFICANT DISCREPANCIES ARE DESCRIBED IN 40CFR 264.72.

ITEM 21: CHECK THE BOX(ES) TO INDICATE THE METHOD(S) USED TO HANDLE OR DISPOSE OF THE WASTE AT THE HAZARDOUS WASTE FACILITY. IF THE WASTE IS TREATED PRIOR TO, OR INSTEAD OF, LAND DISPOSAL WRITE IN THE TREATMENT METHOD (EXAMPLES: NEUTRALIZATION, INCINERATION, OXIDATION).

ITEM 22: IF THE WASTE IS HELD AT THE TSD FACILITY PRIOR TO EVENTUAL SHIPMENT TO ANOTHER FACILITY FOR TREATMENT STORAGE, OR DISPOSAL, PROVIDE THE NAME OF THE DESIGNATED FINAL TSD FACILITY AND ITS EPA I.D. NUMBER. IN SUCH CASES, YOU, AS THE FACILITY OPERATOR (TRANSFER STATION) SHALL FILL OUT A NEW MASTER MANIFEST INDICATING YOUR FACILITY AS THE GENERATOR OF THE WASTE AND DESCRIBING ALL THE WASTES IN THE SHIPMENT. COMPLETED COPIES OF ALL ORIGINAL MANIFESTS ASSOCIATED WITH THE ORIGINAL WASTE SHIPMENTS ACCEPTED BY YOU SHALL BE ATTACHED TO THE MASTER MANIFESTS.

ITEM 23: SIGN THE MANIFEST, PROVIDE YOUR TITLE WITHIN THE ORGANIZATION AND INDICATE THE DATE THE SHIPMENT WAS ACCEPTED AT YOUR FACILITY. THE FACILITY OPERATOR SHALL SEND A COPY OF THE COMPLETED MANIFEST TO THE DOHS ON A MONTHLY BASIS OR AS OTHERWISE REQUIRED. IF WASTES ARE RECEIVED FROM TRANSFER FACILITIES, THE FINAL TSD FACILITY SHALL SEND COPY NUMBER 1 OF EACH MASTER MANIFEST TO DOHS WITH COPIES OF ALL ORIGINAL MANIFESTS STAPLED TO IT. TRANSFER FACILITIES SHALL SEND ONLY ONE SET OF COPIES TO DOHS TO SATISFY THE MANIFEST SUBMISSION REQUIREMENTS FOR GENERATORS AND TSD FACILITY OPERATORS.

TO ENSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLESS TRANSFER.

BOE-C6-0214306

AR RD.

Tank 7
C6-700-82-OPC-0095

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023687

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: KETTLEMAN HILLS
EPA NO. CAT000646117
Address:
City, State, Zip: Bakersfield, CA

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S.	Corrosive	NA 1760	2600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS AL. Etchant - Tank 7

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sulfuric Acid	3		☑ % ☐ ppm.
B. Chromic Acid	6		☑ % ☐ ppm.
C. Hydrofluoric Acid	2		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 89 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Serge Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6-2-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

S.O.# 21258

(15) PICK-UP DATE 6-2-82
TIME 230 ☑ AM ☐ PM

(16) Monsanto Driver — Signature of Authorized Agent and Title — Date 6-2-82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME CWM
EPA NO. CAT000646117
PHONE NO.

(18) QUANTITY (If Measured) 2600 gal
(19) STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Accepted 6/10/82

TO TRANSPORTER

BOE-C6-0214307

PAINT BOOTHS
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024818

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD081651005
Address 190th & Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge	NON-HAZARD		3600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS Aircraft Mfg.

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Paint Sludge	1		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	99		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☑ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-29-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 12-2137
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. TLR. NO.

(15) PICK-UP DATE 6-30-82
TIME ☐ AM ☐ PM

(16) Signature of Authorized Agent and Title — 6-30-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 1630
19 STATE FEE (If Any) 1630

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☑ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — 6/21/82 Accepted

TO GENERATOR

BOE-C6-0214308

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE ''BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214309

10:31

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024861

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190th & Normandie Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Caustic & Water	Corrosive		80	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 4
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Caustic	10		☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	90		☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 90 %			

(10) WASTE PROPERTIES: pH 13.5 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☐ Goggles ☐ Respirator ☐ Other Keep away from skin

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 6-25-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-20720
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T

(15) PICK-UP DATE 6-25-82
TIME 130 ☐ AM ☒ PM

(16) [signature] Signature of Authorized Agent and Title — 6-25-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 10.99
19 STATE FEE (If Any) 10.99

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] 60 Signature of Authorized Agent and Title — 6/30/82 Date Accepted

TO GENERATOR

BOE-C6-0214310

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE [illegible]IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible]S TRANSFER PAPER.

BOE-C6-0214311

C6-700-82-0PA-00

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227- 024862

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO. CAD086510005
Address: 190th & Normandie Phone No.
City, State, Zip: Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK
EPA NO. CAD067786749
Address: 2210 S Azusa Ave
City, State, Zip: W Covina CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Caustic & Water	Corrosive		100 Bbls	
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 4
(7) EX. HAZ. WASTE PERMIT NO. 3-2788
(8) GENERATING PROCESS: Aircraft MFG

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	Caustic	10		☒ % ☐ ppm.
B.	Water	90		☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 90 %

(10) WASTE PROPERTIES: pH 13.5 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☒ Goggles ☒ Respirator ☐ Other Keep Away From Skin

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Signature of Authorized Agent and Title — Date Shipped: 6-25-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 22-20717
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 22T
(15) PICK-UP DATE 6-25-82
TIME 2 PM ☐ AM ☐ PM
(16) Signature of Authorized Agent and Title — Date: 6-25-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.
18 QUANTITY (If Measured) 2103
19 STATE FEE (If Any) 2103

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Accepted: 6/29/82

TO GENERATOR

BOE-C6-0214312

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE [illegible]IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible] S TRANSFER PAPER.

BOE-C6-0214313

~~DOU~~ TANK 7

C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024817

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD 065 100 05
Address 190th. Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD 067 786 749
Address 2210 Azusa Ave.
City, State, Zip West Covina CA

(4) Alternate TSD Facility
Name Kettleman Hills
EPA NO. CAT 000 646 117
Address
City, State, Zip Bakersfield Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S	Corrosive	NA 1760	2900	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS AL. ETCHANT TANK 7

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sulfuric Acid	3		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Chromic Acid	6		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Hydrofluoric Acid	2		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material	%		

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-29-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 21-21548
EPA NO. CAD 050 806 850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21T

(15) PICK-UP DATE 6-29-82
TIME 1:15 ☑ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 6-29-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME
EPA NO. CAT 000 646 117
PHONE NO.

18 QUANTITY (If Measured) 2800 gal
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 6/29/82 Date Accepted

TO GENERATOR

BOE-C6-0214314

Chrome Distruct System
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024812

GENERATOR (Generator Must Complete) 46180

(2) Name: Douglas Aircraft Co
EPA NO.: CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO.: CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca. 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		1800	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO.: 3-2728
(8) GENERATING PROCESS: Clean Chrome Sludge

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped: 6-23-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 17-21434
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T
(15) PICK-UP DATE 6/23/82
TIME 2 ☐ AM ☒ PM

(16) [signature] — Signature of Authorized Agent and Title — Date 6/28/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO.: CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.71
19 STATE FEE (If Any) 5.71

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (60) — Signature of Authorized Agent and Title — Date Accepted: 6-24-82

TO GENERATOR

BOE-C6-0214315

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INS[illegible]E LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CA[illegible]NLESS TRANSFER PAPER.

BOE-C6-0214316

TANK 259

C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024813

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	3200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS: Spent Etch Stor Tank 259

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other may Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6-24-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. S.O. # 21392
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 11 TLR. NO.

(15) PICK-UP DATE 6-24-82
TIME 1:00 ☐ AM ☑ PM

(16) A. Young DRIVER — Signature of Authorized Agent and Title — Date 6-24-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 18.96
19 STATE FEE (If Any) 18.96

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title (60) — Date Ag d 6-24-82

TO GENERATOR

BOE-C6-0214317

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON LESS TRANSFER PAPER.

BOE-C6-0214318

TANK #252

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-024815

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT Co.
EPA NO. CAD086510005
Address 190th NORMANDIE Phone No. 533-7612
City, State, Zip TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK LANDFILL
EPA NO. CAD067786749
Address 2210 S. AZUSA AVE.
City, State, Zip WEST COVINA, CA. 91793

(4) Alternate TSD Facility
Name CASMALIA
EPA NO. CAD020748125
Address 429 SAN YSIDRO ROAD
City, State, Zip CASMALIA, CA.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE ALKALINE SOLUTION	CORROSIVE	UN1824		GALS.
WASTE				

CONTAINERS NUMBER:
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-1804
(8) GENERATING PROCESS SPENT ETCHANT TRUCK 252

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. SODIUM HYDROXIDE	14		☑ % ☐ ppm.
B. TRIETHANOLAMINE	4		☑ % ☐ ppm.
C. SULFUR	1		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 81 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Signature of Authorized Agent and Title — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. TLR. NO.
(15) PICK-UP DATE
TIME ☐ AM ☐ PM

(16) Signature of Authorized Agent and Title — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME
EPA NO.
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date

ORIGINAL

BOE-C6-0214319

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCO waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by T[illegible]porter (send photocopy to DOHS).

TO INS[illegible]IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CA[illegible]ESS TRANSFER PAPER.

BOE-C6-0214320

TANK 252

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227-024816

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190th & NORMANDIE Phone No. 533-742
City, State, Zip TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK LANDFILL
EPA NO. CAD067786749
Address 2210 S. AZUSA AVE.
City, State, Zip WEST COVINA, CA. 91793

(4) Alternate TSD Facility
Name CASMALIA
EPA NO. CAD020748125
Address 429 SAN YSIDRO RD.
City, State, Zip CASMALIA, CA.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE ALKALINE SOLUTION CORROSIVE		UN1824		GALS.
WASTE				

CONTAINERS NUMBER 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS SPENT ETCHANT TANK 252

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	SODIUM HYDROXIDE	14		☑ % ☐ ppm.
B.	TRIETHANOLAMINE	4		☑ % ☐ ppm.
C.	SULFUR	1		☑ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 81 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Signature of Authorized Agent and Title — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. TLR. NO.
(15) PICK-UP DATE
TIME ☐ AM ☐ PM

(16) Signature of Authorized Agent and Title — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME
EPA NO.
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — Date Received

ORIGINAL

BOE-C6-0214321

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. Asphalt cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. EDC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT ON PRESSURE TRANSFER PAPER.

BOE-C6-0214322

TANK 193, 181 + 45
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024809

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 40th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Kettleman Hills
EPA NO. CAT000646117
Address:
City, State, Zip: Bakersfield, CA

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S.	Corrosive	NA 1760	3000	Gals
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Al. Etch, Tank 193, 181 + 45

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Nitric Acid	9		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Chromic Acid	11		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Hydrochloric Acid	2		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Ammonium Nitrate	1		☑ % ☐ ppm.	Non Hazardous Material	77 %		

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS LIQUID. MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Boeve Buyer — Signature of Authorized Agent and Title — Date Shipped 6-23-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 21-21538
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21T
(15) PICK-UP DATE 6/23/82
TIME 2:15 ☑ AM ☐ PM
(16) [signature] Driver — Signature of Authorized Agent and Title — Date 6/23/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME CWMK
EPA NO. CAT000646117
PHONE NO.
18 QUANTITY (If Measured)
19 STATE FEE (If Any)
(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☒ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:
(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — Date Accepted 6-24-82

TO GENERATOR

BOE-C6-0214323

TANK 193, 181 + 45
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024810

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Kettleman Hills
EPA NO. CAT000646117
Address
City, State, Zip BAKERSFIELD, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid N.O.S.	Corrosive	NA1760	3300	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS AL ETCH TANK 193, 181 + 45

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Nitric Acid	9		☑ % ☐ ppm.
B. Chromic Acid	11		☑ % ☐ ppm.
C. Hydrofluoric Acid	2		☑ % ☐ ppm.
D. Ammonium Nitrate	1		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 77 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS LIQUID. MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 6-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 21-21538
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21T
(15) PICK-UP DATE 6/23/82
TIME 2:15 ☑ AM ☐ PM

(16) [illegible] Driver — Signature of Authorized Agent and Title — 6/23/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME CWMK
EPA NO. CAT000646117
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [illegible] — Signature of Authorized Agent and Title — 6-25-82 Date Accepted

TO GENERATOR

BOE-C6-0214324

TANK 400
C6-700-82-OPC-0095

See reverse side for instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023698

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO.: CAD086510005
Address: 90th & Normandie Phone No.: 533-7612
City, State, Zip: Torrance, Ca 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO.: CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Methylene Chloride	ORM-A	UN 1593	2300	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 63
(7) EX. HAZ. WASTE PERMIT NO.: 3-2728
(8) GENERATING PROCESS: Paint Stripper Tank 400

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Methylene Chloride	60		☑ % ☐ ppm.
B. Formic Acid	10		☑ % ☐ ppm.
C. Phenol Cresol	10		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 20 %

(10) WASTE PROPERTIES: pH 3.7 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other POISON MAY CAUSE ~~BU~~ SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Berger — Signature of Authorized Agent and Title — Date Shipped: 6-16-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. #01-21329
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

(15) PICK-UP DATE: 6/16/82
TIME: 2:30 ☑ AM ☐ PM

(16) Andy Moran - Driver — Signature of Authorized Agent and Title — Date: 6/16/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO.: CAD067786749
PHONE NO.:

(18) QUANTITY (If Measured): 9.28
(19) STATE FEE (If Any): 9.28

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME:
EPA NO.:

(23) [illegible] 60 — Signature of Authorized Agent and Title — Date Accepted: 6/16/82

WHITE: GENERATOR

BOE-C6-0214325

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpo[illegible] (send photocopy to DOHS).

TO INSURE L[illegible]E COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONL[illegible] TRANSFER PAPER.

BOE-C6-0214326

Tank 403
C6-700-82-OPC-0095
See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 023699

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 5337612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, CA 91793

(4) Alternate TSD Facility
Name: KETTLEMAN HILLS
EPA NO. CAT000646617
Address:
City, State, Zip: Bakersfield, CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Acid Soln.	Corrosive	UN1755	~~[illegible]~~	GALS
WASTE			2300	

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS DRY LUBE STRIP. Tank 403

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	Chromic Acid	30		☑ % ☐ ppm.
B.	Water	70		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 70 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS LIQUID. MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Rose Buyer — Signature of Authorized Agent and Title — Date Shipped 6-16-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. #21-21530
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 6-16-82
TIME ☐ AM ☐ PM

(16) F. Moore driver — Signature of Authorized Agent and Title — Date 6-16-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME B.K.K.
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 13.59
19 STATE FEE (If Any) 13.59

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) D. [illegible] — Signature of Authorized Agent and Title — Accepted 6/14/82

TO GENERATOR

BOE-C6-0214327

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transpor [illegible] end photocopy to DOHS).

TO INSURE LE[illegible] COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBONLE[illegible] RANSFER PAPER.

BOE-C6-0214328