Salvage YARD
C6-700-82 = OPC-0086

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024824

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086511005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Industries
EPA NO. CAT080012024
Address: 2425 S. GARFIELD
City, State, Zip: MONTEREY PARK, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Biodegradable Coolant	NON HAZARDOUS		4200	GALS
WASTE				

CONTAINERS NUMBER:
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS AIRCRAFT MACHINING

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Bio-degradable Coolant		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-2-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 22-20831
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. TLR. NO.

(15) PICK-UP DATE 7-2-82
TIME ☐ AM ☐ PM

(16) P. Owens Driver — Signature of Authorized Agent and Title — 7/2/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind.
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title — 7-9-82 Date

TO GENERATOR

BOE-C6-0214331

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU' EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR' .ESS TRANSFER PAPER.

BOE-C6-0214332

C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024867

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 Nx Normandie Phone No.
City, State, Zip Torrance Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Ind
EPA NO. CAT080012024
Address 2425 Garfield
City, State, Zip Monterey Park Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + Water	n/a		100	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Aircraft MFG

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	5		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☐ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-2-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-21708
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T

(15) PICK-UP DATE 7-2-82
TIME 6:30 ☒ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 7-2-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012 0
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 7-1-82 Date Accepted

TO GENERATOR

BOE-C6-0214333

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU' ' EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR' 'LESS TRANSFER PAPER.

BOE-C6-0214334

C6-700-82-OPC-00

See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024872

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190 Nd x Normandie Phone No. 533-7612
City, State, Zip Torrance Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip W Covina Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Paint Sludge + Water			75	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 49
(7) EX. HAZ. WASTE PERMIT NO. 3-2728
(8) GENERATING PROCESS Paint Spray Booths

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. Paint Sludge	10		☒ % ☐ ppm.
B. Water	90		☒ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 90 %

(10) WASTE PROPERTIES: pH 7.5 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) JC Bailey — Signature of Authorized Agent and Title — 7-6-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-21738
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T

(15) PICK-UP DATE 7-6-82
TIME 3:30 ☒ AM ☒ PM

(16) J Pietrowicz Driver — Signature of Authorized Agent and Title — 7-6-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Inc
EPA NO. CAD080012021
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 7-7-82 Date Ac

TO GENERATOR

BOE-C6-0214335

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INS[illegible]E LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible] [illegible]NLESS TRANSFER PAPER.

BOE-C6-0214336

C6-700 82-ORC0097

See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024874

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD086510005
Address 190 Normandie Phone No.
City, State, Zip Torrance Ca

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Ind
EPA NO. CAT080012024
Address 2425 Garfield Ave
City, State, Zip Monterey Park Ca

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water	N/A		100	Bbls
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☒ OTHER

(6) WASTE CATEGORY 70 (7) EX. HAZ. WASTE PERMIT NO. N/A (8) GENERATING PROCESS Aircraft Mfg

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud	1		☒ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	99		☒ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-9-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 17-21741
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T

(15) PICK-UP DATE 7-9-82
TIME 6:45 ☒ AM ☐ PM

(16) [signature] Signature of Authorized Agent and Title — 7-9-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] Signature of Authorized Agent and Title — 7-9-82 Date Accepted

TO GENERATOR

BOE-C6-0214337

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INS[illegible] LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible] [illegible]NLESS TRANSFER PAPER.

BOE-C6-0214338

TANK 400

C6-700-82-OPC-0097

See reverse side for Instructions.
Please type or print clearly. Press Hard.

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025103

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2425 S. GARFIELD AVE.
City, State, Zip MONTEREY PARK, CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Dye + Water	NON		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY Dye + Water (7) EX. HAZ. WASTE PERMIT NO. 3-2745 (8) GENERATING PROCESS TANK 400 (Testing)

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Dye	5		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	95		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-12-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21552
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 11

(15) PICK-UP DATE 7-12-82
TIME 2:30 ☐ AM ☑ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — 7-12-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Industries
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 7-[illegible] Date Accepted

TO GENERATOR

BOE-C6-0214339

7059

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO IN E LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C ONLESS TRANSFER PAPER.

BOE-C6-0214340

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025008

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT
EPA NO.: CAD 086510005
Address: 190TH & NORMANDIE Phone No.:
City, State, Zip: TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING IND.
EPA NO.: CAT080012024
Address: 900 PROPERO GRANDE
City, State, Zip: MONTEREY PK., CA.

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NON		4200	GAL.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 70
(7) EX. HAZ. WASTE PERMIT NO.: N/A
(8) GENERATING PROCESS: AIRCRAFT MFG.

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. MUD	5		☒ % ☐ ppm.
B. WATER		95	☒ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☒ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Hart Buyer — Signature of Authorized Agent and Title — 7-16-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO.: 11 TLR. NO.: 21657
(15) PICK-UP DATE: 7/16/82
TIME: 1230 ☐ AM ☒ PM

(16) Andy Moren - Driver — Signature of Authorized Agent and Title — 7/16/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: OPERATING INDUSTRIES
EPA NO.: CAT080012024
PHONE NO.:
(18) QUANTITY (If Measured):
19 STATE FEE (If Any):

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME:
EPA NO.:

(23) Signature of Authorized Agent and Title — 7-17-82 Date Accepted

TO GENERATOR

BOE-C6-0214341

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSI LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CA ILESS TRANSFER PAPER.

BOE-C6-0214342

C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025110

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190 E. Normandie Phone No. 533-2612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S GARFIELD
City, State, Zip MONTEREY PARK CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER	NONE		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70

(7) EX. HAZ. WASTE PERMIT NO. 3-2745

(8) GENERATING PROCESS AIRCRAFT Mfg 2-PP-11 + Slab

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Mud	3		☑ % ☐ ppm.
B. Water	97		☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-16-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. CO 61002
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 110

(15) PICK-UP DATE 7-16-82
TIME ☐ AM ☐ PM

(16) Mike Wagner-Driver — Signature of Authorized Agent and Title — 7-16-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Industries
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 7-15-82 Date Accepted

TO GENERATOR

BOE-C6-0214343

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE ' BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214344

TANK #1

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025112

See reverse side for Instructions.
Please type or print clearly. Press Hard.

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO
EPA NO. CAD065100005
Address 190TH NORMANDIE Phone No.
City, State, Zip TORRANCE, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 900 PORTRERO GRANDE
City, State, Zip MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIO-DEGRADABLE COOLANT	NON-HAZARDOUS		100	BBLS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☑ OTHER

(6) WASTE CATEGORY 43
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS MACHINING PROCESS

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	BIODEGRADABLE COOLANT		3	☑ % ☐ ppm.
B.	WATER	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 8 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 7-19-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S. 021865
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 111
(15) PICK-UP DATE 7-19-82
TIME ☐ AM ☐ PM

(16) [signature] Signature of Authorized Agent and Title — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING INDUSTRIES
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] Signature of Authorized Agent and Title — 7/20/82 Date Accepted

TO GENERATOR

BOE-C6-0214345

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214346

CHROME DISTRUST SYSTEM

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025113

See reverse side for instructions.
Please type or print clearly. Press Hard.

950

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address: 190 E NORMANDIE Phone No. 533-7612
City, State, Zip: TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK LANDFILL
EPA NO. CAD067786749
Address: 2210 S AZUSA AVE
City, State, Zip: WEST COVINA, CA 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE CHROMIC HYDROXIDE	CORROSIVE		1600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS: CLEAN CHROME SLUDGE

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. CHROMIC HYDROXIDE	25	25	☑ % ☐ ppm.
B. ALUMINUM	17.5	17.5	☑ % ☐ ppm.
C. WATER	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Buyer — Signature of Authorized Agent and Title — Date Shipped 7/19/82

TRANSPORTER (HAULER MUST COMPLETE) 21856

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 110

(15) PICK-UP DATE 7/19/82
TIME 3:00 ☐ AM ☐ PM

(16) [signature] — Signature of Authorized Agent and Title — Date 7/19/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 8.21
19 STATE FEE (If Any) 32.84
5.38

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — Date 7/20/82 Accepted

TO GENERATOR

BOE-C6-0214347

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214348

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025009

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING IND.
EPA NO. CAT080012024
Address 900 PROTRERO GRANDE
City, State, Zip MONTEREY PK., CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIODEGRADABLE COOLANT	NONE		4200	GAL.
WASTE WATER				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS AIRCRAFT MFG.

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. BIO COOLANT	3		☒ % ☐ ppm.
B. WATER		97	☒ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Asst. Foreman — Signature of Authorized Agent and Title — Date Shipped 7/19/82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 11 TLR. NO. 21665
(15) PICK-UP DATE 7/19/82
TIME 3:30 ☐ AM ☒ PM

(16) Andy Moren - Driver — Signature of Authorized Agent and Title — Date 7/19/82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME [illegible]
EPA NO. CAD080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — Date Ac[illegible] 7-20-82

TO GENERATOR

BOE-C6-0214349

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO IN[illegible] LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible] [illegible]NLESS TRANSFER PAPER.

BOE-C6-0214350

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025154

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD086510005
Address 190 IA & NORMANDIE Phone No.
City, State, Zip TORRANCE, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 900 POTRERO GRANDE
City, State, Zip MONTEREY PARK, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIO-DEGRADBIE COOLANT	NON HAZARDOUS		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43
(7) EX. HAZ. WASTE PERMIT NO.
(8) GENERATING PROCESS MACHINING PROCESS

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. BIO-DEGRADBIE COOLANT		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] ASST. FOREMAN — Signature of Authorized Agent and Title — 7-19-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21843
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21

(15) PICK-UP DATE 7-19-82
TIME ☐ AM ☐ PM

(16) F. Mijares DRIVER — Signature of Authorized Agent and Title — 7-19-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind. Inc.
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 7-7-8 Date Accepted

TO GENERATOR

BOE-C6-0214351

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU' EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARE ESS TRANSFER PAPER.

BOE-C6-0214352

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025114

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft
EPA NO.: CAD086510005
Address: 190 th + Normandie Phone No.: 533 7612
City, State, Zip: Torrance Cal

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: Operating Ind.
EPA NO.:
Address: 900 Potero Grande
City, State, Zip: Monterey Park Cal

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud + Water	N/A	0	4200	GALS
WASTE Bio Coolant				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 43
(7) EX. HAZ. WASTE PERMIT NO.: 0
(8) GENERATING PROCESS: Machining

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. Mud		1	☐ % ☐ ppm.
B. Water	99	99	☐ % ☐ ppm.
C. Biodegradable Coolant		1	☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Timothy Stout Buyer — Signature of Authorized Agent and Title
7-22-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. S/O 21335
EPA NO.: CAD050806850
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO.: 9 TLR. NO.: 110

(15) PICK-UP DATE: 7-22-82
TIME: ____ ☐ AM ☐ PM

(16) Bill Yaroff Driver — Signature of Authorized Agent and Title
Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: Operating Ind. Inc.
EPA NO.: CAT080012024
PHONE NO.:

(18) QUANTITY (If Measured):
(19) STATE FEE (If Any):

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME:
EPA NO.:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☒ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title
7-22-82 Date Accepted

TO GENERATOR

BOE-C6-0214353

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE [illegible]BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON [illegible] TRANSFER PAPER.

BOE-C6-0214354

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025115

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD026510005
Address [illegible] Phone No.
City, State, Zip Torrance, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Operating Industries
EPA NO. CAT080012024
Address 2405 S Garfield
City, State, Zip Monterey Park

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water		N/A	100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Mud		10	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water		90	☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7.6 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 7-22-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 50 21770
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO.

(15) PICK-UP DATE 7-22-82
TIME ☐ AM ☐ PM

(16) Mike Wagner — Signature of Authorized Agent and Title — 7-22-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating Ind Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) [signature] — Signature of Authorized Agent and Title — 7-22-82 Date Accepted

TO GENERATOR

BOE-C6-0214355

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE [illegible]BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBO[illegible] TRANSFER PAPER.

BOE-C6-0214356

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025017

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD086510005
Address 19601 NORMANDIE Phone No.
City, State, Zip TORRANCE, CA.

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING IND.
EPA NO. CAT080012024
Address 900 PROTRERO GRANDE
City, State, Zip MONTEREY PK., CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIODEGRADABLE COOLANT & NON			4200	GAL.
WASTE WATER				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS AIRCRAFT MFG.

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	BIO COOLANT	3		☒ % ☐ ppm.
B.	WATER		97	☒ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Short Buyer — Signature of Authorized Agent and Title — 7-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 11 TLR. NO. 20440
(15) PICK-UP DATE 7/23/82
TIME 2401 ☐ AM ☒ PM

(16) Andy Moren Driver — Signature of Authorized Agent and Title — 7/23/82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME OPERATING IND. INC.
EPA NO. CAT080012024
PHONE NO.
(18) QUANTITY (If Measured)
19 STATE FEE (If Any)

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(23) Signature of Authorized Agent and Title — 7-27-82 Date Accepted

TO GENERATOR

BOE-C6-0214357

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO IN[illegible] LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible] UNLESS TRANSFER PAPER.

BOE-C6-0214358

TANK #1

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025116

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO.
EPA NO. CAD08651 0005
Address 190 NORMANDIE Phone No. 533 7612
City, State, Zip TORRANCE, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S. GARFIELD
City, State, Zip MONTEREY PARK CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE BIO DEGRADABLE COOLANT	NON HAZARDOUS		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 43 (7) EX. HAZ. WASTE PERMIT NO. 32745 (8) GENERATING PROCESS MACHINING PROCESS

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. BIODEGRADABLE COOLANT		3	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. WATER	97		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Signature of Authorized Agent and Title — 7-23-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 5-0-19917
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 11

(15) PICK-UP DATE 7-23-82
TIME ☐ AM ☐ PM

(16) [signature] Signature of Authorized Agent and Title — 7-23-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME [signature]
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA N

(23) [signature] Signature of Authorized Agent and Title — 7-23-82 Date Accepted

TO GENERATOR

BOE-C6-0214359

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON TRANSFER PAPER.

BOE-C6-0214360

TANK #1
C6-700-82-OPC

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025155

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO
EPA NO.: CA 0 8 6 5 1 0 0 0 5
Address: 19001 S. NORMANDIE Phone No.:
City, State, Zip: TORRANCE, CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: OPERATING INDUSTRIES
EPA NO.: CA 7 0 8 0 0 1 2 0 2 9
Address: 2425 S. GARFIELD
City, State, Zip: MONTEREY PARK, CA

(4) Alternate TSD Facility
Name:
EPA NO.:
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE: RO DEGRADIE COOLANT	NOT HAZARDOUS		4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 43
(7) EX. HAZ. WASTE PERMIT NO.:
(8) GENERATING PROCESS: MACHINING PROCESS

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	RO DEGRADIE COOLANT		3	☑ % ☐ ppm.
B.	WATER	97		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Buyer — Signature of Authorized Agent and Title
7-23-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. S/O #28411
EPA NO.: C A D 0 5 0 8 0 6 8 5 0
ADDRESS: 5756 Alba Street PHONE NO.: (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21
(15) PICK-UP DATE 7-23-82
TIME ☐ AM ☐ PM

(16) [signature] — Signature of Authorized Agent and Title
7-23-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: OPERATING INDUSTRIES INC.
EPA NO.: CA 7 0 8 0 0 1 2 0 2 9
PHONE NO.:
(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title
7-23-82 — Date Accepted

TO GENERATOR

BOE-C6-0214361

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR .ESS TRANSFER PAPER.

BOE-C6-0214362

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025233

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft
EPA NO. CAD065104054
Address 19411 Hamburg
Phone No.
City, State, Zip Torrance CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name Aerospace Industries
EPA NO. CAT080012024
Address 2425 So Gaffey
City, State, Zip Montebello Park

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Mud & Water		N/A	100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☐ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70
(7) EX. HAZ. WASTE PERMIT NO. N/A
(8) GENERATING PROCESS Aircraft

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Mud		10	☐ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water		90	☐ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 7.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☐ Liquid ☐ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other None

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title
7-23-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 50 30997
EPA NO. CAD050806850
ADDRESS 5756 Alba Street
PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 7 TLR. NO. 110
(15) PICK-UP DATE 7-23-82
TIME 8:30 ☐ AM ☐ PM

(16) Signature of Authorized Agent and Title
7-23-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operator TD Inc
EPA NO. CAT080012024
PHONE NO.

(18) QUANTITY (If Measured)
(19) STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
7-27-8 — Date Accepted

TO GENERATOR

BOE-C6-0214363

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU[illegible] EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR[illegible]ESS TRANSFER PAPER.

BOE-C6-0214364

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025238

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT
EPA NO. CAD0865[illegible]
Address 190TH & NORMANDIE Phone No.
City, State, Zip TORRANCE CA

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name OPERATING INDUSTRIES
EPA NO. CAT080012024
Address 2425 S. GARFIELD
City, State, Zip MONTEREY PARK CA

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE MUD & WATER		N/A	100	BBLS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 70

(7) EX. HAZ. WASTE PERMIT NO.

(8) GENERATING PROCESS AIRCRAFT

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. MUD		10	☑ % ☐ ppm.
B. WATER		90	☑ % ☐ ppm.
C.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 7.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☐ Sludge ☑ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☑ Other NONE

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) DC Kidder Supr. — Signature of Authorized Agent and Title — 7-30-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S.O. 21924
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 110

(15) PICK-UP DATE 7-30-82
TIME 8:00 ☑ AM ☐ PM

(16) Mike Wagner - Driver — Signature of Authorized Agent and Title — 7-30-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME Operating TSD Inc
EPA NO. CAT080012024
PHONE NO.

18 QUANTITY (If Measured)
19 STATE FEE (If Any)

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☑ Land Treatment
☐ Treatment (Specify)
☑ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY.

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 7-30-82 Date Accepted

TO GENERATOR

BOE-C6-0214365

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR ESS TRANSFER PAPER.

BOE-C6-0214366

C6-700-82-OPC-0097
CHROME DISTRUCT SYSTEM

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025102

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina CA 91793

(4) Alternate TSD Facility 142
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		1600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 100 %			

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-12-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 21726
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 12 TLR. NO. 12

(15) PICK-UP DATE
TIME ☐ AM ☐ PM

(16) [signature] Driver — Signature of Authorized Agent and Title — 7-12-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 5.77
19 STATE FEE (If Any) 23.08

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R [signature] (60) — Signature of Authorized Agent and Title — 7/12/82 Date Accepted

TO GENERATOR

BOE-C6-0214367

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO IN[illegible]E LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible]ONLESS TRANSFER PAPER.

BOE-C6-0214368

Tank 332a Acid Storage Tank
C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for instructions.
Please type or print clearly. Press Hard.

Manifest Number 227 - 025104

GENERATOR (Generator Must Complete) 46180

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086511005
Address: 190th - Normandie Phone No. 533-2612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S.	Corrosive	NA1760	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS Anodic Stripper Tnk 332

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	CHROMIC ACID	17		☑ % ☐ ppm.
B.	PHOSPHORIC ACID	4		☑ % ☐ ppm.
C.				☐ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 79 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☐ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 7-14-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/D # 21289
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21
(15) PICK-UP DATE 7-14-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title — Date 7-14-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 15.35
19 STATE FEE (If Any) 61.40

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] 70+ — Signature of Authorized Agent and Title — Date Accepted 7-14-82

TO GENERATOR

BOE-C6-0214369

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO IN[illegible] LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT C[illegible]NLESS TRANSFER PAPER.

BOE-C6-0214370

Tank 257

C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

1.40

(1) Manifest Number 227 - 025105

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S Azusa Ave.
City, State, Zip West Covina Ca. 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd.
City, State, Zip Casmalia Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5

(7) EX. HAZ. WASTE PERMIT NO. 3-2745

(8) GENERATING PROCESS CHEMICAL MILLING-TANK 257

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other may Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-14-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 20839

(15) PICK-UP DATE 7/14/82
TIME 1 ☑ AM ☒ PM

(16) Andy Moren - Driver — Signature of Authorized Agent and Title — 7/14/82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. [illegible]
PHONE NO.

18 QUANTITY (If Measured) 20.18
19 STATE FEE (If Any) 80.72

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 7/19/82 Date Accepted

TO GENERATOR

BOE-C6-0214371

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAF LESS TRANSFER PAPER.

BOE-C6-0214372

Chrome District System
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024823

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Hydroxide	Corrosive		50	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS Clean Chrome Sludge

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Hydroxide	25	25	☑ % ☐ ppm.
B. Aluminum	17.5	17.5	☑ % ☐ ppm.
C. Water	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — Date Shipped 7-2-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 20832

(15) PICK-UP DATE 7-2-82
TIME ☐ AM ☐ PM

(16) P. Quinn Driver — Signature of Authorized Agent and Title — Date 7-2-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 4.79
19 STATE FEE (If Any) 4.79

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] — Signature of Authorized Agent and Title — Date Accepted 7/2/82

TO GENERATOR

BOE-C6-0214373

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR .ESS TRANSFER PAPER.

BOE-C6-0214374

C6-700-82-OPC-0096
TANK 403

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024825

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th - Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina CA 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Chromic Acid Soln	Corrosive	UN1755	1806	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS Dry Lube Strip. Tank 403

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Chromic Acid	30		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Water	70		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C.			☐ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 70 %			

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☐ Other May Cause Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-6-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 117
(15) PICK-UP DATE 7-6-82
TIME ☐ AM ☐ PM

(16) Bill Valoff — Signature of Authorized Agent and Title — 7-6-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 8.25
19 STATE FEE (If Any) 8.25

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title — 70+ — 7-6-82 Date

TO GENERATOR

BOE-C6-0214375

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSU' EGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CAR' ESS TRANSFER PAPER.

BOE-C6-0214376

TANKS 206, 207 + 212
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024820

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	3200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3.2728
(8) GENERATING PROCESS: CHEMICAL MILL, 206, 207 + 212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Roeve Buyer — Signature of Authorized Agent and Title
7-1-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 22
(15) PICK-UP DATE
TIME ☐ AM ☐ PM

(16) Bill Volotf Driver — Signature of Authorized Agent and Title
7-1-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 11.55
19 STATE FEE (If Any) 11.55

9.98

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
7-1-82 — Date Accepted

TO GENERATOR

BOE-C6-0214377

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO [illegible]ARE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT [illegible]RBONLESS TRANSFER PAPER.

BOE-C6-0214378

TANK 206, 207 + 212
C6-700-82-DPC-0096

701

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 024821

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th & Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN 1824	100	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS: CHEMICAL MILL-206, 207+212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title
7-1-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 17-21703
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 17T

(15) PICK-UP DATE 7-1-82
TIME 1:15 ☑ AM ☐ PM

(16) [illegible] Driver — Signature of Authorized Agent and Title
7-1-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 20.04
19 STATE FEE (If Any) 20.04

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R [illegible] (60) — Signature of Authorized Agent and Title
7/1/82 — Date Accep[illegible]

TO GENERATOR

BOE-C6-0214379

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous-waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO ''URE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT 'BONLESS TRANSFER PAPER.

BOE-C6-0214380

TANK 206, 207 + 212
C6-700-82-OPC-0096

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 024822

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086510005
Address: 190th + Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave
City, State, Zip: West Covina Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia, Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu	Corrosive	UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5 (7) EX. HAZ. WASTE PERMIT NO. 3-2728 (8) GENERATING PROCESS CHEMICAL MILL - 206, 207 + 212

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Aluminum Oxide	4		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sulfur	1		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D. Water	85		☑ % ☐ ppm.	Non Hazardous Material	85 %		

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other may Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title
7-1-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 2124
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21

(15) PICK-UP DATE 7-1-82
TIME ☐ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title
7-1-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 2390
19 STATE FEE (If Any) 2390

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
Date Accepted

TO GENERATOR

BOE-C6-0214381

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR.

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed bv Transporter (send photocopy to DOHS).

TO [illegible]RE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT [illegible]BONLESS TRANSFER PAPER.

BOE-C6-0214382

TANKS 203+330
C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025101

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name KETTLEMAN HILLS
EPA NO. CAT000646117
Address
City, State, Zip Bakersfield, CA

(4) Alternate TSD Facility
Name COPY
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Acid Liquid, N.O.S.	Corrosive	NA1760	2,000	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS AL. Etchant Tank 203+330

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. NITRIC ACID	10		☑ % ☐ ppm.
B. CHROMIC ACID	5		☑ % ☐ ppm.
C. Hydroflouric Acid	1		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 84 %

(10) WASTE PROPERTIES: pH 1.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other HAZARDOUS MATERIAL. MAY CAUSE SEVERE BURNS.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title
7-12-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O #21785
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21

(15) PICK-UP DATE 7-12-82
TIME 2:00 ☑ AM ☐ PM

(16) F. Mijares driver — Signature of Authorized Agent and Title
7-12-82 — Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME CWM
EPA NO. CAT000646117
PHONE NO.

18 QUANTITY (If Measured) 2000 gal
19 STATE FEE (If Any) 32.00

(21) HANDLING OR DISPOSAL METHOD:
☑ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent and Title
4/12/82 — Date Accepted

ORIGINAL

BOE-C6-0214383

TANK 257 & 259
C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025106

GENERATOR (Generator Must Complete)

(2) Name: Douglas Aircraft Co.
EPA NO. CAD086511005
Address: 190th Normandie Phone No. 533-7612
City, State, Zip: Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK Landfill
EPA NO. CAD067786749
Address: 2210 S. Azusa Ave.
City, State, Zip: West Covina, Ca 91793

(4) Alternate TSD Facility
Name: Casmalia
EPA NO. CAD020748125
Address: 429 San Ysidro Rd.
City, State, Zip: Casmalia Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS CHEM MILLING-TANK 257

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Susie Reeve Beyer — Signature of Authorized Agent and Title — Date Shipped 7-14-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O# 21837 TRUCK NO. 21 TLR. NO. 21
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

(15) PICK-UP DATE 7-14-82
TIME ☐ AM ☐ PM

(16) F. Mjares driver — Signature of Authorized Agent and Title — Date 7-14-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO. 9650911

18 QUANTITY (If Measured) 19.52
19 STATE FEE (If Any) 78.08

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) R. Sagne 60 — Signature of Authorized Agent and Title — Date Accepted 7-15-82

TO GENERATOR

BOE-C6-0214384

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSUR GIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARB SS TRANSFER PAPER.

BOE-C6-0214385

TANK 259
C6-700-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025107

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD 0865 10005
Address 190th + Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave.
City, State, Zip West Covina, Ca 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd
City, State, Zip Casmalia Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS Spent Etch Stor. Tank 259

LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS		CONC. UPPER	RANGE LOWER	UNITS
(9) A. Sodium Hydroxide	14		☑ % ☐ ppm.	E.			☐ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.	F.			☐ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.	G.			☐ % ☐ ppm.
D.			☐ % ☐ ppm.	Non Hazardous Material 80 %			

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-15-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S 0-21004
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 110
(15) PICK-UP DATE 7-15-82
TIME ☐ AM ☐ PM

(16) Mike Wagner - Dr. Vor — Signature of Authorized Agent and Title — 7-15-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 19.33
19 STATE FEE (If Any) $77.32

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] 160 — Signature of Authorized Agent and Title — 7/15/82 Date Accepted

TO GENERATOR

BOE-C6-0214386

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSUR[illegible]IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARB[illegible]SS TRANSFER PAPER.

BOE-C6-0214387

TANK 259

C6-700-82-OPC-0098

46180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025108

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co.
EPA NO. CAD086510005
Address 190th Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S Azusa Ave
City, State, Zip West Covina, CA 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd
City, State, Zip Casmalia, CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu.	Corrosive	UN1824	4200	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5

(7) EX. HAZ. WASTE PERMIT NO. 3-2745

(8) GENERATING PROCESS Spent Etch Stor-Tnk 259

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. Sodium Hydroxide	14		☑ % ☐ ppm.
B. Sulfur	1		☑ % ☐ ppm.
C. Sodium Aluminate	5		☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other May Cause Severe Burns.

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title — 7-15-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 22 TLR. NO. 21564

(15) PICK-UP DATE 7/15/82
TIME 11:30 ☐ AM ☒ PM

(16) Andy Moren-Driver — Signature of Authorized Agent and Title — 7/15/82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 20.05
19 STATE FEE (If Any) $80.20

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO

(23) [signature] 60 — Signature of Authorized Agent and Title — 7/15/82 Date Accepted

TO GENERATOR

BOE-C6-0214388

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSUR[illegible]IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARB[illegible]SS TRANSFER PAPER.

BOE-C6-0214389

TANK 259
C6-200-82-OPC-0098

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025109

GENERATOR (Generator Must Complete)

(2) Name Douglas Aircraft Co
EPA NO. CAD086510005
Address 190th - Normandie Phone No. 533-7612
City, State, Zip Torrance, CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK Landfill
EPA NO. CAD067786749
Address 2210 S. Azusa Ave
City, State, Zip West Covina CA 91793

(4) Alternate TSD Facility
Name Casmalia
EPA NO. CAD020748125
Address 429 San Ysidro Rd.
City, State, Zip Casmalia, Ca

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE Sodium Hydroxide Solu	Corrosive	UN1824	4660	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3 2745
(8) GENERATING PROCESS Spent Etch Stor. Tank 259

LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
(9) A.	Sodium Hydroxide	14		☑ % ☐ ppm.
B.	Sulfur	1		☑ % ☐ ppm.
C.	Sodium Aluminate	5		☑ % ☐ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other may Cause Severe Burns

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Suzie Reeve Buyer — Signature of Authorized Agent and Title
7-15-82 — Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21839
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21
(15) PICK-UP DATE 7-15-82
TIME ☐ AM ☐ PM

(16) F. Mores driver — Signature of Authorized Agent and Title
7-15-82 — Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 22.14
19 STATE FEE (If Any) 88.56

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) Signature of Authorized Agent and Title
7/15/82 — Date Accepted

TO GENERATOR

BOE-C6-0214390

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous-waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSUR IBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARB SS TRANSFER PAPER.

BOE-C6-0214391

TANK #206, 207 & 212

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025119

See reverse side for Instructions.
Please type or print clearly. Press Hard.

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO
EPA NO. CAD086510005
Address: 80TH NORMANDIE Phone No. 533-7612
City, State, Zip: TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK LANDFILL
EPA NO. CAD067786749
Address: 2210 S. AZUSA AVE
City, State, Zip: WEST COVINA CA 91793

(4) Alternate TSD Facility
Name: CASMALIA
EPA NO. CAD020748125
Address: 429 SAN YSIDRO ROAD
City, State, Zip: CASMALIA CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE: SODIUM HYDROXIDE	CORROSIVE	UN1824	3,000	GALS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 32745
(8) GENERATING PROCESS: CHEMICAL MILL 206, 207 & 212

(9) LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
A. SODIUM HYDROXIDE	14		☑ % ☐ ppm.
B. ALUMINUM OXIDE	4		☑ % ☐ ppm.
C. SULFUR	1		☑ % ☐ ppm.
D. WATER	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other: MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [illegible] Signature of Authorized Agent and Title — Date Shipped 7-26-82

TRANSPORTER (HAULER MUST COMPLETE)

S.O. # 21767

(14) NAME: OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 9 TLR. NO. 110

(15) PICK-UP DATE 7-26-82
TIME 500 ☐ AM ☑ PM

(16) [illegible] Driver Signature of Authorized Agent and Title — Date 7-26-82

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO. 965-7777

18 QUANTITY (If Measured) 15.15
19 STATE FEE (If Any) 60.60

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [illegible] 60 Signature of Authorized Agent and Title — 2-2[illegible] Accepted

BOE-C6-0214392

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it. Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE L[illegible]BLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CA[illegible] TRANSFER PAPER.

BOE-C6-0214393

TANK #206, 207-212

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025120

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO
EPA NO. CAD086510005
Address: 19011 NORMANDIE Phone No. 533-7612
City, State, Zip: TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: BKK LANDFILL
EPA NO. CAD067786749
Address: 2210 S. AZUSA AVE
City, State, Zip: WEST COVINA, CA 91793

(4) Alternate TSD Facility
Name: CASMALIA
EPA NO. CAD020748125
Address: 429 SAN YSIDRO ROAD
City, State, Zip: CASMALIA, CA

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE SODIUM HYDROXIDE SOLV.	CORROSIVE	UN1824	3,000	GALS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY: 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS: CHEMICAL MILL 206, 207-212

LIST COMPONENTS:

	CONC. UPPER	RANGE LOWER	UNITS
(9) A. SODIUM HYDROXIDE	14		☑ % ☐ ppm.
B. ALUMINUM OXIDE	4		☑ % ☐ ppm.
C. SULFUR	1		☑ % ☐ ppm.
D. WATER	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [illegible] Signature of Authorized Agent and Title — Date Shipped 7-26-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME: OIL PROCESS CO. 21766
EPA NO. CAD050806850
ADDRESS: 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP: Los Angeles, California 90058

TRUCK NO. 11 TLR. NO.

(15) PICK-UP DATE 7-26-82
TIME 5:00 ☐ AM ☑ PM

(16) A. [illegible] DRIVER Signature of Authorized Agent and Title — Date 7-26-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME: BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 8.78
19 STATE FEE (If Any) 35.12

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) R. [illegible] (60) Signature of Authorized Agent and Title — Date Accepted 7-27-82

TO GENERATOR

BOE-C6-0214394

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE [illegible]LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON [illegible] TRANSFER PAPER.

BOE-C6-0214395

TANK #206, 207 + 212

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

46180

(1) Manifest Number 227 - 025121

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO
EPA NO. CAD086510005
Address 190TH & NORMANDIE Phone No. 533-7612
City, State, Zip TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK LANDFILL
EPA NO. CAD067786749
Address 2210 S. AZUSA AVE
City, State, Zip WEST COVINA, CA 91793

(4) Alternate TSD Facility
Name CASMALIA
EPA NO. CAD020748125
Address 429 SAN YSIDRO ROAD
City, State, Zip CASMALIA, CA.

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE SODIUM HYDROXIDE SOLV	CORROSIVE	UN1824	3,000	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 3-2745
(8) GENERATING PROCESS CHEMICAL MILL 206, 207 + 212

LIST COMPONENTS:

(9)	CONC. UPPER	RANGE LOWER	UNITS
A. SODIUM HYDROXIDE	14		☑ % ☐ ppm.
B. ALUMINUM OXIDE	4		☑ % ☐ ppm.
C. SULFUR	1		☑ % ☐ ppm.
D. WATER	85		☑ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 85 %

(10) WASTE PROPERTIES: pH 13.0 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☑ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☑ Gloves ☑ Goggles ☐ Respirator ☑ Other MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Buyer — Signature of Authorized Agent and Title — 7-26-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. 50-21765
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO.

(15) PICK-UP DATE 7-26-82
TIME ☐ AM ☐ PM

(16) [signature] DRIVER — Signature of Authorized Agent and Title — 7-26-82 Date

TSD FACILITY (FACILITY OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 20.53
19 STATE FEE (If Any) 82.12

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☒ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA

(23) [signature] 60 — Signature of Authorized Agent and Title — 7-27-82 Accepted

TO GENERATOR

BOE-C6-0214396

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

TO INSURE L[illegible]LE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRINT CARBON [illegible] TRANSFER PAPER.

BOE-C6-0214397

TANK #9

COPY

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025123

GENERATOR (Generator Must Complete)

(2) Name: DOUGLAS AIRCRAFT CO
EPA NO. CAD986510005
Address: 190TH & NORMANDIE Phone No. 533-7612
City, State, Zip: TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name: KETTLEMAN HILLS
EPA NO. CAT000646117
Address:
City, State, Zip: BAKERSFIELD, CA.

(4) Alternate TSD Facility
Name:
EPA NO.
Address:
City, State, Zip:

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE CHRONIC		1755	2600	GPCS
WASTE ALODINE 1200				

CONTAINERS NUMBER: 1
TYPE: [ ] DRUMS [ ] BAGS [ ] CARTONS [X] TANK TRUCK [ ] DUMP TRUCK [ ] OTHER

(6) WASTE CATEGORY 1-2 (7) EX. HAZ. WASTE PERMIT NO. 32745 (8) GENERATING PROCESS CONVERSION COATING

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	CHROMIC ACID	.035		[X] % [ ] ppm.
B.	FLUORIDE SALTS	.035		[X] % [ ] ppm.
C.				[ ] % [ ] ppm.
D.				[ ] % [ ] ppm.
E.				[ ] % [ ] ppm.
F.				[ ] % [ ] ppm.
G.				[ ] % [ ] ppm.

Non Hazardous Material ____ %

(10) WASTE PROPERTIES: pH 2.6 [ ] Toxic [ ] Flammable [ ] Corrosive/Irritant [ ] Reactive [ ] Sensitizer [ ] Carcinogen/Mutagen

(11) PHYSICAL STATE: [ ] Solid [X] Liquid [X] Sludge [ ] Slurry [ ] Gas [ ] Other MAY CAUSE EXTERNAL ULCERS

(12) SPECIAL HANDLING INSTRUCTIONS: [ ] Gloves [ ] Goggles [ ] Respirator [ ] Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Bayer — Signature of Authorized Agent and Title — 7-26-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21847
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 21 TLR. NO. 21

(15) PICK-UP DATE 7-27-82
TIME 3:30 [X] AM [ ] PM

(16) F. Myers driver — Signature of Authorized Agent and Title — 7-27-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME CWM
EPA NO. CAT000646117
PHONE NO.

18 QUANTITY (If Measured) 2600 gal
19 STATE FEE (If Any) 44.00

(21) HANDLING OR DISPOSAL METHOD:
[X] Surface Impoundment [ ] Landfill
[ ] Injection Well [ ] Land Treatment
[ ] Treatment (Specify)
[ ] Recovery or Reuse [ ] Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) B. Ram — Signature of Authorized Agent and Title — 7-27-82 Date Accepted

BOE-C6-0214398

CHROME DISTRICT CO. 40180

CALIFORNIA HAZARDOUS WASTE MANIFEST

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

See reverse side for Instructions.
Please type or print clearly. Press Hard.

(1) Manifest Number 227 - 025124

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT CO
EPA NO. CAD086510005
Address 90TH NORMANDIE Phone No. 533-7612
City, State, Zip TORRANCE CA 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name BKK LANDFILL
EPA NO. CAD067786749
Address 2210 S AZUSA AVE
City, State, Zip WEST COVINA CA 91793

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE CHROMIC HYDROXIDE	CORROSIVE		1600	GALS
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☑ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 5
(7) EX. HAZ. WASTE PERMIT NO. 32745
(8) GENERATING PROCESS CLEAN CHROME SLUDGE

(9) LIST COMPONENTS:	CONC. UPPER	RANGE LOWER	UNITS
A. CHROMIC HYDROXIDE	25	25	☑ % ☐ ppm.
B. ALUMINUM	17.5	17.5	☑ % ☐ ppm.
C. WATER	57.5	57.5	☑ % ☐ ppm.
D.			☐ % ☐ ppm.
E.			☐ % ☐ ppm.
F.			☐ % ☐ ppm.
G.			☐ % ☐ ppm.

Non Hazardous Material 100 %

(10) WASTE PROPERTIES: pH 9.5 ☐ Toxic ☐ Flammable ☑ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen
(11) PHYSICAL STATE: ☐ Solid ☑ Liquid ☑ Sludge ☐ Slurry ☐ Gas ☐ Other
(12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator ☐ Other

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) Dorothy Stout Buyer — Signature of Authorized Agent and Title — 7-28-82 Date Shipped

TRANSPORTER (HAULER MUST COMPLETE) S.O. #21760

(14) NAME OIL PROCESS CO.
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 117
(15) PICK-UP DATE 7-28-82
TIME 1:00 ☐ AM ☑ PM

(16) J Toussaint Driver — Signature of Authorized Agent and Title — 7-28-82 Date

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME BKK
EPA NO. CAD067786749
PHONE NO.

18 QUANTITY (If Measured) 6.17
19 STATE FEE (If Any) 24.68

(21) HANDLING OR DISPOSAL METHOD:
☐ Surface Impoundment ☑ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT:

IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] (60) — Signature of Authorized Agent and Title — 7-28-82 Date Accepted

TO GENERATOR

BOE-C6-0214399

INSTRUCTIONS FOR COMPLETING MANIFEST

Type or print clearly. Illegible or incomplete manifests will be returned to you by the State for clarification.

GENERATOR:

ITEM (1) Before filling out the manifest, a unique manifest serial number shall be written or printed on the manifest. (Refer to TRANSPORTER item No. 1 below)

ITEMS (2)(3)(4) Provide the complete names, EPA I.D. numbers, addresses and telephone numbers of the generator and designated TSD Facilities.

ITEM (5) Provide all U.S. DOT required information. Refer to 49 CFR 172 for assistance. If not applicable write "none" in Item 5.

ITEM (6) Provide the most applicable industrial waste category number from the following list. In cases where a waste could be described by more than one category, select the most specific. (Example: If you generate a waste acid plating solution containing dissolved metal, select the category "Plating solution, acid" rather than "Acid solution" or "Heavy metal solution". If none of the listed categories adequately describe your waste, write the waste's category in Item 6.)

1. Acid sludge
2. Acid solution
3. Adhesive
4. Alkaline sludge
5. Alkaline solution
6. Alkali solids
7. Alum sludge
8. API separator sludge
9. Asbestos solids
10. Asbestos sludge
11. Ashes
12. ASD filter cake
13. Baghouse waste
14. Bilge water
15. Blasting sand
16. Capacitors, PCB
17. Catalyst
18. Chemicals, unused
19. Containers, empty
20. Contaminated equipment
21. Contaminated soil
22. Cyanides
23. Detergent
24. Distillation bottoms
25. Drilling mud
26. Drugs
27. FCC waste
28. Filter cake
29. Filters, spent
30. Flux
31. Fly ash
32. Gasoline and water
33. Glaze sludge
34. Glue
35. Hair pulp
36. Heavy metal solution
37. Heavy metal sludge
38. Ink and solvent
39. Ink sludge
40. Ink waste water
41. Laboratory chemicals
42. Lime sludge
43. Machine tool coolant
44. Machining waste
45. Metal dust
46. Oil
47. Oil sludge
48. Oil and water
49. Paint sludge
50. Pesticides
51. Pesticide containers
52. Pesticide rinse water
53. Phenolic waste
54. Photoprocessing waste
55. Plating sludge
56. Plating solution, acid
57. Plating solution, alkaline
58. Polychlorinated biphenyls
59. Resin waste
60. Scrubber sludge
61. Scrubber solution
62. Soap
63. Solvent, chlorinated
64. Solvent, hydrocarbon
65. Solvent, oxygenated
66. Solvent, mixed
67. Spill cleanup residue
68. Stretford solution
69. Sulfide sludge
70. Sump or lagoon sediment
71. Tank bottom sediment
72. Tanning sludge
73. Tetraethyl lead sludge
74. Transformers, PCB
75. Waste water treatment sludge

If waste not listed above, specify in Item 6 on manifest.

ITEM (7) If the waste is extremely hazardous, provide the State extremely hazardous permit number.

ITEM (8) Indicate the process, activity, or operation which generated the waste (Examples: aircraft cleaning, insulation, stripping, reactor cleaning, DDT production, alkylation, printed circuit board etching).

ITEM (9) INFORMATION MUST BE PROVIDED IN THIS ITEM 9, DO NOT LEAVE BLANK. Identify the major hazardous constituents in the waste along with probable upper and lower concentrations. (Examples: hydrochloric acid, lead oxide, phenol, PCB, cyanide, DDT, sodium hydroxide). Provide the approximate concentration of nonhazardous material.

ITEMS (10) (11) Check the appropriate boxes to show the hazardous properties and physical state of the waste. If a waste has more than one hazardous property (e.g., toxic and corrosive) check all appropriate properties (e.g., toxic and corrosive boxes). If the waste is an aqueous liquid, the pH must be reported in Item 11.

ITEM (12) Indicate by checking the appropriate boxes whether gloves, goggles, or respirators should be worn by persons handling the waste. Any special equipment, precautions or hazards should also be noted (Example: Sulfide solution will generate toxic gas if mixed with acids).

ITEM (13) Sign the manifest and provide your title and the date that the waste was removed from your facility. The person signing Item 13 shall be knowledgeable about the chemical and physical properties of the waste and shall be authorized by the management of the generating establishment to sign the manifest. IT IS UNLAWFUL FOR A TRANSPORTER WHO IS NOT THE GENERATOR TO SIGN ITEM 13.

TRANSPORTER:

ITEM (1) Provide the serial number of the manifest. The first three digits shall be your State hazardous waste hauler number. The six last digits may be any convenient combination of digits (e.g., sequential or chronological). For example, if your registration number is 899, the number of your one thousandth load would be 899-001000. The complete nine digit manifest number shall be unique for any five year period (Example: If you use manifest number 899-001000 on May 31, 1981, it shall not be used on a manifest again before June 1, 1986).

ITEM (14) Enter company name, EPA I.D. number, address and telephone number.

ITEM (15) Indicate the date and exact time the waste was removed from the generator's facility.

ITEM (16) Sign the manifest upon receipt of the shipment and indicate the date signed. The driver shall carry this manifest in a location prescribed in 49 CFR 177.817(e).

TSD FACILITY OPERATOR:

ITEM (17) Provide the TSD facility name and EPA I.D. number.

ITEM (18) If the quantity of waste is measured or estimated at the TSD facility (e.g., weighed), indicate the quantity.

ITEM (19) If the waste is applied to the land (e.g., surface impoundment, landfill, injection well, or land treatment area), the State hazardous waste fee must be sent to DOHS. Indicate the fee in Item 19.

ITEM (20) Write in any discrepancies noted between the manifest information provided by the generator or transporter and that found when the shipment was delivered to the facility. (Examples: differences in quantity or character of waste, container type, or vehicle type). Some significant discrepancies are described in 40 CFR 264.72.

ITEM (21) Check the box(es) to indicate the method(s) used to handle or dispose of the waste at the hazardous waste facility. If the waste is treated prior to, or instead of, land disposal write in the treatment method (Examples: neutralization, incineration, oxidation).

ITEM (22) If the waste is held at the TSD facility prior to eventual shipment to another facility for treatment, storage, or disposal, provide the name of the designated final TSD facility and its EPA I.D. number. In such cases, you, as the facility operator (transfer station), shall fill out a new master manifest indicating your facility as the generator of the waste and describing all the wastes in the shipment. Completed copies of all original manifests associated with the original waste shipments accepted by you shall be attached to the master manifests.

ITEM (23) Sign the manifest, provide your title within the organization and indicate the date that the shipment was accepted at your facility.

The facility operator shall send a copy of the completed manifest to the DOHS, on a monthly basis, or as otherwise required. If wastes are received from transfer facilities, the final TSD facility shall send copy number 1 of each master manifest to DOHS with copies of all original manifests STAPLED to it.

Transfer facilities shall send only one set of copies to DOHS to satisfy the manifest submission requirements for generators and TSD facilitity operators.

DISTRIBUTION OF MANIFEST COPIES: Copy No. 1 (Original): TSDF keeps - (send photocopy to DOHS); Copy No. 2: To Transporter after signed by TSDF; Copy No. 3: To Generator from TSDF; Copy No. 4: Generator keeps after signed by Transporter (send photocopy to DOHS).

T JURE LEGIBLE COPIES USE ONLY BLACK CARBON INSERTS OR BLACK PRIN RBONLESS TRANSFER PAPER.

BOE-C6-0214400

TANK #179

CALIFORNIA HAZARDOUS WASTE MANIFEST

See reverse side for Instructions.
Please type or print clearly. Press Hard.

COPY

State Department of Health Services
HAZARDOUS MATERIALS MANAGEMENT SECTION
744 P Street, Sacramento, CA 95814

(1) Manifest Number 227 - 025125

GENERATOR (Generator Must Complete)

(2) Name DOUGLAS AIRCRAFT Co.
EPA NO. CAD086510005
Address 190TH NORMANDIE Phone No. 533-7612
City, State, Zip TORRANCE, CA. 90502

(3) Designated TSD Facility (Authorized to operate under an approved state program or federal program)
Name KETTLEMAN HILLS
EPA NO. CAT000646117
Address
City, State, Zip BAKERSFIELD, CA.

(4) Alternate TSD Facility
Name
EPA NO.
Address
City, State, Zip

(5) U.S. DOT PROPER SHIPPING NAME	U.S. DOT HAZARD CLASS	UN/NA ID NO.	WEIGHT OR VOLUME	UNITS
WASTE NITRIC ACID SOLUTION	CORROSIVE	NA1760	1500	GALS.
WASTE				

CONTAINERS NUMBER: 1
TYPE: ☐ DRUMS ☐ BAGS ☐ CARTONS ☒ TANK TRUCK ☐ DUMP TRUCK ☐ OTHER

(6) WASTE CATEGORY 2 (7) EX. HAZ. WASTE PERMIT NO. 3-2745 (8) GENERATING PROCESS ALUMINUM ETCH TANK 179

(9) LIST COMPONENTS:

		CONC. UPPER	RANGE LOWER	UNITS
A.	NITRIC ACID	20		☒ % ☐ ppm.
B.	WATER	80		☒ % ☐ ppm.
C.				☐ % ☒ ppm.
D.				☐ % ☐ ppm.
E.				☐ % ☐ ppm.
F.				☐ % ☐ ppm.
G.				☐ % ☐ ppm.

Non Hazardous Material 80 %

(10) WASTE PROPERTIES: pH 1 ☐ Toxic ☐ Flammable ☒ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen

(11) PHYSICAL STATE: ☐ Solid ☒ Liquid ☒ Sludge ☐ Slurry ☐ Gas ☐ Other

(12) SPECIAL HANDLING INSTRUCTIONS: ☒ Gloves ☒ Goggles ☒ Respirator ☒ Other HAZARDOUS LIQUID MAY CAUSE SEVERE BURNS

GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA.

IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802

(13) [signature] Assistant Foreman — Signature of Authorized Agent and Title — Date Shipped 7-29-82

TRANSPORTER (HAULER MUST COMPLETE)

(14) NAME OIL PROCESS CO. S/O # 21895
EPA NO. CAD050806850
ADDRESS 5756 Alba Street PHONE NO. (213) 585-5063
CITY, STATE, ZIP Los Angeles, California 90058

TRUCK NO. 17 TLR. NO. 21

(15) PICK-UP DATE 7-29-82
TIME ☐ AM ☐ PM

(16) [signature] DRIVER — Signature of Authorized Agent and Title — Date 7-29-82

TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE)

(17) NAME CWM
EPA NO. CAT000646117
PHONE NO.

18 QUANTITY (If Measured) 1,500 gal
19 STATE FEE (If Any) 28.00

(21) HANDLING OR DISPOSAL METHOD:
☒ Surface Impoundment ☐ Landfill
☐ Injection Well ☐ Land Treatment
☐ Treatment (Specify)
☐ Recovery or Reuse ☐ Storage/Transfer

(20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND SHIPMENT.

WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY:

(22) NAME
EPA NO.

(23) [signature] — Signature of Authorized Agent — 7-30-82

BOE-C6-0214401