From:	Loth, Cameron
To:	Galinsky, Virginia
Cc:	Apolinario, Valeria
Subject:	RE: Questions on CD Semi-Annual Reports
Date:	Wednesday, October 5, 2022 8:30:38 AM

Hi Virginia,
Thank you for your kind words; quite a sad time in the refinery as you can imagine. In regards to the information you requested, would end of day 10/11 work for you? I will hopefully have it here in a few days but just want to make sure I don't over promise.
Thanks again,
Cameron

From: Galinsky, Virginia <Galinsky.Virginia@epa.gov>
Sent: Tuesday, October 4, 2022 2:59 PM
To: Loth, Cameron <Cameron.Loth@bp.com>
Cc: Apolinario, Valeria <Apolinario.Valeria@epa.gov>
Subject: Questions on CD Semi-Annual Reports

Hi Cameron,

Our sincere condolences for the recent incident at the facility and the loss of two BP workers. We were deeply saddened to see the news reports.

We are reaching about because after reviewing the semi-annual CD reports submitted to date, we have compiled a few questions about what was reported. Please see below.

1. Finding Number 3 in BP Husky's 2020 Consent Decree (CD) Audit – Corrective Action Plan (CAP) reported a late first attempt at repair for one control valve in the East Alstom Boiler Unit.
    a. On what date was the leak first detected?
    b. How many days after the 5-day threshold was the repair attempted on the leak?
    c. Was a final repair attempt necessary, and if so, when did it occur?
2. The Comparative Monitoring Finding in BP Husky's 2020 Consent Decree Audit- CAP reported a result above threshold values in the Unsat Gas Plant (valves & pumps) and the LPG Unit (valves).
    a. What is the historic leak percentage for the Unsat Gas Plant?
    b. What is the historic leak percentage for the LPG Unit?
    c. What was the leak percentage for each the Unsat Gas Plant and the LPG Plant during the audit?
3. On Page 7 of BP-Husky's 2020 CD Annual LDAR Compliance Status Report, BP-Husky reported that three valves at the LPG Unit were found untagged. Had these valves been in the LDAR database and timely monitored (i.e. were just missing the field tag) or had they not been in the LDAR database and had missed monitoring?
4. On Page 4 of BP-Husky's 2021 CD Annual LDAR Compliance Status Report, BP-Husky reported that one valve did not receive Repair Verification Monitoring by the end of the next day after a repair attempt. The repair was made Saturday 12/11/21 but was not checked by the end of 12/12/21. On what date did this valve receive Repair Verification Monitoring?

Let me know if you need any clarification on any of the questions.

I'm sure that the recent incident is impacting your work, so we can be flexible with the timeline of

your response to these items. Please let me know when you think would be a reasonable time to reply by.

Best regards,

Virginia Galinsky
Environmental Engineer
Air Enforcement & Compliance Assurance Branch
U.S. EPA, Region 5
Phone: (312) 353-2089
Fax: (312) 697-2711
galinsky.virginia@epa.gov