10/08	E1107 Crude outlet Block valve 16" leaks by.
10/08	Replace 2" steam supply block valve at V1190 stanchion. (V1190 clean up steam)
5/31/07	Steam Line to P1101-A – block valve bad – leaks by – cannot install blind – 3". PP# 26228811
8/9/09	Remove & inspect all F-1160 velocity steam spools – 2 Bad check valves discovered during pit stop , (pass 3, 8 – pass 8 was replaced) also, two globe valve leakers on pass 3, 8.
9/21/09	Replace P1101-A suction valve – leaker during pit stop.
9/21/09	K1171 loopseal MU bypass gate valve broken. Maximo # 252984
9/21/09	K1100B 1st stg suction B/V B/O Maximo # 248258
9/21/09	P1167 Seal flush supply high point vent no plug- valve has no threads. Maximo # 243609
9/21/09	reco 64917 flush oil piping cui Maximo# 235297
9/21/09	cui damaged piping Maximo# 213265
9/21/09	E1103 E1106 outlet valve leaks by. Maximo # 213265
9/21/09	E-1111 crude side B/P stuck open? (not to be confused with ABCR B/V that is stuck open)
9/21	Modify P1179 steam quench piping (per Brad) MAXIMO # 27015
9/24	MULTIPLE LEAKS ON MIST OIL LINES GO AROUND AND TIGHTEN UP ON PIPEING
9/30	Resid Value → SDA Tankage
10/1/09	• INSTALL P-1165/A DOUBLE-BLOCKS ON THE DISCHARGE LINES.

CRAMPED AND RESTRICTIVE FOR SAFE AND ERGONOMICALLY CURRENT POSITIONING. ENLARGE PLATFORM TO ACCOMODATE THESE CHANGES.

10/10 - PUT BLOCK VALVES to issolate seal flush before flanges on P1159/59A. P-1159 flange GASKET is leaking AND CANNOT issolate to DO ON RUN.

4crude - 11PT002 gate valve for Transmeter & gate vale on manifold needs Replacement! (see Mike Pater intrument guy)

10/22 - P-1189 REPACK 3" wash oil block VALVE leaks and BAY VALVE said CANNOT TIGHTEN UP ON ANY MORE DURING PIT STOP.

10/22 [redacted]

PKing 10/27/09

Why do we have EBV's on P1190's + Not on P1195's.

4/13 - MOV ON P-1159A is ON 5 S/C line pump is in 6 S/C service Need to move for emergency situation's

- New block valve 150 pound main block to P-1198 relief pump