MADE IN TACOMA
SINCE 1916
Rite in the Rain
DEFYING MOTHER NATURE

Name Des Moines TCE Site
1698 Wabash St.
Address Des Moines, IA 50309

Phone

Project

RiteintheRain.com

CONTENTS Book 1 of 2

PAGE	REFERENCE	DATE
	START Program Manager	
	Ted Faile	
	START Project Manager	
	Mike Williams	
	EPA Project manager	
	Erin McCoy	
	START Team Members	
	Adam Watkins	
	Shane Strope	
	Christin Russell	
	GUARD SHACK PHONE: 515-803-4425	

6-6-2016

1200 ADAM WATKINS (TT) & SHANE STROPE (TT) ARRIVE @ 1698 WABASH ST. IN DES MOINES, IOWA (SITE). BRIAN MILLS & GABI GEORGE (TITAN) ARE ONSITE.

1213 ERIN McCOY (EPA PM) ARRIVES ONSITE.

1230 TITAN REPRESENTATIVES SHOW START MEMBERS A SECURE LOCATION TO STORE SAMPLING EQUIPMENT/SUPPLIES.

1300 ALL PARTIES PERFORM A SITE WALK OF THE FACILITY & START MARKS DPT LOCATIONS W/ PAINT.

1430 WATKINS & STROPE DEPART SITE TO RUN OVER THE HOSPITAL ROUTE & GRAB SUPPLIES.

1245 NOTE: WATKINS CONDUCTED A DAILY TAILGATE MEETING & HAD EVERYONE SIGN THE SITE HASP.

1530 WATKINS & STROPE ONSITE. PREP TO COLLECT SEDIMENT SAMPLES AROUND THE SOUTH POND AREA.

1620 7151-1 Sed Sample
7151-2-FD
1640 7151-2 Sed Sample
1745 COLLECT 7151-3. SEDIMENT SAMPLE.
1830 1840 COLLECT 7151-4. SEDIMENT SAMPLE.

6-6-2016

1850 WATKINS & STROPE RETURN TO THE SITE STAGING AREA & UNLOAD VEHICLE.

1915 TEAM DEPARTS SITE.

1940 TEAM ARRIVES @ HOTEL. END OF DAY.

6-6-2016

Rite in the Rain

6-7-16

0653 WATKINS & STROPE ARRIVE @ THE SITE. MCCOY & TITAN REPS ALREADY ONSITE. START MOVES TO STAGING AREA TO PREP FOR SAMPLING SEDIMENT IN THE SOUTH POND AREA.

0715 START ARRIVES IN THE SOUTH POND AREA & FINDS A SLEEPING HOMELESS MAN ~~w~~ NEARBY. STROPE CALLS SECURITY WHO RUNS THE HOMELESS MAN AWAY FROM THE SITE, & CALLS THE POLICE.

0720 WATKINS CONDUCTS A MORNING SAFETY TAILGATE MEETING. TOPICS INCLUDE BITING INSECTS, SECURITY, & WINDY CONDITIONS.

0740 WATKINS & STROPE BEGIN SEDIMENT SAMPLING ACTIVITIES.

0800 COLLECT 7151-~~4~~ 5. SEDIMENT SAMPLING.

0810 COLLECT 7151-6. SEDIMENT SAMPLE.

0830 COLLECT 7151-7. SEDIMENT SAMPLE.

0900 COLLECT 7151-8. SEDIMENT SAMPLE.

0920 COLLECT 7151-9. SEDIMENT SAMPLE.

0940 COLLECT 7151-10. SEDIMENT SAMPLE.

1000 RETURN TO STAGING AREA TO STORE SEDIMENT SAMPLE & WAIT FOR THE

6-7-16

PRIVATE UTILITY LOCATORS TO ARRIVE ONSITE.

1118 PRIVATE UTILITY LOCATOR, RICK NORLAND (CCS) ARRIVES ONSITE. HE SIGNS THE HASP.

1130 START UTILITY LOCATING ACTIVITIES.

1250 RICK NORLAND FINISHES UTILITY LOCATING ACTIVITIES. ALL DPT LOCATIOI HAVE BEEN CLEARED. NORLAND DEPARTS SITE. CHRISTIN RUSSELL (TT) ARRIVES ONSITE. SHE SIGNS THE HASP.

1300 START PREPS TO COLLECT SURFACE WATER SAMPLES IN THE SOUTH POND AREA.

1400 COLLECT 7151-401-FD 7151-401. SURFACE WATER SAMPLES.

1430 COLLECT 7151-402. SURFACE WATER SAMPLE.

1510 RETURN TO SITE STAGING AREA.

1640 COLLECT 7151-407-FB. FIELD BLANK SAMPLE.

1641 Depart site. Travel to hotel to package samples.

1800 Depart hotel. Travel to FedEx.

Rite in the Rain

6-7-16

1900 Depart Fed Ex. End field work.

6-7-16
C. Russell

6-8-16

0700 Arrive on site. Meet with Plains, Erin (EPA), and Titan representatives. Watkins conducts safety tailgate. Topics include hearing and vision protection, slips trips & falls & site security.

0745 Arrive at building 5 Watkins and Russell assist with Geoprobe activities.

1000 Arrive at building 3, prep for wipe samples.

1030 IDNR arrives on site.

1050 Collect sample 7151-201, SW WALL brick

1100 Collect sample 7151-202, I-beam, SE corner

1107 Collect sample 7151-203, concrete floor, north central

1115 Collect sample 7151-204, sheet metal, East side

1125 Arrive at Building 2

1130 Collect sample 7151-205, concrete floor, East side

1140 Collect sample 7151-206

Rite in the Rain

6-8-16

north side of building, brick

1150 Collect sample 7151-207, I-beam Central part of building

1155 Collect sample 7151-208, Coated sheet metal, SW wall

1210 Arrive at Geoprobe to assist with activities.

1230 Depart site for lunch break. Purchase field supplies (ice).

1320 Arrive on site. Prep for building materials sampling. Arrive at building 3

1340 Collect sample 7151-301, brick center of east wall

1410 Collect sample 7151-302, insulation, center of south wall

1420 Collect sample 7151-303, cinder block, SW corner

1432 Collect sample 7151-304, white surface coating, center of east wall.

Arrive at building 2

1450 Collect sample 7151-305, brick, center of east wall

6-8-16

1505 Collect sample 7151-306, insulation, center of south wall.

1514 Collect sample 7151-307, cinderblock, center of north wall

1521 Collect sample 7151-308, white surface coating, center of building

1528 Collect sample 7151-309, dry wall furthest northeast corner. CENTRAL ROOM.

1545 Collect sample 7151-310, brick, SOUTH WALL.

1551 Collect sample 7151-311, insulation, CENTER OF BUILDING.

1559 Collect sample 7151-312, dry wall. EAST WALL.

1606 Collect sample 7151-313, white surface coating. WEST WALL

1620 Collect sample 7151-209, CONCRETE FLOOR, CENTER OF BUILDING

1630 Collect sample 7151-210, BRICK WALL, WEST SOUTH WALL

1640 Collect sample 7151-211, SHEET METAL, NORTH WALL

1650 Collect sample 7151-212 METAL BOX. CENTER OF BUILDING

Rill in the Rain

6-8-16

1730 Depart site. Break for dinner

1830 Watkins, Strope, + Russell prep samples at hotel, for shipment.

0030 End Field activities.

6-8-16
C. Russell

6-9-16

0700 Arrive on site. Morning meeting with EPA, Titan, + Plains. Watkins conducts safety tailgate meeting. Topics include Geoprobe activities, heat, eye + hearing protection, respiratory protection

0745 Arrive at Production Building

0750 Collect sample 7151-318, dry wall, center of north wall

0758 Collect sample 7151-319, large brick, northwest corner

0806 Collect sample 7151-315, small brick, west central building

0812 Collect sample 7151-316, cinder block, west wall

0818 Collect sample 7151-317, insulation, yellow, north wall-ceiling

0830 Collect sample 7151-3169, pink insulation, center of north wall

0842 Collect sample 7151-320, ridged brick, center of building

0845 Collect sample 7151-321, white surface coating, center of bldg

Rite in the Rain

6-9-16

0853 Collect sample 7151-322, interior insulation, central eastern wall

0859 Collect sample 7151-323, wood wall, center of building

0941 Collect sample 7151-324, wood wall, SE wooden building

Depart site. Travel to hotel

1120 to pick up sampling supplies. Lunch break.

1215 Arrive on site. Arrive at Production Building G

1300 Collect sample 7151-213, dup, concrete north central part of building

1312 Collect sample 7151-214, concrete, center of building

1324 Collect sample 7151-215, concrete, south central part of building

1355 Collect sample 7151-216, I-beam central-eastern part of building

1403 Collect sample 7151-217, I-beam center of building

1409 Collect sample 7151-218, I-beam, northwest corner

1434 Collect sample 7151-219, dup

6-9-16

Sheet metal, SE corner

1443 Collect sample 7151-220, sheet metal, ~~SE corner~~ or NW corner

1500 Collect sample 7151-221, brick central-eastern part of building

1510 Collect samples 7151-222 and 7151-222-FD, brick, SW corner

1530 Begin prepping samples for PACE shipment (Dioxin)

1615 Depart site to purchase field supplies.

1630 Return to site, complete sample preparation.

1900 Depart site. Travel to FedEx to ship samples

2000 Arrive at hotel. Break for dinner.

2100 Begin sample prep for EPA delivery

0030 End Field Activities

6-9-16
C. Russell

Rite in the Rain

6-10-16

0705 WATKINS & STROPE ARRIVE @ THE SITE. WATKINS CONDUCTS A MORNING SAFETY TAILGATE MEETING. TOPICS INCLUDE SLIPS, TRIPS, & FALLS, PRODUCTION, BUILDING HAZARDS, & HEAT EXHAUSTION. ATTENDEES INCLUDE McCOY (EPA), BRIAN MILLS & GABI GEORGE (TITAN), & HENRY (PLAINS).

0715 MOVE TO SOUTH DPT SAMPLE LOCATION & PREP TO BEGIN DPT SAMPLING ACTIVITIES. DPT SAMPLING ACTIVITIES BEING DOCUMENT-ED W/ LOG BOOK 2.

1300 COLLECT FB-1. FIELD BLANK SAMPLE (DIOXIN).

1310 COLLECT RB 7151-404. RINSATE BLANK SAMPLE.

1320 LOAD SUPPLIES / EQUIPMENT INTO VEHICLE.

1340 DEPART SITE.

Rite in the Rain