	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7	ECA0100	International Tanker Management Limited	ST AQUA	LR	9345881	1/29/2015

	G	H	I	J	K
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	NINGBO	LABUAN; YOSU; PANAMA	PANAMA	NA	NA

	L	M	N	O	P	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	NA	3/29/2015	16:00	3.22	48	ST ROSE

	R	S	T	U	V
1					
2					
3	18	19	20	21	22
4					
5					
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
7	Y	N	NA	NA	Y

	W	X	Y	Z
1				
2				
3	23	24	25	26
4				
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7	N	NA	4/20/2015	12:00

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4					
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
7	Y	10	3	N	1

	AF	AG	AH
1			
2			
3	32	33	34
4			
5			
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	Mr LARS MODIN	itm.dubai@tankermanager.com	97144403600

	AI
1	
2	
3	35
4	
5	
6	Description of Actions to Achieve Compliance
7	Vessel has compliant fuel on board. However after changeover from HFO to LSMGO, fuel oil pumps started leaking. In view of this the vessel has anchored in a safe location outside the entrance to Mississippi river. We request permission to enter the port as a one off case using Heavy Fuel Oil as the fuel for main engine. We will arrange all spares and carry out the repairs in the port.