Lindahl Marine

Putting customers first since 1974

May 4, 2017

Tom Barnett
Manager, Environmental Technology
Arcelor Mittal Indiana Harbor
3001 Dickey Road
East Chicago, IN 46312

Re: Canal outfall inspection

Dear Mr. Barnett,

Thank you for requesting an inspection from Lindahl Marine Contractors, Inc. We are pleased to provide you with the following findings.

On 04/11/2017 we performed an underwater survey of the underwater conditions of the canal outfall at the river for the above referenced facility. Approximately fifty feet of the intake pipe, the entire concrete spillway outside the outfall pipe and directly outside the baffle going into the river was inspected.

We found a light dusting of silt throughout and a few scattered stones but found no oil or evidence of oil anywhere. The concrete was all clean and in good condition with no signs of any anomalies. The same was found outside the baffle on the river side off the baffle in front of the outfall.

If you have any questions please contact me at 815-521-3333.

Sincerely,

Pete Perich Jr.
Vice President of Operations

740 Twin Rail Drive **Minooka, IL 60447** **Ph: 815.521.3333** **Fax: 815.521.1605**
www.LindahlMarine.com