**948 ENE > 1 1.262 mi. 6664 ft.** | **MANHOLE 62619 AVE Z/HOMECREST AVE BROOKLYN, NY** | **NY Spills** | **S105056846 N/A**

**Relative: Higher**

**Actual: 10 ft.**

SPILLS:

| | |
|---|---|
| Name: | MANHOLE 62619 |
| Address: | AVE Z/HOMECREST AVE |
| City,State,Zip: | BROOKLYN, NY |
| Spill Number/Closed Date: | 0100948 / 2001-08-22 |
| Facility ID: | 0100948 |
| Facility Type: | ER |
| DER Facility ID: | 153938 |
| Site ID: | 183919 |
| DEC Region: | 2 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 2401 |
| Spill Date: | 2001-04-24 |
| Investigator: | JHOCONNE |
| Referred To: | Not reported |
| Reported to Dept: | 2001-04-25 |
| CID: | 397 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-04-25 |
| Spill Record Last Update: | 2001-09-10 |
| Spiller Name: | Not reported |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PLACE |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS REPORT 4-24-01 Approx. 1oz. of dielectric fluid had leaked from cable ends onto 500gals. of water. No apparent environmental impact. Liquid sample taken for PCBs and maked for emergency turnaround. LSN 01-05162-001 256ppm 0150hrs. UG is in hole splicing, they have a hot zone set up and a over 50 ppm tanker on location to keep water down. When splicing is comleted flush crew will begin clenaup. 0325hrs. Since there is a earthen sump in structure and sample results are over 50ppm, when cleanup is completed they will have to take sample from sump and will have to wait for results. We will not meet the 24hr. criteria. 1200hrs. Env. Ops reports structure double washed with Bio Gen 760, liquid removed by tanker. 5 sump samples taken and sump sealed. tag remains pending results. 4-27-01 1406hrs. Composite soil sample from sump bottom <1.0ppm(LSN 01-05187), composite soil from sump walls 2ppm Tag removed, job complete. " |
| Remarks: | "1 oz on top of 500 gallons of water pending results" |

All Materials:

| | |
|---|---|
| Site ID: | 183919 |

| | |
|---|---|
| Operable Unit ID: | 837861 |
| Operable Unit: | 01 |
| Material ID: | 536663 |
| Material Code: | 0541A |
| Material Name: | dielectric fluid |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |