11000212 9535
A1/A1/CO
AR752

RECEIVE
FEB 28 2007
Air/Toxics & Inspection
Coordination Branch
6EN-A

February 23, 2007

Mr. Robert Todd
US EPA Region 6
Air Enforcement Section (6EN-AA)
1445 Ross Avenue
Dallas, Texas 75202-2733

Re: Annual Compliance Certification for Weyerhaeuser – Dierks Mill, AFIN 31-00016

Dear Mr. Todd:

Enclosed is a signed copy of the Title V Annual Compliance Certification (ACC) for the Weyerhaeuser mill located in Dierks, Arkansas. The Mill operated under Permit No. 0023-AOP-R3 during the reporting period (February 1, 2006 through January 31, 2007). The signed original was submitted to ADEQ.

If you have any questions about the enclosed reports, please contact me at (870) 286-4380 or Mr. Jeremy Jewell of Trinity Consultants at (501) 225-6400.

Sincerely,

WEYERHAEUSER COMPANY

Larry Huntsberger

Larry Huntsberger
Environmental Manager

Enclosures

cc: Jeremy Jewell – Trinity Consultants

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to **Air Enforcement** at (501) 682-0059, email it to airsubmission@adeq.state.ar.us , or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R3** AFIN: **31-00016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **5/19/2006-5/20/2006** Duration: **156 min., 42 min.**

Time of Upset (starting & ending): **23:48-02:24, 9:12-9:54**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **40.1%**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Planned boiler shutdown for maintenance**

Corrective Actions Taken: **ESP retuned to normal operation after boiler restarted and proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870 286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 2/06

ADEQ

ARKANSAS

Department of Environmental Quality

Air Division – Compliance Enforcement
8001 National Drive, PO Box 8913
Little Rock, Arkansas 72219-8913
Phone: (501) 682-0729
Fax: (501) 682-0059

UPSET CONDITION REPORT FORM

Instructions:

1. *Please make copies of this form to complete. Additional copies of this form may be obtained from the Air Division of the Department.*
2. *Fax the report to* ***Air Enforcement*** *at (501) 682-0059, email it to airsubmission@adeq.state.ar.us , or mail it to the above address by the end of the next business day of the upset.*

Facility Name: **Weyerhaeuser Company**

Location: **Dierks, Arkansas**

Permit Number: **0023-AOP-R3** AFIN: **31-00016**

Equipment in Upset: **No. 7 Boiler – Opacity**

SN# (source number listed in permit): **45**

Date of Upset: **5/22/2006** Duration: **630 min.**

Time of Upset (starting & ending): **13:00-20:24, 20:36-21:54, 22:12-24:00**

Pollutant(s) Involved in Upset (if known): **Opacity**

Emission Rate During Upset (if known): **80.0%**

Violated Emission Limit: **20%** (limit listed in your permit)

Cause of Upset: **Startup after shutdown for maintenance**

Corrective Actions Taken: **ESP retuned to normal operation after boiler restarted and proper stack temperature reached.**

Name of Person Completing Report: **Larry Huntsberger**

Phone: **870 286-4380** Fax: **870 286-4241** Email: **larry.huntsberger@weyerhaeuser.com**

form updated 2/06