To: Peachey, Robert[peachey.robert@epa.gov]
From: Moore, Kendall
Sent: Wed 2/24/2016 3:18:41 PM
Subject: Fw: test email
SVE EHSI PCB 011516.pdf

From: Mullin, Michelle
Sent: Tuesday, February 23, 2016 4:25:28 PM
To: Moore, Kendall; Ramanauskas, Peter; Skadowski, Suzanne
Cc: Star, David
Subject: FW: test email

All-

Attached is the report conducted by an environmental health and safety consultant for the Monroe school in January. It consists of a single wipe test, and 2 air tests. I have also requested any data from the subsequent follow-up sampling their consultant has collected, but they said that right now they do not have data ready to disseminate. I have requested that any preliminary data be shared with us, I'll try to find out how far away from final results they are.

Take care,

Michelle Mullin

PCB Coordinator

US EPA Region 10

1200 6th Avenue |Suite 900 | AWT-150

NOTE NEW MAILING ADDRESS

Seattle, WA 98101

mullin.michelle@epa.gov

206-553-1616

www.epa.gov/region10/pcb.html

From: Piplic, Devlin [mailto:piplicd@monroe.wednet.edu]
Sent: Tuesday, February 23, 2016 2:10 PM
To: Mullin, Michelle <Mullin.Michelle@epa.gov>
Cc: Gregg Middaugh <Gregg.Middaugh@pbsenv.com>
Subject: Re: test email

Michelle,

Here is the report that you request. We currently have Gregg from PBS assisting with the environmental concerns at Sky Valley Education Center. I have included him in the email if you have any additional questions. As for the PCB analysis, Gregg has not completed his analysis of that data so I am not sure he has anything to provide yet as he is still testing.

We are currently in the process of removing all ballasts from Sky Valley Education Center. Pleas let me know if there is anything else or questions I can answer.

Devlin

On Fri, Feb 19, 2016 at 4:32 PM, Mullin, Michelle <Mullin.Michelle@epa.gov> wrote:

Thanks!

If you could send me the following on Monday, that would be great:

1. Contact information for the consultant
2. Report showing analysis for PCBs from initial assessment
3. Any subsequent data or report showing PCB analysis
4. Status of Fluorescent Light Ballast removal

I'll follow up with my email about cleanup methods.

Take care,

Michelle Mullin

PCB Coordinator

US EPA Region 10

1200 6th Avenue |Suite 900 | AWT-150

NOTE NEW MAILING ADDRESS

Seattle, WA 98101

mullin.michelle@epa.gov

206-553-1616

www.epa.gov/region10/pcb.html

From: Piplic, Devlin [mailto:piplicd@monroe.wednet.edu]
Sent: Friday, February 19, 2016 4:30 PM
To: Mullin, Michelle <Mullin.Michelle@epa.gov>
Subject: Re: test email

I got your email.

On Feb 19, 2016 4:02 PM, "Mullin, Michelle" <Mullin.Michelle@epa.gov> wrote:

Michelle Mullin

PCB Coordinator

US EPA Region 10

1200 6th Avenue |Suite 900 | AWT-150

NOTE NEW MAILING ADDRESS

Seattle, WA 98101

mullin.michelle@epa.gov

206-553-1616

www.epa.gov/region10/pcb.html

Any dissemination or use of this information by a person other than the intended recipient is unauthorized and may be illegal. If you have received this e-mail in error, please immediately notify us by return e-mail. All email to and from this domain is archived as a public record in compliance with federal and state requirements. As such they may be both discoverable in a legal action and available through a public records request.

--

Devlin Piplic
Director of Facilities
Monroe School District
200 East Fremont
Monroe, WA 98272
Office: 360.804.2679

Any dissemination or use of this information by a person other than the intended recipient is unauthorized and may be illegal. If you have received this e-mail in error, please immediately notify us by return e-mail. All email to and from this domain is archived as a public record in compliance with federal and state requirements. As such they may be both discoverable in a legal action and available through a public records request.