W/O Flame Stabilizers

Overhead: negative recirculation
We know what will happen

- Will not function with existing spin vanes
  - flat blade design
  - located too far back
  can not achieve targeted swirl factors + recirc. parameters

- BW has not addressed or acknowledged this condition
  - No provisions made in their design
  -

Operation - changes made purely for 1350F to allow thermal expansion
same mode of operation

Need to know by end of week (DROP DEAD on fabrication)
Already 8% premium (needed to know 1st of month)