RJM

discussion

Nissen

Smokey flames:

UIA If outers further open than requested (4¼)
due to sloop, ~~more~~ ~~rob~~ rob air ~~from~~ from inner zone
more outer to outer will see smoker flames

Test close down 1 notch on all 6 burners
registers (on-line) push open / causes you to have more area/depth
than expected

dual probe:
1st inner probe - bad 1½ days

{ suspect magnitudes

stingers - broken leads
vibrated loose