Discuss Operating as same conditions
before / after mods

WB damper pos
burner temps
Excess Air levels { which out point where SOC increased EA [last summer 92]