Burn front

TC's

inconclusive

Reused some T/C's
poor attachment
slightly different location
many inoperable

monthly perf testing