Pulv 2C O/S

~~Sw~~ Swapping pulv 2 G O/S

2 Pulv C O/S

O_2 profile

4/28

Coalquality issues

@ same SO_2 inlet as yesterday

however

Pulv loading up / Bias PA

Concern have to go w/ PA fan high speed

flyash / yesterday OK
today poor

What else has changed?

look @ WBductpress (1 & 3 burner levels - low throttle 2 & 4 more

look @ 1 BAM's (flow + ΔP's)

need data
downloaded

Burner Info

Mon - spin vane adjustments

Tues

No Bids - issues

all 8 profile 8

Wed profile pulv C

Ther

Submit BIDS

Fri

next week