Costs for WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO.....	Description.....	Part No	Part Noun Qual.....	Part Qty Issued	Tot Material Act	Act Tot Labor Cost	Actual Tot Cost
			JOHNSON CONTROLS P/N FTG18A600R				
		30552	COMPOUND, SEALANT	6			
		54203	BANDING, MATERIAL	1			
		50200	BOX, JUNCTION	1			
		58397	CONDUIT, RIGID	1			
		5522	TERMINAL, 1 HOLE LUG	3			
		5523	TERMINAL, 1 HOLE LUG	12			
		34946	FITTING, COPPER SOLDER	20			
		34960	FITTING, COPPER SOLDER	20			
		51271	FITTING, BRASS CONNECTOR	2			
		51243	FITTING, BRASS CONNECTOR	0			
02-60456-23	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR PHIL HAILES) FOR HVAC DUCT RELOCATION	50638	ROD, ALLTHREAD	87	206.88	564.38	771.26
		53506	STEEL, SHEET	0			
		30300	PAINT, SPRAY	0			
02-60456-24	RETURN PRINTED OUTPUT BOARD TO FOXBORO FOR REPAIR/REPLACEMENT.	D	REPAIR & RETURN: BOARD, PRINTED, OUTPUT, FOXBORO P/N 3A2-D2I, IPSC STK NO. 2627 **REFERENCE RA NO. 56249**	0	270.00	0.00	270.00
02-60456-25	OPEN / CLOSE ACCESS DOORS TO THE NEW OVERFIRE AIR DUCT FOR INSPECTION DURING MINI-OUTAGE.			0	0.00	1,002.86	1,002.86
02-60456-26	INSTALL NEW BEARINGS ON THE OVERFIRE AIR DAMPER SHAFTS. TRACKING WORK ORDER FOR (PHIL HAILES). PIPE / POPPET VALVE FLANGE GASKET REPLACED.	D	BEARING, FLANGE, SOLID-LUBE LT700, 4-BOLT FLANGE, 1-3/4" SHAFT, M/N F4BLT700, DODGE P/N 033272	0	1,117.52	0.00	1,117.52
02-60456-27	FABRICATE 4 ea SLAG HAMMERS PER THE ATTACHED DRAWING.	53413	STEEL, ROUND	13	20.62	174.55	195.17
		5337	HAMMER, CHIPPING	0			
		50127	PAINT, SPRAY	0			
02-60456-28	PROVIDE SCAFFOLD AND INSULATION SERVICES TO REPAIR DAMAGED AND MISSING INSULATION ON THE SOOTBLOWER DRAINS PIPING.	D	LAGGING, ALUMINUM, PREFORMED, 45 DEG ELBOW, 4" X 1-1/2", CHILDERS P/N 4X1-1/2, RPR P/N 8	0	474.87	3,365.09	3,839.96
		32102	LAGGING, ALUMINUM	0			
		45045	INSULATION, CALCIUM SILICATE	33			
		32179	INSULATION, CALCIUM SILICATE	2			

IP7_039449