SHOP SUPERVISOR REPORT

AT APPROX 2345 OCT 1 1990 THE SULPHURIC CIRCULATION PUMP BECAME DISCONNECTED FROM ITS PLUMBING ON THE DISCHARGE END. THE PUMP WAS SHUT OFF & THE TANK AREA WAS EVACUATED & THE DOORS CLOSED.

THE FIRE DEPARTMENT WAS CALLED & MY FIRST CONTACT WITH THE RESPONSE TEAM WAS JAMES VADEN, FACILITIES DUTY SUPERVISOR. HE ADVISED EVACUATION OF THE IMMEDIATE AREA AROUND COL WJ-7. (AT LEAST 50 FT). ALL EMPLOYEES WERE EVACUATED.

THE ~~HAZARD~~ EMERGENCY RESPONSE TEAM HAD NOT ENTERED THE AREA AT 0145 OCT 2.

THERE WERE NO INJURIES & NO APPARENT CHEMICAL REACTION.

THIS PUMP HAD BEEN INSTALLED AT APPROX. 2015 OCT 1, & A LEAK WAS DETECTED AT 2030. MAINTAINENCE RESPONDED & REPAIRED THE LEAK. THIS CONNECTION CAME LOOSE APPROX. 2 1/2

HOURS LATER & CAUSED NOTED INCIDENT.

NORRIS