

LEGEND

- Groundwater Monitoring Well
- Active Outfall
- Inactive Outfall
- Toe of Riprap
- Sheetpile Wall
- Concrete Panel Wall
- Fences
- Federal Navigation Channel
- Removal Action Boundary
- Property Boundaries
- Boeing DSOA
- Terminal 117 Early Action Area 5 Boundary

NOTES:

1. Bathymetry surveyed by Lower Duwamish Waterway Group (August 2003).

2. Outfall locations field identified on May 14, 2003.

3. The toe of the riprap slope, inactive 24-inch and 15-inch Boeing property line outfalls were surveyed during a low tide on August 28, 2008.

4. The Boeing-EMJ/Jorgensen cleanup boundaries is identified in the Memorandum of Understanding between Boeing and EMJ/Jorgensen Forge, dated August 2007 (EMJ et al. 2007).

Feet

0 80 160 240 320

Q:\Jobs\080224-01_Jorgensen\Maps\2012_10\Removal_Action_Boundary.mxd nkochie 10/18/2012 10:55:51 AM

ANCHOR QEA

Figure 1
Jorgensen Forge EAA Removal Action Boundary
Statement of Work