

Affected area in grass where release occurred

Vacuuming out pipe sections before disassembly (primary D-Box in background)

Blocked up section of pipe to prevent spillage