PEMACO REMEDIAL ACTION

SHAKEDOWN AND O&M PHASE

Photo Log Book Vol. 6

- EXPOSITION WELLHEAD
- T-101 MOISTURE SEPARATOR REPAIR
- AIR INTAKE SILENCERS
- FENCE INSTALLATION
- GEOFABRIC INSTALLATION
- CONDENSATE SUMP RETROFIT
- MISC. RETROFITS AND REPAIRS

T N & Associates, Inc.
Engineering and Science

317 E. Main Street
Ventura, California 93001
805-585-2110

August 2007

TABLE OF CONTENTS

Photo 01	Exposition Wellhead Detail 01	1
Photo 02	Exposition Wellhead Detail 02	1
Photo 03	Exposition Wellhead Detail 03	2
Photo 04	Exposition Wellhead Detail 04	2
Photo 05	T-101 Moisture Separator Repair 01	3
Photo 06	T-101 Moisture Separator Repair 02	3
Photo 07	T-101 Moisture Separator Repair 03	4
Photo 08	T-101 Moisture Separator Repair 04	4
Photo 09	T-101 Moisture Separator Repair 05	5
Photo 10	T-101 Moisture Separator Repair 06	5
Photo 11	T-101 Moisture Separator Repair 07	6
Photo 12	T-101 Moisture Separator Repair 08	6
Photo 13	V-112 Air Intake Silencer 01	7
Photo 14	V-112 Air Intake Silencer 02	7
Photo 15	V-319 Air Intake Silencer 01	8
Photo 16	V-319 Air Intake Silencer 02	8
Photo 17	Water Meter Repair 01	9
Photo 18	Water Meter Repair 02	9
Photo 19	Treatment Building Fence Installation 01	10
Photo 20	Treatment Building Fence Installation 02	10
Photo 21	Treatment Building Fence Installation 03	11
Photo 22	Treatment Building Fence Installation 04	11
Photo 23	Treatment Building Fence Installation 05	12
Photo 24	Treatment Building Fence Installation 06	12
Photo 25	Treatment Building Fence Installation 07	13
Photo 26	Treatment Building Fence Installation 08	13
Photo 27	Treatment Building Fence Installation 09	14
Photo 28	Treatment Building Fence Installation 10	14
Photo 29	Treatment Building Fence Installation 11	15
Photo 30	FTO Emission Source Test 01	15
Photo 31	FTO Emission Source Test 02	16
Photo 32	FTO Emission Source Test 03	16
Photo 33	Geofabric Installation 01	17
Photo 34	Geofabric Installation 02	17
Photo 35	Geofabric Installation 03	18
Photo 36	Geofabric Installation 04	18
Photo 37	Geofabric Installation 05	19
Photo 38	P-201 Cooling Tower Pump Retrofit	19
Photo 39	P-502 Secondary Containment Sump Pump Retrofit 01	20
Photo 40	P-502 Secondary Containment Sump Pump Retrofit 01	20
Photo 41	VT-201 Magnehelic Differential Pressure Gauge	21
Photo 42	Water Pressure Boost System	21
Photo 43	Condensate Sump Retrofit 01	22
Photo 44	Condensate Sump Retrofit 02	22
Photo 45	Condensate Sump Retrofit 03	23
Photo 46	Condensate Sump Retrofit 04	23
Photo 47	Condensate Sump Retrofit 05	24
Photo 48	Imported Soil Stockpile	24

TABLE OF CONTENTS (Cont'd)

Photo 49	GAC Change-out 01	25
Photo 50	GAC Change-out 02	25
Photo 51	T-403 and T-404 Carbon Vessel Repair 01	26
Photo 52	T-403 and T-404 Carbon Vessel Repair 02	26
Photo 53	T-403 and T-404 Carbon Vessel Repair 03	27
Photo 54	Clay in the GAC Vessel	27
Photo 55	Caustic Soda Solution Delivery 01	28
Photo 56	Caustic Soda Solution Delivery 02	28
Photo 57	Solar Panel Installation 01	29
Photo 58	Solar Panel Installation 02	29
Photo 59	Solar Panel Installation 03	30
Photo 60	Solar Panel Installation 04	30
Photo 61	Dekker Pump Oil Blow Remedy 01	31
Photo 62	Dekker Pump Oil Blow Remedy 02	31
Photo 63	Dekker Pump Oil Blow Remedy 03	32
Photo 64	Dekker Pump Oil Blow Remedy 04	32
Photo 65	ERH Cooling Tower Unit	33
Photo 66	ERH Condenser Unit	33
Photo 67	ERH PCU Unit	34
Photo 68	ERH System 01	34
Photo 69	ERH System 02	35
Photo 70	O&M and Sampling Activity	35
Photo 71	Flow Sensors	36
Photo 72	Punch List Acceptance Meeting 01	36
Photo 73	Punch List Acceptance Meeting 02	37
Photo 74	FTO Operation Training	37



Photo 01 – Exposition Wellhead Detail 01



Photo 02 – Exposition Wellhead Detail 02

Photo 03 – Exposition Wellhead Detail 03



Photo 04 – Exposition Wellhead Detail 04

Photo 05 – T-101 Moisture Separator Repair 01

Photo 06 – T-101 Moisture Separator Repair 02

Photo 07 – T-101 Moisture Separator Repair 03

Photo 08 – T-101 Moisture Separator Repair 04

Photo 09 – T-101 Moisture Separator Repair 05



Photo 10 – T-101 Moisture Separator Repair 06

Photo 11 – T-101 Moisture Separator Repair 07

Photo 12 – T-101 Moisture Separator Repair 08

Photo 13 – V-112 Air Intake Silencer 01

Photo 14 – V-112 Air Intake Silencer 02

Photo 15 – V-319 Air Intake Silencer 01

Photo 16 – V-319 Air Intake Silencer 02

Photo 17 – Water Meter Repair 01

Photo 18 – Water Meter Repair 02

Photo 19 – Treatment Building Fence Installation 01

Photo 20 – Treatment Building Fence Installation 02

Photo 21 – Treatment Building Fence Installation 03



Photo 22 – Treatment Building Fence Installation 04

Photo 23 – Treatment Building Fence Installation 05

Photo 24 – Treatment Building Fence Installation 06

Photo 25 – Treatment Building Fence Installation 07

Photo 26 – Treatment Building Fence Installation 08

Photo 27 – Treatment Building Fence Installation 09

Photo 28 – Treatment Building Fence Installation 10

Photo 29 – Treatment Building Fence Installation 11



Photo 30 – FTO Emission Source Test 01



Photo 31 – FTO Emission Source Test 02

Photo 32 – FTO Emission Source Test 03

Photo 33 – Geofabric Installation 01

Photo 34 – Geofabric Installation 02

Photo 35 – Geofabric Installation 03

Photo 36 – Geofabric Installation 04



Photo 37 – Geofabric Installation 05



Photo 38 – P-201 Cooling Tower Pump Retrofit

Photo 39 – P-502 Secondary Containment Sump Pump Retrofit 01



Photo 40 – P-502 Secondary Containment Sump Pump Retrofit 02



Photo 41 – VT-201 Magnehelic Differential Pressure Gauge

Photo 42 – Water Pressure Boost System

Photo 43 – Condensate Sump Retrofit 01

Photo 44 – Condensate Sump Retrofit 02



Photo 45 – Condensate Sump Retrofit 03

Photo 46 – Condensate Sump Retrofit 04



Photo 47 – Condensate Sump Retrofit 05

Photo 48 – Imported Soil Stockpile

Photo 49 – GAC Change-out 01

Photo 50 – GAC Change-out 02

Photo 51 – T-403 and T-404 Carbon Vessel Repair 01

Photo 52 – T-403 and T-404 Carbon Vessel Repair 02

Photo 53 – T-403 and T-404 Carbon Vessel Repair 03

Photo 54 – Clay in the GAC Vessel

Photo 55 – Caustic Soda Solution Delivery 01

Photo 56 – Caustic Soda Solution Delivery 02

Photo 57 – Solar Panel Installation 01

Photo 58 – Solar Panel Installation 02

Photo 59 – Solar Panel Installation 03

Photo 60 – Solar Panel Installation 04



Photo 61 – Dekker Pump Oil Blow Remedy 01



Photo 62 – Dekker Pump Oil Blow Remedy 02

Photo 63 – Dekker Pump Oil Blow Remedy 03



Photo 64 – Dekker Pump Oil Blow Remedy 04

Photo 65 – ERH Cooling Tower Unit

Photo 66 – ERH Condenser Unit

Photo 67 – ERH PCU Unit

Photo 68 – ERH System 01

Photo 69 – ERH System 02

Photo 70 – O&M and Sampling Activity

Photo 71 – Flow Sensors

Photo 72 – Punch List Acceptance Meeting 01

Photo 73 – Punch List Acceptance Meeting 02

Photo 74 – FTO Operation Training