



POINT TABLE

POINT	NORTHING	EASTING	ELEVATION	DESCRIPTION
1	6888051.87	11831030.59	108.72	INFO


TREES SHOULD BE CLEARED AS NECESSARY IN THIS AREA TO FACILITATE INSTALLATION OF A WATER TREATMENT SYSTEM
TREES SHOULD BE CLEARED AS NECESSARY IN THIS AREA TO FACILITATE MECHANICAL DIRECTING OF ASH. CONTRACTOR TO VERIFY THAT TREES TO BE FELLED ARE LOCATED WITHIN THE LIMITS OF ASH
TREES SHOULD BE CLEARED AS NECESSARY IN THIS AREA TO FACILITATE CONSTRUCTION OF A HAVEROAD.
TREES SHOULD BE CLEARED AS NECESSARY IN THIS AREA TO FACILITATE STOCKPILING OF ASH EXCAVATED FROM POND 1.
POINT TABLE
POINT | NORTHING | EASTING | ELEVATION | DESCRIPTION
1 | 0000001.67 | 1+05+020.50 | 156.77 | NAD