DAM INSPECTION CHECKLIST
POSSUM POINT POWER STATION
POND ABC

Dominion

INSPECTION DATE: FEB 17, 2016

WEATHER: 48, PARTLY CLOUDY

INSPECTED BY: K. ACREE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1307 -> SAND BAGS AND ~~RIPRAP~~ RIPRAP ARE IN PLACE AND THERE IS NO STANDING WATER AGAINST SAND BAGS
Erosion	N	N	IT APPEARS THAT THE SAND BAGS HAVE BEEN IMPACTED BY A PIECE OF EQUIPMENT, SEVERAL SAND BAGS ARE RIPPED.
Low Point, B dike*			
Flow	N	N	1317 -> NO STANDING WATER ON INSIDE OF SAND BAGS, THERE IS A SMALL POOL OF STANDING ON THE OUTSIDE OF THE SAND BAGS
Erosion	N	N	SAND BAGS ARE IN PLACE AND SEVERAL OF THE SAND BAGS ARE RIPPED
Outfall water surface El. (top of stoplogs to water)			1331 -> NO STANDING WATER AGAINST WEIR, NO FLOW GOING THROUGH WEIR, AND WEIR APPEARS TO BE DRY.

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): LOW POINT, C DIKE => NO ~~SAND~~ STANDING WATER AGAINST SAND BAGS, SAND BAGS ARE IN PLACE, AND SEVERAL SAND BAGS ARE RIPPED.

-> SOME WATER AT TOE OF POND A EMBANKMENT (TYPICAL OF PONDS B&C)

-> STANDING WATER AT TOP OF EMBANKMENT OF PONDS A, B AND C (SEE FIGURE BELOW, RED INDICATES STANDING WATER)