XOX09422595-043 9C PPW 12/1/2008

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

**UNIFORM HAZARDOUS WASTE MANIFEST**

1. Generator ID Number: KS0007246846
2. Page 1 of: 1
3. Emergency Response Phone: (800) 483-3718
4. Manifest Tracking Number: 008154590 FLE

5. Generator's Name and Mailing Address: LLC
2549 North New York Street
Wichita, KS 67219
(316) 269-7400

Generator's Site Address (if different than mailing address): SAME

Generator's Phone:

6. Transporter 1 Company Name: BASIN
U.S. EPA ID Number: OKR00023085

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: Clean Harbors Lone Mountain LLC
40355 S County Road 236
Waynoka, OK 73860
U.S. EPA ID Number: OKD065438376

Facility's Phone: (580) 697-3500

| 9a. HM | 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) | 10. Containers No. | 10. Containers Type | 11. Total Quantity | 12. Unit Wt./Vol. | 13. Waste Codes |
|---|---|---|---|---|---|---|
| x | 1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III | 1 | DT | EST 16 | Y | F001 F002 F003 F004 F005 |
| | 2. | | | | | |
| | 3. | | | | | |
| | 4. | | | | | |

14. Special Handling Instructions and Additional Information
1.CH831502X08 ERG#171

TR# 169 TL# ED35

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Jim Tyson
Signature: Jim Tyson
Month 12 Day 16 Year 14

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Ron Murphy
Signature: Ron Murphy
Month 12 Day 16 Year 14

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number

Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name
Signature
Month Day Year

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

Clean Harbors has the appropriate permits for and will accept the waste the generator is shipping.

GENERATOR'S INITIAL COPY

KOX09422595-043 SC PPW 12/1/2008

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

**UNIFORM HAZARDOUS WASTE MANIFEST**

1. Generator ID Number: KSD007246846
2. Page 1 of: 1
3. Emergency Response Phone: (800) 483-3718
4. Manifest Tracking Number: 008154590 FLE

5. Generator's Name and Mailing Address
Clean Harbors Kansas LLC
2549 North New York Street
Wichita, KS 67219
(316) 269-7400
Generator's Phone:

Generator's Site Address (if different than mailing address): SAME

6. Transporter 1 Company Name: BASIN
U.S. EPA ID Number: OKR000023085

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address
Clean Harbors Lone Mountain LLC
40355 S County Road 236
Wanoka, OK 73860
Facility's Phone: (580) 697-3500
U.S. EPA ID Number: OKD065438376

| 9a. HM | 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) | 10. Containers No. | 10. Containers Type | 11. Total Quantity | 12. Unit Wt./Vol. | 13. Waste Codes | | |
|---|---|---|---|---|---|---|---|---|
| X | 1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III | 1 | DT | Est 16 | Y | F001 F004 | F002 F005 | F003 |
| | 2. | | | | | | | |
| | 3. | | | | | | | |
| | 4. | | | | | | | |

14. Special Handling Instructions and Additional Information
1.CHS31502XOB ERG#171

TR# 169 TL# ED35

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Jim Tyson
Signature: Jim Tyson
Month 12 Day 16 Year 14

**INT'L**

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

**TRANSPORTER**

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Ron Murphy
Signature: Ron Murphy
Month 12 Day 16 Year 14
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

**DESIGNATED FACILITY**

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H132 2. 3. 4. 14 7034

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Cindy Bradford
Signature: Cindy Bradford
Month 12 Day 17 Year 14

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

**DESIGNATED FACILITY TO GENERATOR**

Clean Harbors has the appropriate permits for and will accept the waste the generator is shipping.