X0 X09422555 034 SC PPW 12/1/2008

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: KSD007246846
2. Page 1 of: 1
3. Emergency Response Phone: (800) 483-3718
4. Manifest Tracking Number: 008154713 FLE

5. Generator's Name and Mailing Address
Clean Harbors Kansas LLC
2649 North New York Street
Wichita, KS 67219
Generator's Phone: (316) 269-7400

Generator's Site Address (if different than mailing address): SAME

6. Transporter 1 Company Name: [illegible]
U.S. EPA ID Number: ID[illegible]

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address
Clean Harbors Lone Mountain LLC
40355 S County Road 236
Waurika, OK 73573
Facility's Phone: (580) 697-3500

U.S. EPA ID Number: OKD068438376

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	DT	16	Y	F001 F002 F003 F004 F005
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information
1. CH021502X0B ERG# 171 117 525

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: [illegible] Signature: [illegible] Month 2 Day 30 Year 14

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Kellgt Ben(V Signature: [illegible] Month 2 Day 30 Year 14
Transporter 2 Printed/Typed Name: Signature: Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name Signature Month Day Year

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

Clean Harbors has the appropriate permits for and will accept the waste the Generator is shipping.

GENERATOR'S INITIAL COPY

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) XO X09422595-034 SC PPW 12/1/2008

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: KSD007246846
2. Page 1 of: 1
3. Emergency Response Phone: (800) 483-3718
4. Manifest Tracking Number: 008154713 FLE

5. Generator's Name and Mailing Address
Clean Harbors Kansas LLC
2549 North New York Street
Wichita, KS 67219
Generator's Phone: (316) 269-7400

Generator's Site Address (if different than mailing address): SAME

6. Transporter 1 Company Name: Steve Forler
U.S. EPA ID Number: ~~ID~~ ~~205625~~ KKP000001263

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address
Clean Harbors Lone Mountain LLC
40355 S County Road 236
Wagoner, OK 73860
Facility's Phone: (800) 697-3500

U.S. EPA ID Number: OKD065438376

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
x	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	Dt	Est 16	Y	F001	F002	F003
						F004	F005	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1.CH831502XOB ERG#171
TRK#117 TRL#525

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Jim Tyson
Signature: [signature]
Month 12 Day 30 Year 14

GENERATOR

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Transporter signature (for exports only):
Port of entry/exit:
Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Kingt Bend
Signature: [signature]
Month 12 Day 30 Year 14

Transporter 2 Printed/Typed Name
Signature
Month 1 Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H132			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Patrick Sparkman
Signature: [signature]
Month 12 Day 30 Year 14

H 7335

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

Clean Harbors has the appropriate permits for and will accept the waste the Generator is shipping.

DESIGNATED FACILITY TO GENERATOR