State of Ohio, Department of Commerce
Division of State Fire Marshal—Bureau of Underground Storage Tank Regulations
8895 East Main Street, Reynoldsburg, Ohio 43068
Phone (614) 752-7938 Fax (614) 752-7942

EPA Region 5 Records Ctr.
331255

BUSTR Compliance Inspection Report

Owner #: W023763	Facility #: 31010671
Owner Name: Reuben W Peppers	Facility Name: Writesel & Sons Recycl.
Address: 9360 Stoneridge Dr.	Address: 4510 W Mitchell Ave
City/State/Zip: Cincinnati OH 45237	City/State/Zip: Cincinnati OH 45232
Owner Contact: Reuben W Peppers	Facility Representative: Rob Writesel
Phone Number: 513-615-6701	Phone Number: 513-259-1573
Inspection Type: ☐ New Inspection ☐ Re-Inspection ☒ Referral/Complaint	Inspection Result: ☐ In Compliance on This Date ☐ Re-Inspection Needed ☒ New Violation(s) Found
	Latitude: 39.16968°
	Longitude: (-) 84.51417°

Directions: To the right of each underground storage tank (UST) component, write the name of the component based upon your observations. If a component with an asterisk (*) is not present, but is required to be present, then thoroughly document your observations on a supplemental report.

	# 1	# 2	# 3	# 4	# 5	6
(1a) UST Identification						
(1b) UST Capacity	Unknown	Unknown	Unknown	Unknown	Unknown	Un
(1c) UST Contents	Waste oil	Waste oil	Waste oil	Waste oil	Waste oil	W
(2) UST Configuration (SW or SC)	SW	SW	SW	SW	SW	SW
(3) UST Construction	Bm	Bm	Bm	Bm	Bm	Bm
(4) UST Corrosion Protection Equipment*	NP	NP	NP	NP	NP	NP
(5) UST Release Detection Equipment*	NP	NP	NP	NP	NP	NP
(6) Piping Configuration (SW or SC)	SC	SC	SC	SC	SC	SC
(7) Piping Style (P or S or G)	G	G	G	G	G	G
(8) Piping Construction	Bm	Bm	Bm	Bm	Bm	Bm
(9) Piping Corrosion Protection Equipment*	NP	NP	NP	NP	NP	NP
(10) Piping Release Detection Equipment*	NP	NP	NP	NP	NP	NP
(12) Spill Containment Equipment (Spill Bucket)*	NP	NP	NP	NP	NP	NP
(13) Other Containment Equipment (UST / Dispenser)	NR	NR	NR	NR	NR	NR
(14) Containment Release Detection Equipment	NR	NR	NR	NR	NR	NR
(15) Overfill Prevention Equipment*	NP	NR	NR	NR	NR	NR

Directions: To the right of each operational compliance item, write the appropriate compliance indicator based upon your observations. Thoroughly document all non-compliant observations on a supplemental report. (C = compliant, NC = non-compliant, NA = not applicable, U = undetermined)

(16) BUSTR Registration	NC	NC	NC	NC	NC	NC
(17) PUSTRCB Certificate	NC	NC	NC	NC	NC	NC
(18) Financial Responsibility	NC	NC	NC	NC	NC	NC
(19) Permit Related Requirements	NC	NC	NC	NC	NC	NC
(20) Out-of-Service Requirements	NC	NC	NC	NC	NC	NC
(21) Records and Release Reporting Requirements	NR	NR	NR	NR	NR	NR
(22) Spill and Overfill Operation	NR	NR	NR	NR	NR	NR
(23) UST/Piping Release Detection Operation	NR	NR	NR	NR	NR	NR
(24) UST/Piping Corrosion Protection Operation	NR	NR	NR	NR	NR	NR
(25) Other Containment Operation (UST / Dispenser)	NR	NR	NR	NR	NR	NR
(26) Containment Release Detection Operation	NR	NR	NR	NR	NR	NR
(27) Other UST/Piping/Ancillary Equipment Operation	NR	NR	NR	NR	NR	NR

Inspector: [signature]	Date: 6/4/07	Time on Site: 1.0

Ohio Department of Commerce, Division of State Fire Marshal
Bureau of Underground Storage Tank Regulations
P.O. Box 687, Reynoldsburg, Ohio. 43068-9009
Phone (614) 752-7938 Fax (614) 752-7942

SUPPLEMENTAL REPORT

Facility Number: 3101067

Facility Name: Writesel & Sons Recycling

Facility Address: 4510 W Mitchell Ave, Cincinnati OH 45232

BUSTR Staff Personnel: Jason Gabany **Date:** 6/4/07

I observed 6 vent lines and 3 fill ports waste oil in 3 of the tanks I was unable to verify contents of tanks 4, 5 & 6. Cincinnati FD Assistant Chief Duane Herth called in complaint to me while I was in Cincinnati. UST's discovered inside building after building burned. UST's still accessible & waste oil was 5-6 ft. deep in tank #1. Facility is currently salvage/recycling business

NOV issued for out of service greater than 12-months, No registration & No PUSTRCF Insurance Certificate.

Tanks have not been used since 1989.

Ohio Department of Commerce, Division of State Fire Marshal
Bureau of Underground Storage Tank Regulations
P.O. Box 687, Reynoldsburg, Ohio, 43068-9009
Phone (614) 752-7938 Fax (614) 752-7942

Notice of Underground Storage Tank Facility Violation

Owner Number: W023763	Facility Number: 310071
Owner/Operator Name: Reuben W Peppers	Facility Name: Wetzel & Sons Recycling
Address: 9860 Skyridge Dr.	Address: 4510 W Mitchell Ave
City/State/Postal Code: Cincinnati OH 45258	City/State/Postal Code: Cincinnati OH 45237
Contact Number: 513-615-6701	Contact Number: 513-259-1513

IMPORTANT: An inspection of the above listed facility indicates that this facility is operating in non-compliance with the applicable sections of the Ohio Administrative Code (OAC). It is the responsibility of owners and operators to submit documentation to the State Fire Marshal's Bureau of Underground Storage Tank Regulations (SFM/BUSTR) office demonstrating correction of violations. Failure to correct violations may result in fines up to the amount of $10,000 per day for each violation that continues. Violation(s) of the OAC are as checked below.

WHAT YOU NEED TO DO: Owners and operators shall correct all violations no later than sixty (60) days after the Date of Inspection and submit documentation to the address listed at the top of this form demonstrating that all violations have been corrected. Do not wait for the inspector to perform a re-inspection. SFM/BUSTR may, at any time, pursue enforcement of any violation. Failure to submit documentation to the BUSTR office by the prescribed date may result in escalation of enforcement. **Please mail or fax documentation to the BUSTR office demonstrating correction of each violation. In addition, please include the pink copy of this form when submitting information to the BUSTR office.**

1) ☒...Code 1301: 7-9-04(B)(1). **Failure to submit annual registration application.** Method of correction: Submit a registration application and all fees that are past due to the Testing and Registration Bureau (877-264-0023) and submit a copy of the registration certificate to BUSTR.

2) ☒...Code 1301: 7-9-05(G)(1). **Failure to demonstrate a valid certificate of coverage from PUSTRCB.** Method of correction: Obtain a certificate of coverage from PUSTRCB (800-224-4659) and submit a copy of the certificate to BUSTR.

3) ☐...Code 1301:7-9-08(C)(2)(a). **Failure to test cathodic protection system as required.** Method of correction: Contact a Certified UST Installer and immediately perform the work necessary to correct the pending violation. Submit test results and/or copies of invoices to BUSTR.

4) ☐...Code 1301:7-9-08(F)(2). **Inadequate operation or maintenance of a monthly method of leak detection.** Method of correction: Contact a Certified UST Installer and immediately perform the work necessary to correct the pending violation. Submit test results and/or copies of invoices to BUSTR.

5) ☐...Code 1301:7-9-08(F)(4)(a). **Failure to annually test automatic line leak detectors.** Method of correction: Contact a Certified UST Installer and immediately perform the work necessary to correct the pending violation. Submit test results and/or copies of invoices to BUSTR.

6) ☐...Code 1301:7-9-08(F)(4)(b). **Failure to perform periodic tightness test of pressure piping.** Method of correction: Contact a Certified UST Installer and immediately perform the work necessary to correct the pending violation. Submit test results and/or copies of invoices to BUSTR.

7) ☒...Code 1301:7-9-12(E)(4) or (5). **Failure to properly manage an UST system that has been out of service for more than twelve months.** Method of correction: Perform a tightness test and place the UST system back into service or remove the UST system. Submit test results and/or copies of invoices to BUSTR.

8) ☐...OTHER: Code 1301:7-9-_____

I personally observed the violation(s) as noted above, all pursuant to authority under RC §§ 3737.88 and 3737.882.

☐ I provided the recipient with a copy of this Notice of UST Facility Violation

☐ I mailed a copy of this Notice of UST Facility Violation to the owner address as listed above

BUSTR Inspector: [signature] Date of Inspection: 6/4/07

NEED HELP? Go to the BUSTR web page at http://www.com.state.oh.us/sfm/bu.stl. Click on the Release Prevention link and search for a Certified UST Installer or a Certified UST Inspector in your area. These individuals can check your system or put you in contact with contractors who can perform the tests needed to demonstrate compliance.

Without admission of any violation of any law or administrative regulation governing underground storage tanks or liability for same, I acknowledge by my signature receipt of this "Notice of UST Facility Violation" and the accompanying copy of the information package.

Recipient's Name (print): _____ Title: _____

Recipient's Signature: _____ Date: _____