EPA Region 5 Records Ctr.
351341



D+J



XXX

66.40

PARK
OPEN
FROM
8:00A.M.-9:30P.M.

TRANSPORT MOTOR EXPRESS, INC.
9
TRANSPORT MOTOR EXPRESS, INC.
10


SEIWERT
TRUCK LEASING CO.
CHICAGO, ILL.
SE 8-2700
40AT
1737
22.
HAZARDOUS
MATERIAL

1684

RAIL-ROADER
MOBILE STORAGE
25315
25
CAUTION
13' HIGH

Super Products

EY 40 39

SUMMIT PARK
SUMMIT PARK DISTRICT

THEURER

DANGER
HAZARDOUS
MATERIAL
12
L

photo #1
Set #1

Inspection 9/26/83

Area in front of building #107
Note standing water and pile of soil contaminated with the bluish chips as mentioned in the trip report dated Oct. 3, 1983.

Dan Hopkins

photo #2
Set #1

Inspection 9/26/83

Corner of building #107 (left center) and hallway to next building

D. Hopkins

photo #3
Set #1

Inspection 9/26/83

Building #107. In foreground is a pile of contaminated soil on a plastic sheet.

D. Hopkins

photo #5
Set #1

Inspection 9/26/83

Wengrow standing next to pile of contaminated soil

D. Hopkins

photo #7
Set #1

Inspection 9/26/83

Storage area near wall - Building #107
(Taken w/flash)

D. Hopkins

photo #9
Set #1

Inspection 9/26/83

Hallway from storage area in building #107
This is the same hallway seen (from the opposite direction) in photo #10.
(Taken w/flash)

D. Hopkins

photo #10
Set #1

Inspection 9/26/83

Storage area and entrance to hallway in building #107.
(Taken w/ flash)

D. Hopkins

photo #12
Set #1

Inspection 9/26/83

Essentially same photograph as #11

D. Hopkins

photo #15 Set #1 Inspection 9/26/83

Chips in storage area in building #115 (Taken w/ flash)

D. Hopkins

photo #16 Set #1 Inspection 9/26/83

Essentially same photo as #15

D. Hopkins

photo #17 Set #1 Inspection 9/26/83

Storage area - building #115.

D. Hopkins

photo #18 Set #1 Inspection 9/26/83

Continuation of view from photo #17 (Taken w/ flash) D. Hopkins

photo #19 Set #1 Inspection 9/26/83

This print shows half of two different snapshots. Building #115

D. Hopkins

photo #20 Set #1 Inspection 9/26/83

Cyanide contaminated chips in storage area in building #115 (Taken w/ flash)

D. Hopkins

Photo #22 Set #1 Inspection 9/26/83

Hallway (right center of photo) connected to building #115

D. Hopkins

photo 1
Set 2

12-7-83
inspection
Dixon I/
Green River
Industrial Park

Hallway from
building #107
note snow on chippile
near end of hall

Dan
Hopkins

photo 2
Set 2

12-7-83

Hallway / building
#107

photo # 3
Set 2

12-7-83

Main storage area
and hallway / building #107

photo 4
Set 2

12-7-83

Main Storage area
building #107

photo 5
Set 2

12-7-83

Building #107
Entrance to main
Storage area

photo 6
Set 2

12-7-83

Building 107
entrance door open

photo 7
Set 2

12-7-83

Building 107
ice covered water has
filled loading ramp

photo #8
Set 2

12-7-83

Building #115
ends of concrete walls
indicate bays (20' wide x
50' deep)

photo 9
Set 2
12-7-83

Building 115
large storage area & hallway
(background) bay (foreground)

photo 10
Set 2
12-7-83

Building 115

photo 11
Set 2
12-7-83

Hallway of building #115

photo 12
Set 2
12-7-83

large storage
area building 115

photo 13
Set 2
12-7-83

large storage area
building #115 (continuation
of view from photo 12)

photo 14
Set 2
12-7-83

large storage area
building #115 (cont. from
photo 13)

photo 15
Set #2
12-7-83

Building 115

photo 16
Set 2
12-7-83

Building 115
glare on upper
left corner

photo #16
Set 2

12-7-83

Building 115 adjoining hallway. Entrance to building can be made through hole in hallway wall (just right of figure)

photo #17
Set #2

12-7-83

Building 115
continuation of photo
#16

photo #18
Set # 2

12-7-83

Building 115
cont. of view from
photo #17

photo #19
Set #2

12-7-83
inspection

View of building #115. Hallway from building #115 has chips stored in it to the bricked wall closing off hallway. The brick wall can be seen about midway up the hallway and just left of the telephone pole.

photo 5
Set 1

12-7-83

Building 107
Entrance to main
Storage area

photo 7
Set 1

12-7-83

Building 107
ice covered water
has filled loading ramp

photo 16
Set 1

12-7-83

Building 115
glare on upper
left corner

photo 18
Set #1

12-7-83

Building 115
Cont. of view from
photo #17