SW Jefferson County Mining Remedial 4/8/16

0708 STM Jackson at Hillsboro field office Homeowner letters

0755 STM Hally on site, check work email.

0800 STM Barbeau getting car maintanence.

0850 STM Barbeau at Hillsboro field office.

0920 Leaving Field office to Sample. Shane & Lauren

0917 Drop Letters at Post office

0941 arrive at 612 N 2nd street (2698) to Sample
Collected: C1-C3, DZ, DW, LS1-LS2

1005 at 2701 (412 Am St) Collect C1-C4, DZ, PA, DW

1028 at 2705 (107 williamsburg Dr) Collect C1-C3, DZ, LS

1049 at 2651 (902 Mississippi Ave) Collect C1-C4, DZ, DW, LS1 LS4,
~~at 2591 (305 Lindsay Ave). Collect C1-C~~

1120 at 305 Lindsay Ave (2591) to Sample Collected:
C1-C4, LS, DZ, DW, RK, G

1200 Return to field office. Draw properties.

1155 Prudent Hinds Clears 2245 (511 Rollins)

1350 Email updated field sheet for 1951 (4428 Horseshoe)
Emailed updated field sheet for 128 (7611 Old State Rd H) at 0856.

1420 Calibrate XRF 1934 with RCRA 500 488±37, blank 8.8, and 2700 standard 2693±84

	1192 LS1		1192 LS2		1192 LS3		1192 LS4		1192 LS5
~~S18~~									
S15	15±8	S19	41±11	S23	24±10	S27	26±10	S31	40±11
S16	33±10	S20	49±12	S24	41±11	S28	28±10	S32	51±12
S17	17±9	S21	34±10	S25	42±11	S29	18±9	S33	28±10
S18	22±9	S22	41±11	S26	36±11	S30	24±10	S34	40±11

	1192 LS6		
S35	26±10	S37	21±9
S36	37±11	S38	28±10

30303621

SW Jefferson County Mining Remedial 4/8/16

	2765 C1		2765 C2		2765 C3		2765 C4
539	141 ± 17	543	110 ± 15	547	94 ± 15	551	45 ± 11
540	154 ± 18	544	122 ± 16	548	93 ± 15	552	57 ± 12
541	150 ± 18	545	112 ± 16	549	88 ± 14	553	61 ± 13
542	148 ± 18	546	115 ± 16	550	92 ± 15	554	54 ± 12

	2765 DZ		2765 G		2765 LS1		2765 LS2
555	1526 ± 56	559	36 ± 10	563	132 ± 17	567	235 ± 22
556	1599 ± 59	560	39 ± 11	564	118 ± 16	568	161 ± 19
557	1728 ± 59	561	39 ± 11	565	120 ± 16	569	164 ± 18
558	1617 ± 58	562	38 ± 10	566	123 ± 16	570	187 ± 20

	2765 LS3		2765 LS4		2765 LS5
571	96 ± 15	575	1614 ± 58	579	44 ± 11
572	102 ± 15	576	1584 ± 58	580	66 ± 13
573	115 ± 16	577	1794 ± 60	581	37 ± 10
574	104 ± 15	578	1664 ± 59	582	49 ± 11

Calibrate XRF 1934 with RCRA 500 Standard 466 ± 36
blank 8.0 2700 Standard 2700 ± 85
1540 STM Jackson off site for Walmart for supplies
then end day.

4/8/16