SDMS DOCID # 1154865

| RECORD OF COMMUNICATION | ☐ Phone Call ☐ Discussion ☐ Field Trip ☐ Conference ☒ Other (specify) Clarifier Inspection |
|---|---|
| TO: ~~DAB~~ 7/26, File | FROM: MPS | DATE: 7/18/89 |
| SUBJECT: City of L.A. Bureau of Fleet Services North Hollywood Facility Clarifier Inspection | FILE NO: AB104.0761 |

SUMMARY OF COMMUNICATION:

On 7/18/89, the facility's IWL was inspected. No cracks or holes were observed in any of the compartments walls. Only two of the compartments had a part of their bottom visible due to the thickness + "gummy" nature of the sludge at the bottoms (w/c could be tar). The walls looked quite intact nevertheless.

The facility did not have the clarifier wastewater/sludge analysis at the time of inspection. Mr. Wilbur Green & Mr. Jim Bonnville of City of L.A., who were present during the clarifier inspection, were requested to submit the clarifier sludge profile with their subs. inv. workplan. Photos taken.

The wastewater being pumped out had heavy oil & grease in it. Mr. Bonnville said he already has the subs. inv. workplan but he's still waiting

CONCLUSIONS, ACTION TAKEN OR REQUIRED:

for an "ok" to submit it to us.

INFORMATION COPIES TO: