Paul W. Jackson
& Associates
3604 Beach Drive S.W.
Seattle, WA 98116-2739

Your project partner!

BATCH ID
2407249.00

Sampling Data Sheet
for
Asbestos, Lead, Mold & Other

L A B S

(Please Type or Print)
Client Name: Paul W Jackson + Associates
Job Location: Rainier Brewery
Total Samples: 4

Project#: 050504
NVL Batch #:

Results Needed By: 5 Days

		Company	Date
Sampled by: Paul Jackson		PW Jackson + Associates	5/24/04
Relinquished by: Paul Jackson			
Received by:			
Analyzed by:			
Reviewed by:			

Sample ID: 524-254 HW
Sample Type: B
Protection: Half Mask
Decon:
Environment: Smokey
Pump #: 2
Date: 5/24/04

Location: Hall way Bldg 25 East Side
Activities: Torch Cutting Steel
Worker: Richard Pute
Time: Start 10:20 Rate: Start 2
End ___ End ___
Minutes= ___ Average= ___
Liters ___ Fibers /fields ___ LOD ___ Fibers /cc ___
Pump Quit Time Unbeter
No Sample Submitted

Sample ID: 524-25-CA1
Sample Type: A
Protection:
Decon:
Environment: Smokey
Pump #: 1
Date: 5/24/04

Location: Tank Side East - South
Activities: Plasma Cutting Steel
Worker:
Time: Start 10:40 Rate: Start 2.5
End 16:16 End 3
Minutes=336 Average=2.75
Liters 924 Fibers /fields ___ LOD ___ Fibers /cc ___

Sample ID: 524-25-CA2
Sample Type: B
Protection: Type 'C'
Decon:
Environment: Smokey
Pump #: 3
Date: 5/24/04

Location: Tank Side East - Center
Activities: Torch Cutting Steel
Worker: Robert A. Smith
Time: Start 10:41 Rate: Start 2
End 16:20 End 2.5
Minutes=339 Average=2.25
Liters 927 Fibers /fields ___ LOD ___ Fibers /cc ___

Sample ID: 524-25-CA3
Sample Type: A
Protection:
Decon:
Environment: Smokey
Pump #: 4
Date: 5/24/04

Location: Tankside East Center
Activities: Torch Cutting Steel
Worker:
Time: Start 10:50 Rate: Start 2.5
End 16:27 End 3
Minutes=337 Average=2.75
Liters 927 Fibers /fields ___ LOD ___ Fibers /cc ___

SAMPLE TYPES

P Pre abatement	X Aggressive clearance	RESP. PROT	
A Area	FB Field blank	PA Pressure dem. air	
I Inside reg. area	TB Trip blank	CA Continuous flow air	
O Outside reg. area	B Breathing zone (TWA)	PAPR	
H HEPA exhaust	C Ceiling (STEL)	F Full face mask APR	
Cl. Clearance		M Half face mask APR	

CONTROLS

DECON.	ENVIRONMENT
D,S Decon. w/ shower	H HEPA vac.
D Decon. w/o shower	N Negative air
	G Glovebag
	O Outside

Page ___ OF ___
Form#: 7000-3