REF. DWG NO. 500-0007

DAILY LOG

DAY	DATE	TIME	CAUSTIC LEVEL	FLOC LEVEL	pH READING PROCESS MONITOR	pH READING OUTPUT MONITOR	pH PAPER PROCESS MONITOR	pH PAPER OUTPUT MONITOR	FLOWMETER	CYCLES	TEMP °F LARGE TANK	TEMP °F SMALL TANK	COMMENTS, PROBLEMS, & REMARKS
MONDAY	7/4	7:00	12	4	9.6	9.44	—	9	3535	44			Holiday
		3:00											
		11:30											
TUESDAY	7/5	7:00	12	4	9.6	9.44	—	9	3535	44	120	120°	5:00 Stand
		3:00	12	4	11.6	9.68	—	—	5535	11	120	120°	Forgot to Reset PAC Press Cleaned & Emptied
		11:30	10	3	9.0	10.49	~~9.0~~	~~10.49~~	7178	26	120°	125°	
WEDNESDAY	7/6	7:00	10	3	8.9	11.26	—	—	7584 / 3985	31	120°	120°	5:00 Stand
		3:00	9	1	11.3	11.11	—	—	1773	19	110°	120°	
		11:30	8	1	8.5	10.3	—	—	2463	29	110°	110°	
THURSDAY	7/7	7:00	8	1	9.5	10.16	—	—	2526	41	100°	105°	5:00 Stand Emptied Pre-Press Added Floc
		3:00	7	15	8.5	10.06	—	—	1111	11	115	115	
		11:30	5	12	9.8	10.75	—	—	2405	33	120°	120°	
FRIDAY	7/8	7:00	5	12	10.2	11.80	—	—	2651	38	120°	120°	
		3:00	5	11	8.3	11.54	—	—	758	3	115°	120°	
		11:30	5	?	7.6	11.14	—	—	1442	10	120	120	Please instruct Dan O'Hanlin
SATURDAY	7/9		5	10	11.0	10.90	—	—	2921	14	115°	120°	
			4	10	10.2	11.00	—	—	725	5	120°	120°	
			4	10	10.4	11.75				5	120	125	
SUNDAY													

AKC-0013186

REF. DWG NO. 500

DAILY LOG

DAY	DATE	TIME	CAUSTIC LEVEL	FLOC LEVEL	pH READING PROCESS MONITOR	pH READING OUTPUT MONITOR	pH PAPER PROCESS MONITOR	pH PAPER OUTPUT MONITOR	FLOWMETER	CYCLES	TEMP °F LARGE TANK	TEMP °F SMALL TANK	COMMENTS, PROBLEMS, & REMARKS
MONDAY	7/11	7:00	4	9	10.3	11.45	—	—	1208	5	120°	120°	500 Start
		3:00	4	9	9.0	11.22	-	-	1659	5	120°	120°	
		11:30											
TUESDAY	7/12	7:00	4	8	9.4	10.59	—	—	2745	23	120°	120	500 START
		~~3:00~~ 7 PM	3	~~12.8~~	12.1	10.87	—	-	?	16	120	120	
		11:30	2	~~12.3~~	11.1	10.75	-	-	~~[illegible]~~	20	120	120	
WEDNESDAY	7/13	7:00	2	5	8.0	10.63	—	-	3287	28	120	120	500 Start forgot to Reset flow
		3:00	33		9.0	10.61	-	-		16	120	120	
		11:30	33	5	9.0	10.52	-	-	6084	24	120	125	
THURSDAY	7/14	7:00	33	5	7.6	10.44	—	10	~~[illegible]~~ 6266	29	120°	120°	500 Start 9 6 6 3 2 9 7 2939
		3:00	32	5	9	10.28	—	—	1164	?30	120	120	
		11:30	3.2	5	7.6	10.12	—	-	1236	11	120	120	
FRIDAY	7/15	7:00	31	4	7.7	9.70	—	10	2100	19	120°	120°	500 Start PAC Press Emptied
		3:00	30	4	7.6	9.44	—	—	1472	9	120°	120°	
		11:30	30	0	8.4	9.40			2911	13	120	12	
SATURDAY													
SUNDAY													

AKC-0013187

REF. DWG NO. 500-0007

DAILY LOG

DAY	DATE	TIME	CAUSTIC LEVEL	FLOC LEVEL	pH READING PROCESS MONITOR	pH READING OUTPUT MONITOR	pH PAPER PROCESS MONITOR	pH PAPER OUTPUT MONITOR	FLOWMETER	CYCLES	TEMP °F LARGE TANK	TEMP °F SMALL TANK	COMMENTS, PROBLEMS, & REMARKS
MONDAY	7/18	7:00	30	2	11.8	8.75	—	9	2971	18	120°	120°	500 Stand Cleaned Sumps Add floc
		3:00	30	2	10.2	12.25	—	—	1974	15	120°	120°	
		11:30											
TUESDAY	7/19	7:00	26	15	11.3	11.65	—	11	3371	34	120°	120°	Forgot to Reset Flow meter
		3:00	26	15	12.3	11.50	—	—	4436	40	120°	120°	
		11:30	24	12	10.5	11.93	—	12	4440	69	105	110	out put Pump is not working Right
WEDNESDAY	7/20	7:00	24	12	9.3	12.25	—	12	3068	69	105°	100°	
		3:00	2.2	11	7.5	10.90	—	—	13 35	12	120	120	
		11:30	2.2	10	10.9	10.16	—	—	2129	21	120	120	
THURSDAY	7/21	7:00	22	10	10.5	10.18	—	—	2258	23	120	120	
		3:00	21	9	11.1	10.58	—	—	1510	12	120°	120°	
		11:30	20	9	11.7	11.5	—	—	2259	27	120	120	
FRIDAY	7/22	7:00	20	8	9.0	10.72	—	11	2378	29	115°	115°	
		3:00	19	7	11.8	10.54	—	—	2353	10	120°	120°	
		11:30	18	7	11	10.92				29	120°	120°	
SATURDAY													
SUNDAY													

AKC-0013188

REF. DWG NO. 500-0007

DAILY LOG

DAY	DATE	TIME	CAUSTIC LEVEL	FLOC LEVEL	pH READING PROCESS MONITOR	pH READING OUTPUT MONITOR	pH PAPER PROCESS MONITOR	pH PAPER OUTPUT MONITOR	FLOWMETER	CYCLES	TEMP °F LARGE TANK	TEMP °F SMALL TANK	COMMENTS, PROBLEMS, & REMARKS
MONDAY	7/25	7:00	17	7	11.2	10.01	—	—	3307	33	100°	100°	Slow Paddle Stuck 5:00 Start
		3:00	16	5	11.3	11.22	—	—	4025	45	110°	110°	
		11:30	15	4	9.0	10.77	—	—	4286	68	120	120	
TUESDAY	7/26	7:00	15	4	8.2	10.37	—	—	5677 / 2370	74	120°	120°	Sl 5677 / 3307 / 2370 5:00 Start
		3:00	13	4	11.6	11.19	—	—	336	8	120°	120°	
		11:30	12	2	9.9	9.80			334	29	120	120	Flow meter
WEDNESDAY	7/27	7:00	12	2	12.1	9.97	—	—	3265	35	120°	120°	5:00 Start Add Floc
		3:00											
		11:30	09	12	11.9	10.75		11	0	39	120°	125°	
THURSDAY	7/28	7:00	8	11	8.4	11.57	—	11	3075	44	120°	125°	5:00 Start Flowmeter
		3:00	7	11	11.2	11.00	—	11	—	15	120°	125°	
		11:30	5	9	10.1	11.80	—	11	—	39	120°	125°	
FRIDAY	7/29	7:00	5	9	11.6	11.88	—	12	3280	44	120°	120°	5:00 Start flow meter fix PAC Press Emptied
		3:00	4	9	7.7	11.07	—	—	755	16	120°	120°	
		11:30	2	7	11.8	9.20	—	11	1982	39	120°	120°	
SATURDAY	7/30	5:00	2	5	12.4	9.22	—	9	1982	43	120°	120°	5:00 Start Add Caustic
		11	33	5	11.7	10.85	—	—	692	9	120°	120°	
		9:30	33	5	10.3	11.59	—	11	1436	18	120°	135°	
SUNDAY													

AKC-0013189