4/4 Meeting @ MacDermid - Waterbury
Huntington Ave

Gregg S.
Joe W.
Maryanne T
Rich N.
Rick McFee

107 - plugged ~ 6' depth

104 may be able to save - silted in (cap was missing)

10 add wells w/out > above
101 - up gradient - bedrock

RCRA RECORDS CENTER
FACILITY MACDermid
ID. NO. CTD001164599
FILE LOC. R-13
OTHER RDMS # 100765

RDMS DocID 00100765

HRP - modified low flow sampling
want to discuss

Sediment mgt plan - 1998 -
Gen same material / same places used as

Ball bearings - used 111TCA

* Get ?'s / comments to Rick - by Friday / Monday

MacDermid will review

Rick will prepare CMAP in letter format

~ 2-3 weeks to get report out

- req. that they try to get depth of well - MAC1/MW110

Rick will ✓ in summary tables
& finger printing analysis - units
& get me copy of Sediment Mgt. Plan
already req. map w/ property boundary

rusted drums ~ 100 - further —
from AOC A

MW111 & MW112 - recessed into ground
repairable
implications soil infiltration

Cathy Brass cap
Ca, Zn prominent in area