Form 4 1990

GENERATOR ANNUAL DANGEROUS WASTE REPORT

1990 Form 4

PLEASE PRINT OR TYPE — Blue or Black Ink Only — (Form designed for use on Elite (12 pitch) typewriter) Use spacebar between each character

SDMS Document ID
1012014

PLACE THE LABEL HERE

You must complete Sections 1 through 4 in addition to placing the label here.
Do not cross out incorrect information.

1. EPA/STATE HAZARDOUS WASTE SITE IDENTIFICATION NUMBER: WAD980738033

2. COMPANY NAME: WEYERHAEUSER TECHNOLOGY CENTER

3. SITE CONTACT PERSON, AND TITLE: CUSTER (LAST) RICHARD (FIRST) ENVIR. COORD. (TITLE)
PHONE NUMBER: 206-924-6187 ext. ----

4. COMPANY MAILING ADDRESS: 32901 WEYERHAEUSER WAY SOUTH
FEDERAL WAY WA 98003
CITY: FEDERAL WAY STATE: WA ZIP: 98003-

5. SITE LOCATION ADDRESS: 32901 WEYERHAEUSER WAY SOUTH
CITY: FEDERAL WAY STATE: WA ZIP: 98003-

6. SITE LOCATION COUNTY: KING

7. WASHINGTON DEPT. OF REVENUE REGISTRATION (UBI) NUMBER: 278-012-337

8. STANDARD INDUSTRIAL CLASSIFICATION (SIC) CODES: PRIMARY 7391 SECONDARY OTHER

9. SITE EMPLOYMENT ON DECEMBER 31, 1990: 1000

FOR ECOLOGY USE ONLY
DATE RECEIVED
Init. _____ Date _____
Init. _____ Date _____
Revision ☐ Pages _____
Init. _____ Date _____
Keypunched ☐
Init. _____ Date _____
Verified _____ Date _____
Batch No. _____
☐A ☐B ☐C
FOR ECOLOGY USE ONLY

SEND TO:

DEPT. OF ECOLOGY
Hazardous Waste Section
Attn: Annual Reports
R/6 No. 4
Mail Stop PV-11
Olympia, WA 98504-8711

Assistance 1-800-874-2022
(206) 459-6387

DUE DATE:
Postmarked
No Later Than
MARCH 1, 1991

WASHINGTON STATE DEPARTMENT OF ECOLOGY

10. REGULATORY STATUS CERTIFICATION—Refer to the instructions and/or the "Guide For Hazardous Waste Generators" to complete this section. Mark only one entry by placing your initials in the space provided. If none of these conditions apply to you, skip this section and complete the continuation sheet(s).
A. ____ B. ____ C. ____ D. ____ E. ____ lbs. F. ____

11. CERTIFICATION—I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

RICHARD W. CUSTER — PRINT OR TYPE NAME
Richard W. Custer — SIGNATURE (must be in ink)
FEBRUARY 27, 1991 — DATE SIGNED

ECY 28 (10/90) 1518 ecl28

Form 1 1990 GENERATOR ANNUAL DANGEROUS WASTE REPORT 1990 Form 4

12. YOUR EPA/STATE I.D. NUMBER: WAD980738033

13. RECEIVING FACILITY (TSD)
EPA/STATE I.D. NUMBER: TXD007349327
NAME: Texas Industries, Inc.
ADDRESS: 245 Ward Road
City: Midlothian, State TX ZIP: 76065

14. TRANSPORTER
EPA/STATE I.D. NUMBER: WAD988471629
NAME: Chemical Handling Corporation
ADDRESS: 11811 Upham Street
City: Broomfield, State CO ZIP: 80020

15. WASTE IDENTIFICATION

LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)	H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. WEIGHT O=Pounds P=Tons	K. For TSD Facility Use Only
1	20011	03 13 90		SL	O	Paint, Acetone, Stripping sludge	D001 F002 WT02	D	3267	P	
2	20010	03 13 90		L	OI	Paint, Mineral Spirits, Brushes	D001 WT02	D	781	P	
3	20010	03 13 90		L	O	Methylene Chloride, Paint Thinner	D001 F003 WT02	D	473	P	
4	20010	03 13 90		L	OI	Laboratory Solvent Waste (Hal./Non-Hal.)	D001 F002 WT02 F003	D	402	P	
5							F005				
6	20010	03 13 90		L	O	Phenolic Resin Solution	D001 U188 WT02	D	638	P	
7	20082	05 02 90	E	L	I	Magnesium Bromide/Glycerin Solution			(10,653.5P)		
8	20082	05 02 90	E	L	O	Tripropylene Glycol			(583P)		
9	20082	05 02 90	E	L	O	Glycerin			(621.5P)		
10	20084	05 02 90		L	O	Acetone, Methylene Chloride, Toluene, Acetonitrile	D001 F003 WT02 F005	D	1848	P	
11	20192	08 15 90		L	O	Oil Contaminated With 1,1,1 Trichloroethane	D001 F001 WT02 F002	D	7805	P	
12							F003 F005				
13	20192	08 15 90	E	L	O	Oil			(1540P)		
14											
15											

16. COMMENTS (Enter information by section and/or line number—see instructions).

Page ____ of ____

Form 4 1990 **GENERATOR ANNUAL DANGEROUS WASTE REPORT** 1990 Form 4

12. YOUR EPA/STATE I.D. NUMBER	13. RECEIVING FACILITY (TSD)		14. TRANSPORTER
WAD980738033	EPA/STATE I.D. NUMBER: COD982581050	NAME: Chemical Handling Corporation ADDRESS: 11811 Upham Street City: Broomfield, State: CO, ZIP: 80020	NAME: Chemical Handling Corporation EPA/STATE I.D. NUMBER: WAD988471629 ADDRESS: City: Tacoma, State: WA, ZIP:

15. WASTE IDENTIFICATION

LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)	H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. W E C I O G D H E T	K. For TSD Facility Use Only
1	20187	08 24 90		L	O	Methylene Chloride, Xylene	D001 WT02 F002 F003	D	468	P	
2							F005				
3	20188	08 24 90		L	OI	Enamel and Latex Paint	D001 WT02	D	1881	P	
4	20188	08 24 90		L	O	Toluene, Xylene	D001 WT02 F003 F005	D	792	P	
5	20231	09 21 90		L	OI	Household Paint Related Material					
6	20232	09 21 90		L	OI	Paint, Xylene, Toluene	D001 WT02 F003 F005	D	4032	P	
7	20232	09 21 90		L	O	Xylene, Toluene	D001 WT02 F003 F005	D	2052	P	
8	20232	09 21 90		L	O	Methylene Chloride, Phenols	F002 WT01 F003	D	384	P	
9	20282	11 02 90		L	O	Paint, Xylene, Toluene	D001 WT02 F003 F005	D	517	P	
10	20282	11 02 90		L	OI	Xylene, Toluene	D001 WT02 F003 F005	D	1188	P	
11	20282	11 02 90		L	O	Methylene Chloride, Phenols	F002 WT01 F003	D	704	P	
12	20283	11 02 90		L	OI	Methylene Chloride, Xylene	D001 WT02 F002 F003		957	P	
13							F005				
14	20284	11 02 90	E	S	I	Scrap Metal, Crushed Empty Containers			(1600P)		
15											

16. COMMENTS (Enter information by section and/or line number—see instructions).

Manifest 20232 Designated Facility: Ashgrove Cement Co. USEPAID#: NED 007260672
20282 Hwy 50 & 66 Interchange
Louisville, NE 68037

Page____ of____

Form 4 1990 GENERATOR ANNUAL DANGEROUS WASTE REPORT 1990 Form 4

12. YOUR EPA/STATE I.D. NUMBER	13. RECEIVING FACILITY (TSD)		14. TRANSPORTER
WAD980738033	EPA/STATE I.D. NUMBER: NED007260672	NAME: Ash Grove Cement Company ADDRESS: Highway 50 and 66 Interchange City: Louisville, State: NE, ZIP: 68037	EPA/STATE I.D. NUMBER: WAD988471629 NAME: Chemical Handling Corporation ADDRESS: City: Tacoma, State: WA, ZIP:

15. WASTE IDENTIFICATION

LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)	H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. WEIGHT OR VOLUME	K. For TSD Facility Use Only
1	20295	11 09 90		L	O	Toluene, Methanol	D001 WT02 F003 F005	D	979	P	
2	20295	11 09 90		L	O	Toluene, 1,1,1 Trichloroethane	D001 WT02 F002 F003	D	4356	P	
3							F005				
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											

16. COMMENTS (Enter information by section and/or line number—see instructions).

Page ____ of ____

Form 4 1990 GENERATOR ANNUAL DANGEROUS WASTE REPORT 1990 Form 4

12. YOUR EPA/STATE I.D. NUMBER	13. RECEIVING FACILITY (TSD)		14. TRANSPORTER	
WAD980738033	EPA/STATE I.D. NUMBER: ARD069748129	NAME: Ensco ADDRESS: American Oil Road City: Eldorado, State: AR, ZIP: 71730	EPA/STATE I.D. NUMBER: WAD988471629	NAME: Chemical Handling Corporation ADDRESS: City: Tacoma, State: WA, ZIP:

15. WASTE IDENTIFICATION LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)	H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. WECIOGDHET	K. For TSD Facility Use Only
1	20345	12 27 90		L	O	Iso-propanol	D001 D003 / WL01 U108		150	P	
2							F002 F003 / F005				
3	20345	12 27 90		L	O	Silane	D001 D003 / WL01		11	P	
4	20345	12 27 90		S	O	Coke, Carbon	D018 / WL01		15	P	
5	20345	12 27 90		S	O	Carbide	D001 D003 / WL01		15	P	
6	20345	12 27 90		L	OI	Zirconyl Chloride	D002 / WL02		160	P	
7	20345	12 27 90		L	I	Nitric Acid	D002 D006 / WL01 D007		108	P	
8							D009				
9	20345	12 27 90		L	I	Sodium Hydroxide	D002 / WL01		40	P	
10	20345	12 27 90		S	I	Sodium Hydroxide	NR / WL01		70	P	
11	20345	12 27 90		L	O	Acetic Acid, Glacial	D002 / WL01		46	P	
12	20345	12 27 90		L	O	Phenol	U188 / WL01		280	P	
13	20345	12 27 90		S	I	Osmium Tetroxide	P087 D007 / WL01		113	P	
14	20345	12 27 90		S	I	Calcium Nitrate	D001 / WL01		60	P	
15	20345	12 27 90		L	I	Nitric Acid	D001 D007 / WL02		44	P	

16. COMMENTS (Enter information by section and/or line number—see instructions).

Page ____ of ____

Form 1990 GENERATOR ANNUAL DANGEROUS WASTE REPORT 1990 Form 4

12. YOUR EPA/STATE I.D. NUMBER: WAD980738033

13. RECEIVING FACILITY (TSD) EPA/STATE I.D. NUMBER: ARD069748129
NAME: Ensco
ADDRESS: American Oil Road
City: Eldorado, State: AR ZIP: 71730

14. TRANSPORTER EPA/STATE I.D. NUMBER: WAD988471629
NAME: Chemical Handling Corporation
ADDRESS:
City: Tacoma, State: WA ZIP:

15. WASTE IDENTIFICATION

LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)		H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. W E C I O G D H E T	K. For TSD Facility Use Only
1	20345	12 27 90		L	I	Formaldehyde	D001 D007	WL02	D	44	P	
2	20345	12 27 90		L	O	Benzoyl Peroxide, Urea Peroxide	D003	WL01	E	17	P	
3	20345	12 27 90		L	OI	Alcohol Resin	D001	WL02	D	76	P	
4	20345	12 27 90		L	I	Picric Acid Solution	F003	WL02	E	95	P	
5	20345	12 27 90		L	I	Ammonia	D002	WL02	D	64	P	
6	20345	12 27 90		L	O	Amines with Petroleum Derivatives	D001 D002	WL02	D	17	P	
7	20345	12 27 90		SL	I	Bromine	D002	WL01	E	11	P	
8	20345	12 27 90		SL	I	Phosphorous, Yellow, in Water	D001 D003	WL01	E	25	P	
9	20345	12 27 90		L	O	Quaternary Amines	NR	WL02	D	52	P	
10	20345	12 27 90		L	I	Non-RCRA Liquid	NR	WL02		55	P	
11	20345	12 27 90		S	I	Non-RCRA Solid	NR	WL02		120	P	
12	20345	12 27 90		S	I	Vanadium Pentoxide	P120	WL02	E	165	P	
13	20345	12 27 90	T	L	O	Acetone, Polychlorinated Biphenyls	D001 F002	D002 F003		50	P	
14							F005 D018	D019 D028				
15							D021					

16. COMMENTS (Enter information by section and/or line number—see instructions).

Page ____ of ____

FORM ECY 030-28 (Rev. 10-90) -28B-1518-

—CONTINUATION SHEET—

Form 4

Form 2 1990 **GENERATOR ANNUAL DANGEROUS WASTE REPORT** 1990 F n 4

12. YOUR EPA/STATE I.D. NUMBER	13. RECEIVING FACILITY (TSD)		14. TRANSPORTER
	EPA/STATE I.D. NUMBER	NAME: Quicksilver Products, Inc.	EPA/STATE I.D. NUMBER
WAD980738033	CAD981424732	ADDRESS: 2000 Valley Drive, Suite One	WAD988471629
		City: Brisbane, State CA ZIP: 94005	NAME: Chemical Handling Corporation ADDRESS: City: Tacoma, State WA ZIP:

15. WASTE IDENTIFICATION

LINE	A. Manifest Document Number	B. Manifest Shipment Date (MM DD YY)	C. Status	D. Physical State S=Solid L=Liquid G=Sludge M=Compressed Gas	E. Chemical Nature O=Organic I=Inorganic	F. Waste Description (see instructions)	G. Dangerous Waste Number (see instructions and WAC 173-303)	H. Waste Designation D=DW E=EHW	I. Amount of Waste	J. W E C I O G D H E T	K. For TSD Facility Use Only
1	20342	12 28 90		SL	I	Mercury, Metallic	U151 WL01	D	280	P	
2											
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											

16. COMMENTS (Enter information by section and/or line number—see instructions).

Page____ of____