SDMS DOCID# 1118175

f California—Health and Welfare Agency
IDOUS WASTE MANAGEMENT BRANCH
...eet
...nento, CA 95814

March 28, 1983

UNIFORM HAZARDOUS WASTE MANIFEST

Department of Health Services
P.O. #3585
Shipper # 11117

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83029734

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE
3242 E. Olympic
Los Angeles, CA.
AREA CODE/PHONE NUMBER 268-4281

MANIFEST DOCUMENT NUMBER

EPA ID NUMBER
CAX000036488

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA. 90602

VEH./CONTAINER NO.

EPA ID NUMBER
CA DO 422450011

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.

EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.
AREA CODE/PHONE NUMBER 213/698-0991

EPA ID NUMBER
CA DO 422450011

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT NO.	DIS MET
Hazardous Substance, Liquid N.O.S. Flexosolvent - ORM-E	NA 9188	120	G	4	DN	211	01

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
Perchlorethylene	70	60		
N-Butanol	14	12		
Photo PDLt, nzr Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS
gross 49.1 gals
waste 30.2 gals

4 #30 gal

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

Printed or typed full name and signature

MO. 04 DAY 04 YR. 83

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
Isaac Woods Jr
DATE REC'D & ACCEPTED MO. 4 DAY 4 YR. 83

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO. DAY YR.

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature
Steve Simpson

EPA ID NUMBER
CA DO 422450011

DATE RECEIVED & ACCEPTED MO. 04 DAY 05 YR. 83

06/13/2001 "ORIGINAL MANIFEST COPY"

State of California – Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
744 P Street
Sacramento, CA 95814

UNIFORM HAZARDOUS WASTE MANIFEST
June 8, 1983

Department of Health Services
Shipper 11478
P.O.# 3672

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83029903

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS (Tony)
PARA PLATE
3242 E. Olympic Blvd.
Los Angeles, CA 90023
AREA CODE PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER

EPA ID NUMBER CAX00 00364 83

TRANSPORTER NO 1
OMEGA CHEMICAL CORP.
12504 E.Whittier Blvd.
Whittier CA 90602

VEH./CONTAINER NO.

EPA ID NUMBER CAD004 22450 01

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.

EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.

EPA ID NUMBER CAD004 22450 01

AREA CODE PHONE NUMBER 213/698-0991

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT NO.	DISP. METH.
Hazardous Substance, Liquid NOS-ORM-E	NA 9 1 B9	90	G	3	DM	2 0 1	0 1
(FLEXOSOLVENT)							

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene	70	60		
Butanol	14	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS
yield 39.3 gals waste 26 gals.

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

Printed or typed full name and signature [signature] MO. 6 DAY 8 YR. 83

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature [signature] DATE REC'D & ACCEPTED MO. 6 DAY 8 YR 83

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature DATE REC'D & ACCEPTED MO. DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

STEVE SIMPSON [signature]
Printed or typed full name and signature

EPA ID NUMBER CAD004 22450 01

DATE RECEIVED & ACCEPTED MO. 06 DAY 15 YR 83

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
744 P Street
Sacramento, CA 95814

UNIFORM HAZARDOUS WASTE MANIFEST

June 20, 1983

Department of Health Services
Shipper #020
P.O.# 3681

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83029937

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE (Tony)
3242 E. Olympic Blvd.
Los Angeles, CA 90023
AREA CODE/PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER

EPA ID NUMBER CA X00 00 36 4 83

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier CA 90602

VEH./CONTAINER NO.

EPA ID NUMBER CAD 042246001

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.

EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
Omega Chemical Corp.
12504 E. Whittier Blvd.
AREA CODE/PHONE NUMBER 213/698-0991

EPA ID NUMBER CAD 042246001

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT./VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT NO.	DISP. METH
Hazardous waste, Liquid, N.O.S.		30		1	DM	211	91
(FLEXOSOLVENT)	NA 9189	~~60~~	G	~~02~~	~~DM~~	~~211~~	~~01~~

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
PERCHLORETHYLENE	70	60		
BUTANOL	14	12		
PHOTOPOLYMER RESIN	30	20		

SPECIAL HANDLING INSTRUCTIONS
yield 13.7 gals. waste 8.8 gals.

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

Printed or typed full name and signature [signature] MO. DAY YR.

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature [signature] DATE REC'D & ACCEPTED MO. 6 DAY 21 YR. 83

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature DATE REC'D & ACCEPTED MO. DAY YR.

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature STEVE SIMPSON [signature]

EPA ID NUMBER CAD 042246001

DATE RECEIVED & ACCEPTED MO. 06 DAY 24 YR. 83

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

06/01/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814

UNIFORM HAZARDOUS WASTE MANIFEST

August 4, 1983

Department of Health Services
P.O.# 3962
Shipper 11634

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83212218

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE (Max)
3242 E. Olympic Blvd.
Los Angeles, CA 90023
AREA CODE/PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER CA XO 00 0 36 4 83

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier CA 90602

VEH./CONTAINER NO.
EPA ID NUMBER CA D 0 4 2 24 5 0 01

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.
EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.

EPA ID NUMBER CA D0 4 2 245 0 01

AREA CODE/PHONE NUMBER 213/698-0991

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT. NO.	DISP. METH
Hazardous waste, Liquid N.O.S.-ORM-E	N A 9 189	080	G	0 2	DM	2 11	01
(FLEXOSOLVENT)							

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene	70	60		
N-Butyl Alcohol	14	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature

MO DAY YR

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO. 8 DAY 15 YR. 83

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature

EPA ID NUMBER CA D0 4 2 245 0 01

DATE RECEIVED & ACCEPTED MO. 0 8 DAY YR 8 3

NO DHS-8022A 11/82

GENERATOR SENDS THIS COPY TO DOHS WITHIN 15 DAYS

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814

September 6, 1983
UNIFORM HAZARDOUS WASTE MANIFEST

Department of Health Services
P.O.#3981
Shipper #11796

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83212340

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE
3242 E. Olympic
Los Angeles, Ca. 90023
AREA CODE/PHONE NUMBER

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER
CAX01 000 364 483

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA. 90602

VEH./CONTAINER NO. 141507
EPA ID NUMBER CA D01 42245001

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.
EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.
AREA CODE/PHONE NUMBER

EPA ID NUMBER CA D01 42245001

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT. NO.	DISP. METH.
Hazardous Substance, Liquid N.O.S (FLEXOSOLVENT) ORM-E	NA 9188	90	G	3	DM	211	06

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene	70	60		
N-Butyl Alcohol	14	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS
full 50.2 gals. waste 17.2 gals

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature

MO DAY YR

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Henry Solomon
Printed or typed full name and signature

DATE REC'D & ACCEPTED MO 09 DAY 12 YR 83

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature

DATE REC'D & ACCEPTED MO DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.
STEVE SIMPSON
Printed or typed full name and signature

EPA ID NUMBER CA D0 42245001

DATE RECEIVED & ACCEPTED MO 09 DAY 12 YR 83

FORM NO. DHS 8022A 11/82

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

03/29/2000 "ORIGINAL MANIFEST COPY"

10/12/81

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814

Department of Health Services

UNIFORM HAZARDOUS WASTE MANIFEST

Shipper #11955
P.O.#3107

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83376131

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARAPPLATE
3242 E. Olympic Blvd.
Los Angeles,Ca. 90023
AREA CODE/PHONE NUMBER 268-4283

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER CAX000036483

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, Ca. 90602

VEH./CONTAINER NO. 0 00 42 5 08
EPA ID NUMBER CA D0 42245001

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY
V.EH./CONTAINER NO.
EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.
AREA CODE/PHONE NUMBER 698-0991
EPA ID NUMBER CA D0 42245001

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT. NO.	DISP. METH.
Hazardous Waste Liquid N.O.S. (FLEXOSOLVENT)	NA 9188	00	G	02	DM	111	d1

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene	70	60		
N-Butyl Alcohol	14	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

Printed or typed full name and signature

MO. DAY YR.

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO. 10 DAY 12 YR. 81

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO. DAY YR.

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

EPA ID NUMBER CA D0 42245001

DATE RECEIVED & ACCEPTED MO. DAY YR.

Printed or typed full name and signature

FORM NO. DHS-8022A 11/82

GENERATOR SENDS THIS COPY TO DOHS WITHIN 15 DAYS

05/31/2001 "ORIGINAL MANIFEST COPY"

ate of California – Health and Welfare Agency
AZARDOUS WASTE MANAGEMENT BRANCH
4 744 P Street
icramento CA 95814

UNIFORM HAZARDOUS WASTE MANIFEST
February 29, 1983

Department of Health Services
P.O.# 7251
Shipper 358666

ease print or type with ELITE type (12 characters per inch)

STATE ID NUMBER 83410733

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE CO.
3242 E. Olympic Blvd.
Los Angeles, CA 90023
AREA CODE PHONE NUMBER

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER
CAX000036483

TRANSPORTER NO 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602

VEH /CONTAINER NO
EPA ID NUMBER
CAD042245001

TRANSPORTER NO 2/ALTERNATE TSD FACILITY

VEH /CONTAINER NO
EPA ID NUMBER

TREATMENT, STORAGE OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.
AREA CODE/PHONE NUMBER 213/698-0991

EPA ID NUMBER
CAD042245001

PROPER U.S. DOT SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO	CONTAINER TYPE	WASTE CAT NO	DISP METH
Hazardous Waste, Liquid NOS -ORM-E (FLEXOSOLVENT)	NA9189	60	G	02	DM	2110	01

COMPONENTS	CONC RANGE UPPER	CONC RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene	70	60		
N-Butanol	19	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS
yield 29.4 gals waste 10.1 gals.

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature

MO 02 DAY 1 YR 84

☐ Check if continuation sheet is used Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO 03 DAY 1 YR 84

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
Printed or typed full name and signature
DATE REC'D & ACCEPTED MO DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.
STEVE SIMPSON
Printed or typed full name and signature

EPA ID NUMBER CAD042245001

DATE RECEIVED & ACCEPTED MO 03 DAY 02 YR 84

FORM NO DHS-8022A 11/82

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

83-87967

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814 P.O.#6011

Department of Health Services

UNIFORM HAZARDOUS WASTE MANIFEST

Please print or type with ELITE type (12 characters per inch)

STATE ID NUMBER 83410809

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
Para Plate
3242 E. Olympic Blvd.
Los Angeles, Ca.
AREA CODE/PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER CAX000036483

TRANSPORTER NO 1
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, Ca. 90602

VEH./CONTAINER NO
EPA ID NUMBER CAD042245001

TRANSPORTER NO 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO
EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMega Chemical Corp.
AREA CODE/PHONE NUMBER 213/698-0991

EPA ID NUMBER CAD042245001

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT NO	DISP METH
Hazardous Waste, Liquid N.O.S -ORM-E FLEXOSOLVENT	NA 9189	60	G	02	DM	211	01

COMPONENTS	CONC RANGE UPPER	CONC RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylene				
Photo Polymer Resin				
N-Butyl Alcohol				

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

MAX STEVANUS — MO 11 DAY 07 YR 84

Printed or typed full name and signature

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES
ISAAC Woods Jr — DATE REC'D & ACCEPTED MO 11 DAY 07 YR 84

Printed or typed full name and signature

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES — DATE REC'D & ACCEPTED MO DAY YR

Printed or typed full name and signature

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

11-07-84

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

STEVE SIMPSON — EPA ID NUMBER CAD042245001 — DATE RECEIVED & ACCEPTED MO 11 DAY 07 YR 84

Printed or typed full name and signature

FORM NO DHS 8022A 11/87 — TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS — 83-87967

State of California – Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814

05/09/84

Department of Health Services

UNIFORM HAZARDOUS WASTE MANIFEST

Please print or type with ELITE type (12 characters per inch)

STATE ID NUMBER 83494051

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE
3242 E. OLYMPIC
LOS ANGELES, CA.

AREA CODE/PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER

EPA ID NUMBER CAX000036423

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. WHITTIER BLVD
WHITTIER, CA. 90602

VEH./CONTAINER NO. 00042507

EPA ID NUMBER CAD042245001

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.

EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.

AREA CODE/PHONE NUMBER 213/268-4281

EPA ID NUMBER CAD042245001

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT. NO.	DISP. METH.
HAZARDOUS WASTE, LIQUID N.O.S - ORM-E FLEXOSOLVENT	NA9189	60	G	02	DM	211	01

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
PERCHLOROETHYLENE	70	60		
PHOTO POLYMER RESIN	30	20		
N-BUTYL ALCOHOL	14	12		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature [signature] MO. 05 DAY 10 YR 84

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature [signature] DATE REC'D & ACCEPTED MO. 05 DAY 10 YR 84

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature DATE REC'D & ACCEPTED MO. DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature STEVE SIMPSON [signature]

EPA ID NUMBER CAD042245001

DATE RECEIVED & ACCEPTED MO. 05 DAY 10 YR 84

FORM NO. DHS-8022A 11/82

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

83-87987

05/27/84

California Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
1700 K Street
Sacramento, CA 95814

P.O. #7274
SHIPPER #297381

Department of Health Services

UNIFORM HAZARDOUS WASTE MANIFEST

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83494162

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARAPPLATE
3242 E. OLYMPIC BLVD.
LOS ANGELES, CA.

AREA CODE/PHONE NUMBER

MANIFEST DOCUMENT NUMBER

EPA ID NUMBER CAX000013483

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. WHITTIER BLVD.
WHITTIER, CA. 90602

VEH./CONTAINER NO. 0004250 7

EPA ID NUMBER CAD042245001

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.

EPA ID NUMBER

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.

EPA ID NUMBER CAD042245001

AREA CODE/PHONE NUMBER 213/698-0991099

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO	CONTAINER TYPE	WASTE CAT. NO	DISP METH
HAZARDOUS WASTE, LIQUID N.O.S	NA9189	60	G	02	DM	211	01

COMPONENTS	CONC. RANGE UPPER	CONC. RANGE LOWER	UNITS %	UNITS PPM
PERCHLOROETHYLENE	70	60		
PHOTO POLYMER RESIN	30	20		
N-BUTYL ALCOHOL	14	12		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature

MO DAY YR

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature

DATE REC'D & ACCEPTED MO 5 DAY 28 YR 84

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature

DATE REC'D & ACCEPTED MO DAY YR

DISCREPANCY INDICATION SPACE

TO BE FILLED IN BY TSDF

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature

EPA ID NUMBER CAD042245001

DATE RECEIVED & ACCEPTED MO DAY YR

DHS 8022A 11/82

GENERATOR SENDS THIS COPY TO DOHS WITHIN 15 DAYS

04/26/2000 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714-744 P Street
Sacramento, CA 95814

P.O.#7485

08/13/84

UNIFORM HAZARDOUS WASTE MANIFEST

Department of Health Services

Please print or type with ELITE type (12 characters per inch).

STATE ID NUMBER 83564065

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE PLASTICS
3242 E. OLYMPIC BLVD.
LOS ANGELES, CA. 90023

AREA CODE/PHONE NUMBER

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER
CA X 00 00 3 6 48 3

TRANSPORTER NO. 1
OMEGA CHEMICAL CORP.
12504 E. WHITTIER BLVD.
WHITTIER, CA. 90602

VEH./CONTAINER NO.: 0 00 42 5 07
EPA ID NUMBER: C AD 0 4 22 45 0 01

TRANSPORTER NO. 2/ALTERNATE TSD FACILITY

VEH./CONTAINER NO.:
EPA ID NUMBER:

TREATMENT, STORAGE, OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.

EPA ID NUMBER
C AD 04 2 2 4 500 1

AREA CODE/PHONE NUMBER 213/698-0991

PROPER U.S. D.O.T. SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO.	CONTAINER TYPE	WASTE CAT NO	DISP METH
HAZARDOUS WASTE, LIQUID N.O.S - ORM-E FLEXOSOLVENT	N A9 1 89	60	G	0	D M	21 1	01

COMPONENTS	CONC RANGE UPPER	CONC RANGE LOWER	UNITS %	UNITS PPM
PERCHLOROETHYLENE		65		
PHOTO POLYMER RESIN		20		
N-BUTYL ALCOHOL		15		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA.

Printed or typed full name and signature MAX STEVANUS

MO. 08 DAY 14 YR 84

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature Tim Baltzer

DATE REC'D & ACCEPTED MO. 08 DAY 14 YR 84

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature

DATE REC'D & ACCEPTED MO. DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions.

Printed or typed full name and signature STEVE SIMPSON

EPA ID NUMBER CA D 0 4 22 45 00 1

DATE RECEIVED & ACCEPTED MO. 08 DAY 14 YR 84

FORM NO. DHS-8022A 11/82

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

83-87967

State of California—Health and Welfare Agency
HAZARDOUS WASTE MANAGEMENT BRANCH
714 744 P Street
Sacramento, CA 95814

UNIFORM HAZARDOUS WASTE MANIFEST

Sept. 25, 1984

Department of Health Services
P.O.# 8074
Shipper 13047

Please print or type with ELITE type (12 characters per inch)

STATE ID NUMBER 83564148

TO BE FILLED IN BY GENERATOR

GENERATOR NAME AND MAILING ADDRESS
PARA PLATE PLASTICS
3242 E. Olympic Blvd.
Los Angeles, CA 90023
AREA CODE PHONE NUMBER 213/268-4281

MANIFEST DOCUMENT NUMBER
EPA ID NUMBER
CAXD003648 3

TRANSPORTER NO 1
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602

VEH/CONTAINER NO: 42507
EPA ID NUMBER: CAD042245001

TRANSPORTER NO 2 ALTERNATE TSD FACILITY

VEH/CONTAINER NO
EPA ID NUMBER

TREATMENT STORAGE OR DISPOSAL (TSD) FACILITY
OMEGA CHEMICAL CORP.
AREA CODE PHONE NUMBER 213/698-0991
EPA ID NUMBER: CAD042245001

PROPER U.S. DOT SHIPPING NAME AND HAZARD CLASS	UN/NA NUMBER	TOTAL QUANTITY	UNIT WT/VOL	CONTAINER NO	CONTAINER TYPE	WASTE CAT NO	DISP METH
Hazardous Waste, Liquid NOS. -ORM- E	NA 9189	030	G	02	DM	211	01
(FLEXOSOLVENT)							

COMPONENTS	CONC RANGE UPPER	CONC RANGE LOWER	UNITS %	UNITS PPM
Perchloroethylen	70	60		
N-Butyl Alcohol	14	12		
Photo Polymer Resin	30	20		

SPECIAL HANDLING INSTRUCTIONS

This is to certify that the above-named wastes are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable requirements of the Department of Transportation and the EPA

Printed or typed full name and signature: TONY SKRATULIA Tony Skratulia

MO 9 DAY 27 YR 84

☐ Check if continuation sheet is used. Number of continuation sheets

TO BE FILLED IN BY TRANSPORTER

TRANSPORTER 1 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature: Henry Solomon Henry Solomon

DATE REC'D & ACCEPTED MO 9 DAY 27 YR 84

TRANSPORTER 2 ACKNOWLEDGEMENT OF RECEIPT OF ABOVE WASTES

Printed or typed full name and signature

DATE REC'D & ACCEPTED MO DAY YR

TO BE FILLED IN BY TSDF

DISCREPANCY INDICATION SPACE

Facility owner or operator: Certification of receipt of hazardous waste covered by this manifest except as noted in the discrepancy indication space above. Note: TSDF must complete waste number. See instructions

STEVE SIMPSON Steve Simpson
Printed or typed full name and signature

EPA ID NUMBER: CAD042245001

DATE RECEIVED & ACCEPTED: MO 09 DAY 27 YR 84

FORM NO DHS 8022A 11/82

TSDF SENDS THIS COPY TO DOHS WITHIN 15 DAYS

83-87967

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd.
Los Angeles, Ca. 90023

4. Generator's Phone 213/698-0991

A. State Manifest Document Number 84341247

B. State Generator's ID CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.

6. US EPA ID Number: CAD042245001

C. State Transporter's ID

D. Transporter's Phone 213/598-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S (flexosolvent) ORM-A	02	DM	720	P	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
*PERCHLORETHYLENE
* ~~MEGAHUM~~ BUTANOL
* PHOTOPOLYMER RESIN

K. Handling Codes for Wastes Listed Above: 01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANUS — Signature: [signature] — Date (Month Day Year): 12/19/84

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr. — Signature: Isaac Woods Jr. — Date (Month Day Year): 12/19/84

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date (Month Day Year)

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVE SIMPSON — Signature: [signature] — Date (Month Day Year): 12/19/84

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 80641

PERMANENT EPA # to follow

State of California—Health and Welfare Agency

January 21, 1985

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 0000 36483
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE (TONY)
3242 E. Olympic Blvd.
Los Angeles, CA 90023

4. Generator's Phone 213/268-4281

A. State Manifest Document Number 84341307
B. State Generator's ID CAX 0000 36483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID SS-19
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD 042 245 001
H. Facility's Phone 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Hazardous Waste, Liquid NOS ORM-E NA 9189 (FLEXOSOLVENT)	1	DM	30	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PER CHLOREETHYLENE
BUTYL ALCOHOL
PHOTO POLYMER RESIN

K. Handling Codes for Wastes Listed Above
01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Max Stevanus
Signature: MAX STEVANUS
Date: Month 1 Day 23 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods Jr.
Date: Month 1 Day 23 Year 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVE SIMPSON
Signature: Steve Simpson
Date: Month 01 Day 23 Year 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

BN 80641

State of California—Health and Welfare Agency

3-7-85

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, CA 90023
4. Generator's Phone (213) 268-4281 Tony

A. State Manifest Document Number: 8434142U
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 5267P
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. HAZARDOUS WASTE, LIQUID N.O.S. ORM-A NA1693 (FLEXOSOLVENT)	6	DM	220	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PERCHLORETHYLINE
BUTANOL
PHOTOPOLYMER

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information
*** 4 Drums - 30 Gallon Drums
2 Drums - 55 Gallon Drums.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVENS
Signature: [signature]
Date: Month 3 Day 7 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods Jr
Date: Month 3 Day 7 Year 85

18. Transporter 2 Acknowledgement or Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 03 Day 07 Year 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 80541

State of California—Health

Department of Health Services
Toxic Substances Control Division
Sacramento, California

3-27-85

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, CA 90023
4. Generator's Phone (213) 268-4281 Tony

A. State Manifest Document Number: 84341476
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 62572
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/ 698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S. NA9189 (FLEXOSOLVENT)	1	DM	30	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
* PERCHLORETHYLENE
* BUTANOL
* PHOTOPOLYMER RESIN

K. Handling Codes for Wastes Listed Above: P01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANUS
Signature: Max Stevanus
Date: Month Day Year 3 27 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Isaac Woods Jr
Signature: Isaac Woods Jr.
Date: Month Day Year 3 27 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month Day Year 03 28 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 80641

Shipper 13653

State of California—Health and Welfare Agency

April 15, 1985

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd. L.A., CA 90032

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 84341518

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 62569

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S. NA 1693 (Flexosolvent)	3	DM	90	G	211
b. PERCHLORETHYLENE					
c. BUTANOL					
d. PHENOLSTYRENE RESIN					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANUS — Signature: [signature] — Date: Month 4 Day 10 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: [signature] — Date: Month 4 Day 11 Year 85

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: [signature] — Date: Month 4 Day 15 Year 85

MAX STEVANUS

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 80541

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, Ca. 90032

4. Generator's Phone ( )

A. State Manifest Document Number: 84341650
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Chemical Corp.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 62369
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, Ca. 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S , NA 1693 (FLEXOSOLVENT) ORM-A	1	DM	30	G	211
b. PERCHLORETHYLENE					
c. BUTANOL					
d. PHOTOPOLYMER RESIN					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANUS
Signature: Max Stevanus
Date: Month 5 Day 13 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: [illegible]
Signature: [illegible]
Date: Month 5 Day 13 Year 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 05 Day 13 Year 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 80541

Shipper 14156

State of California—Health and Welfare Agency

June 10, 1985

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, CA 90032

4. Generator's Phone: 213) 268-4281

A. State Manifest Document Number: 84341723
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 62569
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S (Flexosolvent) NA 1693 ORM-A N.O.S	02	DM	66	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchlorothyl, Butyl Alcohol, Rubberism

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Date: Month 6 Day 12 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month 6 Day 12 Year 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 06 Day 12 Year 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 89641

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: cax000036483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca.
4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 84341726
B. State Generator's ID: cax000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 52172
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier Ca. 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 - ORM-A (Flexosolvent)	03	DM	120	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PERCHLORETHLENE
BUTANOL
PHENOPOLYMERO RESIN

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANOS
Signature: Max Stevanos
Date (Month Day Year): 7 24 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods Jr
Date (Month Day Year): 7 24 85

18. Transporter 2 Acknowledgement or Receipt of Materials
Printed/Typed Name:
Signature:
Date (Month Day Year):

FACILITY

19. Discrepancy Indication Space
REC 71.6 gals.

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date (Month Day Year): 07 24 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 89541

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX000036483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca.

4. Generator's Phone

A. State Manifest Document Number: 84341798

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA CHEMICAL CORP.
6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 20572

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA CHEMICAL CORP.
12504 E. Whittier Blvd.
Whittier, Ca. 90602
10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (Flexosolvent)	1	DM	360	P	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchlorethylene
N-Butanol
Photo Resist

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: [illegible] | Signature: [illegible] | Date: Month 8 Day 21 Year 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: [illegible] | Signature: [illegible] | Date: Month 8 Day 21 Year 85

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
RECIEVED 250 lbs

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19

Printed/Typed Name: STEVE SIMPSON | Signature: [illegible] | Date: Month 8 Day 21 Year 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 89641

Para Plate
84341894

Unless I am a small generator who has been exempted by statute or by regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Generator:

Authorized Signature: Mac Hoen 10-10-85

Date:

State of California—Health and Welfare Agency

October 7, 1985

C

Shipper 14550
Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, Calif.

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number 84341894

B. State Generator's ID CAX000036483

5. Transporter 1 Company Name: Omega Chemical Corp.

6. US EPA ID Number: CAD042245001

C. State Transporter's ID 62372

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. ORM-A NA 1693 (Flexosolvent)	4	DM	120	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PERCHLOROETHYLENE
BUTANOL
PHOTOPOLYMER RESIN

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVENS — Signature: [signature] — Date: Month Day Year 10 10 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Isaac Woods Jr — Signature: [signature] — Date: Month Day Year 10 10 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
RECEIVED 76.0 GAL

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: STEVEN SIMPSON — Signature: [signature] — Date: Month Day Year 10 10 85

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 86541

Shipper 14613

State of California—Health and Welfare Agency

October 28, 1985

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX000036483
Manifest Document No:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., LA, CA 90023
4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 84341942
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Chemical Corp.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID:
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. ORM-A NA 1693 (Flexosolvent)	02	DM		G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

VOID

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name | Signature | Date Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date Month Day Year

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name | Signature | Date Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date Month Day Year

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 89541

05/31/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic, Los Angeles, Ca. 90023

4. Generator's Phone ( )

A. State Manifest Document Number: 84345254
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID:
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID: 62572
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blvd.
Whittier, Ca. 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S , NA 1693 ORM-A (Flexosolvent)	4	DM	120	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchloroethylene
N-Butanol
PHOTOPOLYMER

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: PRESTON ROBIN LEDESMA
Signature: Preston Robin Ledesma
Date: Month 3 Day 24 Year 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods Jr
Date: Month 3 Day 24 Year 86

18. Transporter 2 Acknowledgement or Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
RECEIVED 877 GAL

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 03 Day 24 Year 86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8100-22)

84 89641

Para Plate 84345264

Unless I am a small generator who has been exempted by statute or by regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Generator:

Authorized Signature: Peter R. Leder

Date: 3-24-86

P 061

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX000036483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca.

4. Generator's Phone ( )

A. State Manifest Document Number: 84345323
B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 701734
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blvd.
Whittier, Ca. 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 (Flexosolvent) ORM-A	03	DM	75 gallons	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchloroethylene Butnol photopolymer

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Preston Robin Ledesma
Signature: Preston Robin Ledesma
Date: Month 4 Day 16 Year 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods Jr
Date: Month 04 Day 16 Year 86

18. Transporter 2 Acknowledgement or Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
RECEIVED 53 GALS.

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 04 Day 16 Year 86

DHS 8022 A (7/84)
(EPA 8700-22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

84 89541

05/31/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Whittier, Ca. 90602

4. Generator's Phone (213) 698-0991

A. State Manifest Document Number: 84345354

B. State Generator's ID: CAD042245001

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 701735

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blvd.
Whittier, Ca. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 ORM-A (Flexosolvent)	01	DM	30	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: PRESTON ROBIN LEDESMA — Signature: Preston L. Ledesma — Date: Month 5 Day 7 Year 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: TIM BALTIERRA — Signature: Tim Baltierra — Date: Month 05 Day 07 Year 86

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: Steve Simpson — Date: Month 05 Day 09 Year 86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 86641

Para Plate
84345354

Unless I am a small generator who has been exempted by statut
or by regulation
effective
communication
certify that
quantity of waste
economically
practicable
minimizes the present
environment.

Generator
Authorized Signature
Date 5-7-86

State of California—Health and Welfare Agency

C

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca.

4. Generator's Phone ( )

A. State Manifest Document Number: 84720033

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 63576

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blvd.
Whittier, Ca. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (Flexosolvent)	02	DM	55	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
*PERCHLORETHYLENE
*BUTANOL
*1 PHOTOPOLYMER

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANS — Signature: [signature] — Date: Month Day Year 1 2 1 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: Isaac Woods Jr — Date: Month Day Year 01 22 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: Steve Simpson — Date: Month Day Year 01 22 86

84720033

DHS 8022 A (11/84)
(EPA 8700-22)

WHITE TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 3000, Sacramento CA 95812

84 6954

Para Plate 84720033

Unless I am a small generator who has been exempted by statute or by regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Generator:

Authorized Signature:

Date: 1-22-86

Shipper 14713

Dec. 6, 1985

State of California—Health and Welfare Agency

C

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, CA

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number 84881768

B. State Generator's ID CAX000036483

5. Transporter 1 Company Name Omega Chemical Corp.

6. US EPA ID Number CAD042245001

C. State Transporter's ID 62522

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. (Flexosolvent) ORM-A NA 1693	~~002~~ 3	DM	~~3~~90	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
* PERCHLORETHYLENE
* BUTANOL
* PHOTOPOLYMER

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: MAX STEVANUS — Signature: [signature] — Date: Month 12 Day 12 Year 85

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: Isaac Woods Jr. — Date: Month 12 Day 12 Year 85

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

19. Discrepancy Indication Space
RECEIVED 701 GALS.

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: Steve Simpson — Date: Month 12 Day 12 Year 85

84881768

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

DHS 8022 A (11/84)
(EPA 8700-22)

84-89641

May 19, 1986

Shipper 16185

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483

Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, CA 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86534416

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 70113

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	002	DM	45	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: R01

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: PRESTON ROBIN LEDESMA | Signature: Preston R. Ledesma | Month Day Year: 05/19/86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: TIM BATTERRA | Signature: Tim Batterra | Month Day Year: 05/19/86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON | Signature: Steve Simpson | Month Day Year: 05/19/86

86534416

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A X 0 0 0 0 3 6 4 8 3 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca. 90023

4. Generator's Phone ( )

A. State Manifest Document Number: 86534457

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: C A D 0 4 2 2 4 5 0 0 1

C. State Transporter's ID: 701737

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blvd.
Whittier, Ca. 90602

10. US EPA ID Number: C A D 0 4 2 2 4 5 0 0 1

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA1693 ORM-A (Flexosolvent) Z	1	DM	25	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PERCHLOROETHYLENE
N-BUTANOL
PHOTOPOLYMER

K. Handling Codes for Wastes Listed Above
R01

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: MAX STEVENS — Signature: [signature] — Month Day Year: 06 24 86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: [signature] — Month Day Year: 06 24 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space
RECEIVED 19.3 gal

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: [signature] — Month Day Year: 06 24 86

86534457

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P O Box 3000, Sacramento CA 95812

Shipper 16447

August 1, 1986

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, CA 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86534545

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CAD042245001

C. State Transporter's ID

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. (Flexosolvent) NA 1693 ORM-A	00	DM	16	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: R01

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: Preston R. Ledesma — Signature: Preston R. Ledesma — Month Day Year: 08 07 86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: John Hacta — Signature: [illegible] — Month Day Year: 08 07 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON — Signature: Steve Simpson — Month Day Year: 08 07 86

GENERATOR — TRANSPORTER — FACILITY

86534545

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

Shipper 16689

10/6 / 86

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA XD 0 0 0 3 6 4 8 3 — Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, CA 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86534705

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CA D0 4 2 2 4 5 0 0 1

C. State Transporter's ID: 701734

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CA D0 4 2 2 4 5 0 0 1

G. State Facility's ID: CAD 042245 001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N O S NA 1693 ORM-A (FLEXOSOLVENT)	0 04	DM	120	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: Preston Robin Ledesma — Signature: Preston Robin Ledesma — Month Day Year: 10 06 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Frank Woods Jr — Signature: Frank Woods Jr — Month Day Year: 10 06 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 10 06 86

86534705

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento CA 95812

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CIAIX1010101013161418 13

Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, Ca. 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86534799

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CIADI0I4I2I2I4I5I0I0I1

C. State Transporter's ID: 701734

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

6. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, Ca. 90602

10. US EPA ID Number: CIADI0I4I2I2I4I5I0I0I1

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/6980991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 ORM-A (Flexosolvent)	3	DM	00090	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchloroethylene
N-Butanol + Photo Resin

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: PRESTON ROBIN LEDESMA | Signature: Preston Robin Ledesma | Month Day Year: 1/12/04 18

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Isaac Woods Jr | Signature: Isaac Woods Jr | Month Day Year: 1/12/04 18

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD | Signature: Frank Ford | Month Day Year: 1/12/04 18

86534799

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

A

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CIAIX101010101316141813

Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, Ca. 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86544073

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 701737

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, Ca. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 ORM-A (Flexosolvent)	03	DM	300	P	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: 01

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: X Tony Skratulia — Signature: X Tony Skratulia — Month Day Year: 10/1/16/87

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: TIM BALTIERRA — Signature: Tim Baltierra — Month Day Year: 01/1/6/87

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 10/1/6/87

86544073

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles, Ca. 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number: 86544135

B. State Generator's ID: CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 701735

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Blv.d
Whittier, Ca. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

GENERATOR

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 (Flexosolvent)	4	DM	120	G	211
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Perchloroethylene
N-Butanol
Photo Resin

K. Handling Codes for Wastes Listed Above: 01

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: ALBERT KOIKE — Signature: Albert Koike — Month Day Year: 10 12 16 87

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: Isaac Woods Jr — Month Day Year: 10 12 16 87

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 10 12 16 87

86544135

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
to P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C|A|X|0|0|0|0|3|6|4|8|3| — Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. Olympic Blvd., Los Angeles

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number 86544176

B. State Generator's ID CAX000036483

5. Transporter 1 Company Name: Omega Chemical Corp.

6. US EPA ID Number: C|A|D|0|4|2|2|4|5|0|0|1

C. State Transporter's ID 701735

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. WhittierBlvd.
Whittier,Ca. 90602

10. US EPA ID Number: C|A|D|0|4|2|2|4|5|0|0|1

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S, NA 1693 (Flexosolvent) ORM-A	[illegible]	DM	[illegible]	[illegible]	[illegible]
b.	003	DF	000910	G	211
c.					
d.					

J. Additional Descriptions for Materials Listed Above
PERCHLOROETHYLENE 60/50
N. BUTYL ALCOHOL 15/15
PHOTO POLYMER RESIN 25/35

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: ALBERT KOIKE — Signature: [illegible] — Month Day Year: 03 27 87

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: [illegible] — Month Day Year: 03 27 87

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Month Day Year

86544176

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter))

08/13/87

Shipper

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CA X 0 0 0 3 6 4 8 3
Manifest Document No:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
3242 E. Olympic Blvd., Los Angeles, CA 90023

4. Generator's Phone (213 268-4281

A. State Manifest Document Number: 87114229
B. State Generator's ID: C A X 00 0 0 3 64 8 3

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: C A D 0 4 2 2 4 5 0 0 1
C. State Transporter's ID: 507782
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: C A D 0 4 2 2 4 5 0 0 1
G. State Facility's ID: C A D 0 4 2 2 4 5 0 0 1
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	90	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
K. Handling Codes for Wastes Listed Above: a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT KOIKE
Signature: Albert Koike
Month Day Year: 08 14 87

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: TIM BALTIERRA
Signature: Tim Baltierra
Month Day Year: 08 14 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 08 14 87

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1-87)
EPA 8700-22
(Rev. 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

9-11-87 SHIPPER 17742

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483
Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. OLYMPIC BLVD. LOS ANGELES, CA 90023
4. Generator's Phone (213) 268-4281

A. State Manifest Document Number 87114288
B. State Generator's ID CAX000036483

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID
D. Transporter's Phone 213/ 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/ 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S. NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	060	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT KOIKE
Signature: Albert Koike
Month Day Year: 09 11 87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: TIM BALTIERRA
Signature: Tim Baltierra
Month Day Year: 09 11 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature: ~~ALBERT KOIKE~~
Month Day Year: 09 11 87

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 09 11 87

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050--0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

10-1-87 SHIPPER 17796

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000013648B
Manifest Document No. 1111

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
3242 E. OLYMPIC BLVD. LOS ANGELES, CA 90023

4. Generator's Phone (213) 268-4281

A. State Manifest Document Number 87114318

B. State Generator's ID CAX000364883

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 403765

D. Transporter's Phone: 213/ 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/ 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S. NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	160	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. D1 b. c. d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT KOIKE — Signature: [signature] — Month Day Year: 10 02 87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: IM BALTIERRA — Signature: [signature] — Month Day Year: 10 02 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 10 02 87

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

04-15-88 SHIPPER 15253

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX 000 036 483
Manifest Document No.:

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87114430

B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 24480

D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD042245001

H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	60	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: [signature]
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Gil Solomon
Signature: [signature]
Month Day Year: 4/1/88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: [signature]
Month Day Year: 4/1/88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

01/21/88 Shipper 14941

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: C A X 0 0 0 0 36483
Manifest Document No.

2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 87118531

B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: C A D 042 245 001

C. State Transporter's ID

D. Transporter's Phone: ~~213/698-0991~~

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: C A D 042 245 001

G. State Facility's ID: C A D 0 4 2 2 4 5 0 0 1

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	001	DM	30	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
Perchloroethylene
N-Butyl Alcohol
Photo. Resist Resin

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT KOIKE
Signature: Albert Koike
Month Day Year: 1 1 2 2 8 8

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Fred Mittwer
Signature: Fred Mittwer
Month Day Year: 1 1 2 2 8 8

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 1 0 1 2 2 8 8

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).) 02-10-88 SHIPPER 15008

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CIAIX|0|0|0 10|3|6|6|8|3
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87118559
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CIAID|0|4|2|2|4|5|0|0|1
C. State Transporter's ID: 803785
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CIAID|0|4|2|2|4|5|0|0|1
G. State Facility's ID: CAID042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A NOS NA 1693 ORM-A (FLEXOSOLVENT)	003	DM	1910	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT KOIKE
Signature: Albert Koike
Month Day Year: 02 15 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 02 15 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 02 15 88

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-89)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

02/24/88

Shipper 15068

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A X 0 0 00 3 6 48 3 — Manifest Document No

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87118582

B. State Generator's ID

5. Transporter 1 Company Name
Omega Recovery Services

6. US EPA ID Number CAD 042 245 001

C. State Transporter's ID

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number C AD 042 245 001

G. State Facility's ID CAD042245991

H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	001	DM	30	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: JULIO A. ROSALES — Signature: Julio A. Rosales — Month Day Year: 02 25 88

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: JAVIER HERNANDEZ — Signature: Javier Hernandez — Month Day Year: 02 25 88

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 02 25 88

GENERATOR

TRANSPORTER

FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter). 3-10-88 SHIPPER 18157

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 000035483
Manifest Document No.

2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER., CERRITOS, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87118639
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID
D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE DRM-A NOS NA 1693 DRM-A (FLEXOSOLVENT)	001	DIM	≈45	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Julio C. Rosales
Signature
Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: CHRIS E. MARTINEZ
Signature
Month Day Year 03 16 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature
Month Day Year 03 16 88

GENERATOR
TRANSPORTER
FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White, TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

03/23/88

Shipper 15

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: C AX 0 00 0 364 8 3
Manifest Document No.:

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 87118663

B. State Generator's ID:

5. Transporter 1 Company Name: Omega RecoveryServices

6. US EPA ID Number: C A D 04 2 245 00 1

C. State Transporter's ID: 803783

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: C A D 04 2 2 45 001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	00 2	DM	60	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 03 24 88

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: [illegible]
Month Day Year: 03 24 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 03 29 88

GENERATOR
TRANSPORTER
FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

Shipper 18410 5/6/88

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA X D 0 0 1 0 3 6 4 8 3
Manifest Document No

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 87118777

B. State Generator's ID

5. Transporter 1 Company Name
Omega Recovery Services

6. US EPA ID Number C AD 04 2 2 4 50 0 1

C. State Transporter's ID 904880

D. Transporter's Phone 213-698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number C AD 04 2 2 4 50 01

G. State Facility's ID CAD042245001

H. Facility's Phone 213-698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. NA 1693 ORM-A (Flexosolvent)	2	DM	60	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: [signature]
Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: [signature]
Month Day Year 05 09 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

ncy Indication Space

Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
FORD
Signature: [signature]
Month Day Year 05 10 88

White, TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

GENERATOR

TRANSPORTER

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

Ref. 20172 06/10/88

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000036483
Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87118810

B. State Generator's ID

5. Transporter 1 Company Name
Omega Recovery Services

6. US EPA ID Number CAD042245001

C. State Transporter's ID 904879

D. Transporter's Phone

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone 213-698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. NA 1693 ORM-A (Flexosolvent)	2	DM	010060		State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 06 11 2818

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr
Signature: Isaac Woods
Month Day Year: 06 11 2818

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 06 28 88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

8807 08 0074 2086

05/30/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

05/27/88 Shipper

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A X 9 00 0 3 64 8 3 — Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 87118830

B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: C A D 04 22 4 5 0 01

C. State Transporter's ID 904880

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: C AD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 9189 ORM-A (Flexosolvent)	002	DM	90 (1,50)	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year 10 6 0 1 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ISAAC Woods Jr — Signature: Isaac Woods Jr — Month Day Year 10 6 0 1 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year 10 6 0 1 88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter))

06-30-88 SHIPPER 18835

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX 000 036 483
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87118908
B. State Generator's ID:

5. Transporter 1 Company Name: OEMGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 904878
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLV
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S. NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	010100	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: ALBERT FOIKE
Signature: Albert Foike
Month Day Year: 10 11 13 8 8

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 10 7 13 8 8

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 7 13 5 8

GENERATOR
TRANSPORTER
FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB-No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

07/27/88 Shipper 18202

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A X 0 0 0 03 6 483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87118967
B. State Generator's ID

5. Transporter 1 Company Name
Omega Recovery Services
6. US EPA ID Number C AD 042 245 001
C. State Transporter's ID
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number C A D 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	80	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: FRANK E. HERNANDEZ
Month Day Year: 7 28 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: CHRIS E. MARTINEZ
Signature: Chris E. Martinez
Month Day Year: 7 28 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 7 28 88

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12 pitch typewriter))

11-23-87 SHIPPER 17963

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX0000364 83
Manifest Document No:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA 90701
4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 87119016
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 803785
D. Transporter's Phone: 213/ 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. ORM-A NOS NA 1693 ORM-A (FLEXOSOLVENT)	004	DM	1210	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 11 12 87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 11 12 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 11 12 87

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1-87)
EPA 8700—22
(Rev. 9-87) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

08-12-88 SHIPPER 18202

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX 000 036 483
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87119063
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA REOCVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 904878
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA REOCVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 6980991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	000060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: FRANK E. Hernandez
Signature: [signature]
Month Day Year: 10 8 12 7 8 8

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: [signature]
Month Day Year: 10 8 1 7 8 8

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: [signature]
Month Day Year: 10 8 1 7 8 8

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White, TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)

09-12-88 SHIPPER 20105

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000 036 483 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, , CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87119180

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 904879

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD014224501

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVNET)	003 ~~002~~	DM	01090	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: ALBERT KOIKE — Signature: [signature] — Month Day Year: 09 12 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CIRINGEONI — Signature: [signature] — Month Day Year: 09 12 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 09 12 88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete

White, TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS.
To P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

09-21-88 SHIPPER 18943

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX 000 036 483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15010 SHOEMAKER, , CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87119183
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 010418 754
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD 042 245 001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	001	DM	00030	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: JULIO A. ROSALES
Signature: J. A. Rosales
Month Day Year: 09 12 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. Ciringiano
Signature: Robert J. Ciringiano
Month Day Year: 09 12 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 09 12 88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

ite of California—Health and Welfare Agency
rm Approved OMB No. 2050—0039 (Expires 9-30-88)
ase print or type. (Form designed for use on elite (12-pitch typewriter).

10/05/88 Shipper 19006

Department of Health Services
Toxic Substances Control Divisi n
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 0 0 3 6 4 8 3 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87119222

B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 904879

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 (Flexosolvent)	02	DM	00060	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year: 110107 88

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Robert J CIRINGEONI — Signature: Robert J Ciringeoni — Month Day Year: 110107 88

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 110107 88

2 A (1/87)
1—22
6) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

03/28/2000 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

SHIPPER 20120 10-23-88

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000 036 483
Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 87119280

B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES

6. US EPA ID Number CAD 042 245 001

C. State Transporter's ID 904879

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	010060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: FRANK E. HERNANDEZ
Signature: Frank E. Hernandez
Month Day Year: 10 26 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T. Cibugeoni
Signature: Robert T. Cibugeoni
Month Day Year: 10 26 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by the manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 26 88

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. (Form designed for use on elite (12-pitch typewriter))

11-16-88 SHIPPER 18676

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX000036483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702

4. Generator's Phone 213) 404-3434

A. State Manifest Document Number: 87119433
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 9045878
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
2504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213)698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	012	DM	610	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** *I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.*

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Francisco L. Mata
Signature:
Month Day Year: 11 11 7 8 8

GENERATOR

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature:
Month Day Year: 11 11 7 8 8

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

TRANSPORTER

19. Discrepancy Indication Space

FACILITY

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 11 11 7 8 8

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

11-28-88 SHIPPER 18745

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER., CERRITOS, CA 90702

4. Generator's Phone 213 404-3434

A. State Manifest Document Number 87119437

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001

C. State Transporter's ID 924879

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone (213) 698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	0012	DM	000060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Jose M. Dimas — Signature — Month Day Year 11 20 28 88

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T Cirinigna — Signature — Month Day Year 11 20 28 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD — Signature — Month Day Year 11 20 28 88

DHS 8022 A (1-87)
EPA 8700—22
(Rev 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88)
Please print or type (Form designed for use on elite (12-pitch typewriter).

42 CY Jan. 4, 1987 Shipper 18072

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000013683
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87119560
B. State Generator's ID:

5. Transporter 1 Company Name: Omega Chemical Corp.
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 303785
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Chemical Corp.
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt./Vol.	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	0103	DM	190	C	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: MAX SIEVANOS
Signature: Max Sievanos
Month Day Year: 01 10 88

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 01 10 88

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 01 10 88

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/87)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-88) 12/29/88 SHIPPER #20317

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch typewriter))

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX 000 036 483
Manifest Document No:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 87119619
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 904879
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	010	DM	001/210	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 10/10/89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Ciringeoni
Signature: Robert J Ciringeoni
Month Day Year: 10/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10/10/89

DHS 8022 A (1/87)
EPA 8700—22
(Rev 9-86) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

INSTRUCTIONS ON THE BACK

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000 036 483
Manifest Document No
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
COATINGS RESOURCE
2552 LEE AVENUE, SO. EL MONTE, CA 91733
4. Generator's Phone (818) 579-9000

A. State Manifest Document Number 8 8293421
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042245 001
C. State Transporter's ID 904878
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLAMMABLE LIQUID N.O.S UN 1993 (WASH THINNER)	01	19 DM	000940	G	State / EPA/Other
b. HAZARDOUS WASTE LIQUID N.O.S NA 9189 (OIL)	001	DM	45	G	State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) WASH THINNER
B) WASTE OIL

K. Handling Codes for Wastes Listed Above
a. 01 b. 01 c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: JOHN GARCIA
Signature
Month Day Year 10 11 17 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature
Month Day Year 10 11 17 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature
Month Day Year 10 11 17 89

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

8 8293421

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

SHIPPER 20445 01-25-89

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER., CERRITOS, CA 90702

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 8 8293463

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001

C. State Transporter's ID 904879

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N,O.S NA 1693 (FLEXOSOLVENT)	004	DM	0001120	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature — Month Day Year: 10 11 27 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cirington — Signature — Month Day Year: 10 11 27 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD — Signature — Month Day Year: 10 11 27 89

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

8 8293463

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA X00 0 0 3 6 4 8 8
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15919 Shoemaker, Cerritos, CA
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 8 8293500
B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 904879
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Imega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042245 001
G. State Facility's ID CAD014214501
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	0102	DM	01001610	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
A) Recycle back to customer.

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 10 20 06 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Ciraudani
Signature: Robert J Ciraudani
Month Day Year: 02 20 06 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 20 06 89

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

8 8293500

DHS 8022-A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

03/28/2000 "ORIGINAL MANIFEST COPY"

SHIPPER 20546 02-13-89

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter)*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

8 8293536

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAX000013683
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER., CERRITOS, CA 90702

4. Generator's Phone (213)404-3434

A. State Manifest Document Number: 88293536
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 904879
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	000060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: LUIS TIEKEMARS
Signature: Luis Tiekemars
Month Day Year: 02/15/89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T. Cirugeon
Signature: Robert T. Cirugeon
Month Day Year: 02/15/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 02/15/89

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

SHIPPER 19110 02-27-89

State of California—Health and Wolfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

8 8293578

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER., CERRITOS, CA 90702

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88293578

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 904878

D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD982245901

H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	00060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 10 30 1989

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: JAVIER HERNANDEZ — Signature: [signature] — Month Day Year: 10 30 1989

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 10 30 1989

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

03-16-89 SHIPPER 19226

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.:

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 8 8293668

B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 904880

D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	00060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. D1
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: FRANK E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 03 22 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ROBERT J GRINGRAW
Signature: Robert Gringraw
Month Day Year: 03 22 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 03 22 89

GENERATOR

TRANSPORTER

FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

8 8293668

DHS 8022 A (1/88)
EPA 8700—22
(Rev 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

03-29-89 SHIPPER 19311

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CLAX01 000 864 83 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88293722

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID 904880

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	00960	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the *present and future threat to human health and the environment;* OR, *if I am a small quantity generator, I have made a good faith effort to minimize my waste* generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year 10 4 0 4 8 9

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Robert J Cibulsen — Signature: Robert J. Cibulsen — Month Day Year 10 4 0 4 8 9

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year 10 4 0 4 8 9

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

03/28/2000 "ORIGINAL MANIFEST COPY"

04-17-89 SHIPPER 20659

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 8-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

8 8293780

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAK000068188
Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15919 SHOEMAKER, CERRITOS, CA 90702

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88293780

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245501

C. State Transporter's ID 904880

D. Transporter's Phone (213)698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245501

G. State Facility's ID CAD042245501

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	00060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. D1
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 04 20 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T Cirugeda
Signature: Robert T. Cirugeda
Month Day Year: 04 20 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 04 20 89

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; IN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No. 4 5 1 3 0 1 3
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA. 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88345303
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 208457
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA. 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., NA 1693 (Flexosolvent)	004	DM	00090	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d. a.material for recycle					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
Profile#B10016
*Emergency#213/404-3434

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 1/01/91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/01/91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 1/01/91

DHS 8022 A (1/86)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88345368

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008125298 3
Manifest Document No.: 4 5 3 1 6 1 8
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS,CA. 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88345368
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 208452
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER,CA. 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., NA 1693	007	DM	002000	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a.-Material for Recycle

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
Profile#B10016

*Emergency#213/404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 11 10 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Jav Hernandez
Month Day Year: 11 10 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 11 10 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88345451

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.: 415415 1
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS,CA. 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88345451
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 208451
D. Transporter's Phone: 310/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER,CA. 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD 042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., NA 1693 (Perchloroethylene,N-Butyl Alcohol)	01	DM	001295	G	State 211,212; EPA/Other F001,F003
b.					State; EPA/Other
c.					State; EPA/Other
d.					State; EPA/Other

J. Additional Descriptions for Materials Listed Above
a.-Material for recycle

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
Profile#B10016

*Emergency#213/404-3434

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 11 21 91

GENERATOR

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 11 21 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 11 21 91.

FACILITY

DHS 6022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983 — Manifest Document No. 46409

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA. 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88346409

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES — 6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 110237

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLV.
WHITTIER, CA. 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone (X213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., ORM-A NA 1693 (Flexosolvent)	0018	DM	002410	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a.-Material For Recycle

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information
Profile#B10016 *Emergency#(213)404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; **OR**, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: Frank E. Hernandez — Month Day Year: 10 20 1991

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. Livingston — Signature: Robert J. Livingston — Month Day Year: 10 20 1991

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON — Signature: N. Jay Solomon — Month Day Year: 10 20 1991

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88346409

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

~~8888 0000 0825 0099~~

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88346450

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.: 46450
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS, CA. 90703
4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 88346450
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 203451
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA. 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A, N.O.S. NA 1693 (Flexosolvent)	0103	DM	000184	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a.-Material for disposal

K. Handling Codes for Wastes Listed Above
a. 01.
b.
c.
d.

15. Special Handling Instructions and Additional Information
Profile#B10016 *Emergency#(213) 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 07 16 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 07 16 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 07 16 91.

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 1000 Sacramento CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88346491

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No. 464911
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88346491
B. State Generator's ID

5. Transporter 1 Company Name OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 208452
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	006	DM	001/180	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
emergency contact 213 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 08 01 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cirincione
Signature: Robert J Cirincione
Month Day Year: 08 01 91

TRANSPORTER

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

19. Discrepancy Indication Space

FACILITY

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON
Signature: N. Jay Solomon
Month Day Year: 08 01 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88346554

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD008252983 — Manifest Document No. 46554

2. Page 1 of — Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE, CERRITOS, CA. 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88346554

B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD042245001

C. State Transporter's ID: 208451

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER, CA. 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID: CA0042245001

H. Facility's Phone: 213/6980991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., NA 1693 (Flexosolvent)	005	DM	010130	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a. Material for recycle

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information
Profile#B10016
*Emergency#213/404-3434

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 08/14/91

TRANSPORTER — 17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ — Signature: [signature] — Month Day Year: 08/14/91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

FACILITY — 19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: John Hafte — Signature: [signature] — Month Day Year: 8/15/91

DHS 8022 A (1/86)
EPA 8700—22
(Rev. 9-85) Previous editions are obsolete

Do Not Write Below This Line

a

White: Return this copy to DOHS within 30 days
P.O. Box 3000 Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD008252983 Manifest Document No. 84891

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker Ave., Cerritos, CA. 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88346570

B. State Generator's ID

5. Transporter 1 Company Name
Omega Recovery Services

6. US EPA ID Number CAD042245001

C. State Transporter's ID 208452

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA. 90602

10. US EPA ID Number CAD042245001

G. State Facility's ID CAD042245041

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A, N.O.S., NA 1693 (Perchloroethylene, N-Butyl Alcohol)	005	DM	00112000	G	State 211, 212 EPA/Other F003, F001
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other

J. Additional Descriptions for Materials Listed Above
a. Material to be recycled

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information
Profile #B10016 *Emergency# (213) 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; **OR**, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 10 8 2 8 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cawley
Signature
Month Day Year: 10 8 2 8 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John Hartt
Signature
Month Day Year: 8 29 91

Do Not Write Below This Line

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS to P.O. Box 3000 Sacramento, CA 95812

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88346570

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88346646

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983 — Manifest Document No. 4 6 6 4 6

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS,CA. 90703

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88346646

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 208452

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD.
WHITTIER,CA. 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S., NA 1693	008	DM	00024/0	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a.-Material for recycle

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
Profile#B10016
*Emergency#213/404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 09 12 6 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert Icirwbeow — Signature: [signature] — Month Day Year: 09 12 6 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HACK — Signature: [signature] — Month Day Year: 9 12 4 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento, CA 95812

07-21-89 SHIPPER 15406

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER., CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88614613
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 042385
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXASOLVENT)	002	DM	010010	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: FRANK E. Hernandez
Signature: [signature]
Month Day Year: 07 26 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CIRINEAU
Signature: [signature]
Month Day Year: 07 26 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: [signature]
Month Day Year: 07 26 89

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; within CALIFORNIA CALL 1-800-852-7550

8022 A (1/88)
8700—22
(3-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

08-14-89 SHIPPER 15505

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD008252988 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER., CERRITOS, CA 90703

4. Generator's Phone 213 404-3434

A. State Manifest Document Number 88614738

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES — 6. US EPA ID Number: CAD042245001

C. State Transporter's ID 010384

D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD014222451001

G. State Facility's ID CAD014222451001

H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A n.o.s NA 1693 (FLEXOSOLVENT)	012	DM	000160	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 08 17 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: JAVIER HERNANDEZ — Signature: [signature] — Month Day Year: 08 17 89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 08 17 89

US 8022 A (1/88)
PA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0001 0080

09-07-89 SHIPPER 15580

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000036483
Manifest Document No.:
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER., CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88614793
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 010321
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	005 ~~01 01~~	DM	00150	G	State / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E Hernandez
Signature: [signature]
Month Day Year: 09/1/2589

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T CIANCEOW
Signature: [signature]
Month Day Year: 09/1/2589

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: [signature]
Month Day Year: 09/1/2589

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88614793

Do Not Write Below This Line

DHS 8022 A (1/89)
DTSC 8700—22
(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: C A K 0 0 0 3 6 4 8 3
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, Calif.
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88614855
B. State Generator's ID:

5. Transporter 1 Company Name: Omega Recovery services
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 010289
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM -A NOS NA 1693 ORM-A (Flexosolvent)	002	DM	00060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. D1
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 09 12 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T CIRINGEONI
Signature: Robert T Ciringeoni
Month Day Year: 09 12 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 09 12 89

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; within CALIFORNIA CALL 1-800-852-7550

88614855

DHS 8022 A (1/86)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CA X 0000 36483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 88615329
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110336
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery SErvices
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	002	DM	000160	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01.
b.
c.
d.

15. Special Handling Instructions and Additional Information
A) Recycle back to customer.
Profile No. A-15618

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: X FRANK E. HERNANDEZ
Signature: X Frank E. Hernandez
Month Day Year: 08/01/90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 08/01/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY Solomon
Signature: N. Jay Solomon
Month Day Year: 08/01/90

GENERATOR
TRANSPORTER
FACILITY

IS 8022 A (1/89)
DPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAK 000 036 483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA. 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88615400
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID:
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	004	DM	010120		State 211 / EPA/Other 1002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
K. Handling Codes for Wastes Listed Above: a. b. c. d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A 14464

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: [signature]
Month Day Year: 01 8 2010

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert G. GIRINGEON
Signature: [signature]
Month Day Year: 01 8 2010

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: ~~Frank E. Hernandez~~
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HACTE
Signature: [signature]
Month Day Year: 1 8 22 10

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88615400

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX 000 036 488
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88615478
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991
7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	0515	DM	20150		State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A 14464

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 09 20 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Chiaweoni
Signature: Robert Je
Month Day Year: 09 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON
Signature: N. Jay Solomon
Month Day Year: 09 20 90

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

88615478

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker Ave., Cerritos, CA 90703
4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88615518
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 0422 45 001
C. State Transporter's ID 110336
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 (Flexosolvent)	003	DM	015015	G	State 211, 212 / EPA/Other F001, F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

Profile No. B10016

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; **OR**, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 1/10/90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/10/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 1/10/1990

Do Not Write Below This Line

(1/88)
Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

88615518

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88615544

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.., CERRITOS, CA 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88615544
B. State Generator's ID
C. State Transporter's ID 110236
D. Transporter's Phone 213 698-0991

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	003	DM	000090	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

PROFILE NUMBER B-10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 1/01/90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/01/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John Hacke
Signature
Month Day Year: 1/01/90

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0034 0007

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 86615562
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110236
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	000160	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

PROFILE NUMBER B-10016

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: [signature]
Month Day Year: 1/01/94

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/01/94

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HALTE
Signature: [signature]
Month Day Year: 1/01/94

Do Not Write Below This Line

(1/88)
-22
Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0030 .0082

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88615615
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 110236
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	003	DM	010090	G	State 211, 212 / EPA/Other F001, F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01. b.
c. d.

15. Special Handling Instructions and Additional Information

PROFILE NUMBER B 10016

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 1/10/90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/10/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 1/10/90

Do Not Write Below This Line

(1/88)
-22
Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88675855

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A X 0 0 0 0 3 6 4 8 3 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88675855

B. State Generator's ID:

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 010387

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blve.
Whittier, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD 042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	00080	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

Profile No. 14464

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: FRANK E. HERNANDEZ — Signature: [signature] — Month Day Year: 1/10/1989

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Robert T. CIRINGEONI — Signature: [signature] — Month Day Year: 1/10/1989

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name: — Signature: — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 1/10/1989

Do Not Write Below This Line

DHS 8022 A (1/88)
TSCD—22
(1/88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88675905

IN CASE OF SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CA X0 0 0 0 3 6 4 8 3
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88675905
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 24 5 001
C. State Transporter's ID: 910384
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD 042 245 001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	000440	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: a. 01 b. c. d.

15. Special Handling Instructions and Additional Information
Profile No. 14464

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: FRANK E. HERNandez
Signature: [signature]
Month Day Year: 1/10/89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T CRINKOW
Signature: [signature]
Month Day Year: 1/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: [signature]
Month Day Year: 1/10/89

DTSC 022 A (1/88)
(DTSC—22
(1-88) Previous editions are obsolete.

Do Not Write Below This Line

White: DOH SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88676039

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CA X 0 0 0 3 6483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88676039
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 010352
D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. Whittier Bvld.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	00090	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

Profile No. A14464

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: FM C. Hernandez
Month Day Year: 1/20/89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 1/20/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 1/20/89

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0001 09 0034

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88676146

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000 036488 — Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15916 SHOEMAKER AVE.., CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88676146

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES — 6. US EPA ID Number: CAD042245001

C. State Transporter's ID 010384

D. Transporter's Phone 213/ 698-0991

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD042245001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/ 698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.OS NA 1693 ORM-A (FLEXOSOLVENT)	001	DM	001/210	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A-14464

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 01/15/90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cubinson — Signature: [signature] — Month Day Year: 01/15/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 01/15/90

DHS 6022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

06-08-89 SHIPPER 19488

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88676928

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CIAIXIOIOIOIOI3I6I4I8I3 — Manifest Document No.
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88676928
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CIAIDI0I4I2I2I4I5I0I0I1
C. State Transporter's ID: 010-384
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CIAIDI0I42 24I5I0I0I1
G. State Facility's ID: CADI0I4I2I2I4I5I0I0I1
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	0I0I2	DM	0I0I0I6I0	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. D1 b.
c. d.

15. *Special Handling Instructions and Additional Information*

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 06/13/89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CIRINGEONI — Signature: [signature] — Month Day Year: 06/13/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. *Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19*
Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 06/13/89

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701

4. Generator's Phone ( )

A. State Manifest Document Number: 88676962

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES — 6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 010 384

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	00090	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above: a. 01 b. c. d.

15. Special Handling Instructions and Additional Information
Profile NO. A15618

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature: [signature] — Month Day Year: 05 11 90

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Robert J Ciringeon — Signature: [signature] — Month Day Year: 05 11 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 05 11 90

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88676962

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-85) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88677028

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA XO 0 0 3 6 4 8 3
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker Ave., Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88677028
B. State Generator's ID

5. Transporter 1 Company Name OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 010384
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery SErvices
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	003	DM	00090	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

Profile No. A15618

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 05 25 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Ciringioni
Signature: Robert J Ciringioni
Month Day Year: 05 25 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 05 25 90

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P.O. Box 3000 Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAK 000 036 483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.., CERRITOS, CA. 90701
4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 88677093
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 910589
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD 042 245 201
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O,S NA 1693 (WASTE FLEXOSOLVENT)	003	DM	000910	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A 15618

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 06 11 5 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Ciringione
Signature: Robert J Ciringione
Month Day Year: 06 11 5 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 06 1 5 90

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88677093

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX 000 036 483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS, CA 90701

A. State Manifest Document Number: 88677161

B. State Generator's ID:

4. Generator's Phone (213) 268-4281

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:

E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLEXOSOLVENT N,O,S ORM-A NA 1693	003	DM	00090	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. D1
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A 14464

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: FRANK E. Hernandez — Signature: [signature] — Month Day Year: 06 28 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Ciriaberi — Signature: [signature] — Month Day Year: 06 28 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD — Signature: [signature] — Month Day Year: 06 28 90

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88677161

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX 000 036 483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA 90701

A. State Manifest Document Number: 88677229
B. State Generator's ID:

4. Generator's Phone (213) 268-4281

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 710237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLEXOSOLVENT, ORM-A N.O.S NA 1693	003	DM	00010	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. D1
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A 14464

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 10 7 1 89 0

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. CIRINGEONI
Signature: Robert J. Cir
Month Day Year: 10 7 1 89 0

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 7 1 89 0

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

88677229

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS.
To: P.O. Box 3000, Sacramento, CA 95812.

05/29/2001 "ORIGINAL MANIFEST COPY"

04/26/89 Shipper 20716

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA X 0000 3 8 483
Manifest Document No.

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15919 Shoemaker, Cerritos, CA 90701

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88677330

B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 904878

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (Flexosolvent)	002	DM	00060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 04 07 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 04 07 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 04 27 89

DHS 8022 A (1/86)
PA 6700—22
Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento, CA 95812

03/28/2000 "ORIGINAL MANIFEST COPY"

05/09/89 Shipper 19396

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88677394

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA X0000 364 83
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88677394
B. State Generator's ID

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 910-389
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega RecoveryServices
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM - A NCS NA 1693 ORM-A (Flexosolvent)	002	DM	00060	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
A) Recycle

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name | Signature | Month Day Year 10/5/1989

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cirinegani | Signature | Month Day Year 10/5/1989

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK E Hernandez | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Frank Ford | Signature | Month Day Year 10/5/1989

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White- TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0522-89 SHIPPER 20811

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88677452

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88677452
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID 010384
D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID CAD042245001
H. Facility's Phone (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	000060	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulig — Signature: Tony Skratulig — Month Day Year: 05 26 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CARINGEON — Signature: Robert J Caringeon — Month Day Year: 05 26 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Frank Ford — Signature: FRANK FORD — Month Day Year: 05 26 89

GENERATOR — TRANSPORTER — FACILITY

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

Item 1-5

Shipper 19442

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAKD000086488
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88677505
B. State Generator's ID:

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD042245001
C. State Transporter's ID: 010389
D. Transporter's Phone:

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213-698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A N.O.S. NA 1693 ORM-A (Flammsolvent)	01	DM	0100610		State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature:
Month Day Year: 06 19 89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. Cirinegioni
Signature:
Month Day Year: 06 19 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by the manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 06 19 89

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88677505

DHS 8022 A (1/86)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

Writer TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS To: P.O. Box 3000, Sacramento, CA 95812

8905 19 0089 2128

07-07-89 SHIPPER 15285

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000036483 — Manifest Document No.
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88677598
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
C. State Transporter's ID 010384
D. Transporter's Phone (213) 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID CAD042245001
H. Facility's Phone (213)698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (FLEXOSOLVENT)	002	DM	00055	G	State / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year: 07/11/89

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ — Signature: Javier Hernandez — Month Day Year: 07/10/89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 07/10/89

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88677598

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

8907 14 0089 0800 P.O. Box 3000 Sacramento CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88681472
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245901
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	003	DM	000910		State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01.
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 1/1/2010

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. CIRINEONI
Signature:
Month Day Year: 1/1/2010

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON
Signature: N. Jay Solomon
Month Day Year: 1/1/2010

Do Not Write Below This Line

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

88681472

0078 0017

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88681510

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS, CA 90703

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88681510
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110237
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. WASTE ORM-A N,O,S NA 1693 (FLESOSOLVENT)	008	DM	000990		State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01. b.
c. d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 11 13 2010

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert I. CIRINGEONI
Signature: Robert I. Ciringeoni
Month Day Year: 11 13 2010

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 11 13 2010

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter)

See instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88681558

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.., CERRITOS, CA 90703

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88681558
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110237
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	0013	DM	000010		State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
K. Handling Codes for Wastes Listed Above
a. 01 b.
c. d.

15. Special Handling Instructions and Additional Information

PROFILE NUMBER B 10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 1/21/90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. Crawford
Signature:
Month Day Year: 1/21/90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: John Hatt
Signature:
Month Day Year: 1/24/90

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.,CERRITOS, CA 90703

A. State Manifest Document Number: 88681636
B. State Generator's ID:

4. Generator's Phone (213) 404-3434

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 11237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	009	DM	00970		State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

PROFILE NUMBER B10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 01 09 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: ROBERT J CARPENTER
Signature:
Month Day Year: 10 10 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Gilbert Solomon
Signature:
Month Day Year: 1 1991

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88681636

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88681652

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88681652
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110236
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD014224501
H. Facility's Phone 213 698-0991

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	0101	DM	0100315	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. *Special Handling Instructions and Additional Information*

PROFILE NUMBER B 10016

16.

GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 01 11 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 01 11 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 01 11 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050--0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone (213 404-3434

A. State Manifest Document Number: 88681701
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S ORM-A NA 1693 (FLEXOSOLVENT)	002	DM	5,000		State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: JULIO A ROSALES
Signature: Rosales
Month Day Year: 10 11 28 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CIRINGEON
Signature:
Month Day Year: 10 11 28 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HALTE
Signature:
Month Day Year: 11 12 91

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88681701

DHS 8022 A (1/88)
EPA 8700--22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

05/29/2001 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88681756
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 110237
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA REOCVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLEXOSOLVENT, ORM-A N.O.S NA 1693	006	DM	00180	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 10/21/1991

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cirincion
Signature
Month Day Year: 10/21/1991

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John Hart
Signature
Month Day Year: 10/21/91

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88681756

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88683229

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX000 03648 3 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARAPLATE
15910 Shoemaker, Carritos, CA 90701

4. Generator's Phone (213

A. State Manifest Document Number 88683229

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 010384

D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery SErvices
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A NOS NA 1693 ORM-A (Flexosolvent)	002	DM	000610	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01 b. c. d.

15. Special Handling Instructions and Additional Information

Profile No.

16. *GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name* and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment, OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year 10 20 1990

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Robert J CIBINGEONI — Signature: Robert J Cibingeoni — Month Day Year 10 20 1990

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year 10 20 1990

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550.

88683306

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CA X0 00 0 364 83
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 Shoemaker, Cerritos, CA 90701
4. Generator's Phone (218 404-3434

A. State Manifest Document Number 88683306
B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 010384
D. Transporter's Phone 213/698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste ORM-A NOS NA 1693 ORM-A (FLEXOSOLVENT)	0103	DM	00096	G	State 211 / EPA/Other
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

Profile No.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: FRANK E. HERNANDEZ
Signature: Frank E. Hernandez
Month Day Year: 10 22 6 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J. CIRINGION
Signature
Month Day Year: 10 22 6 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 22 6 90

DHS 8022 A (1/89)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88683364

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000 036 483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER, CERRITOS, CA 90701
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88683364
B. State Generator's ID
C. State Transporter's ID 010 384
D. Transporter's Phone 213 698-0991

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD 014 221 450 01/1
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A NOS NA 1693 ORM-A (FLEXOSOLVENT)	093	DM	00090	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER _____

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 10 31 1990

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T Ciringeoni
Signature: Robert T Ciringeoni
Month Day Year: 10 31 1990

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 10 31 1990

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAX 000 036 483
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE., CERRITOS, CA 90701
4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88683443
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 010384
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER, BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD014224001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A NOS NA 1693 orm-a (FLEXOSOLVENT)	003	DM	00090	G	State 211 / EPA/Other F002
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 03 30 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert Ciriugeoni
Signature: Robert J. Ciriugeoni
Month Day Year: 03 30 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature: Frank Ford
Month Day Year: 03 30 90

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88683443

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX1000 036483
Manifest Document No.:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90701

A. State Manifest Document Number: 88683498
B. State Generator's ID:

4. Generator's Phone: (213) 404-3434

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 010384
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD041245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 ORM-A (WASTE FLEXOSOLVENT)	003	DM	01090	G	State 211 / EPA/Other F001
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER A15618

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: JULIO A ROSALES
Signature: J Rosales
Month Day Year: 04 20 90

GENERATOR

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J Cirinbegni
Signature:
Month Day Year: 04 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: FRANK FORD
Signature:
Month Day Year: 04 20 90

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88683498

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

NOTE: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 982
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703

A. State Manifest Document Number 88684604

B. State Generator's ID

4. Generator's Phone (213 404-3434

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID 110837
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S ORMA-A NA 1693 (FLEXOSOLVENT)	009	DM	001280	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez — Signature — Month Day Year: 03 01 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert J CIRINGEON — Signature — Month Day Year: 03 01 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Frank E. Hernandez — Signature — Month Day Year: 03 01 91

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John Hall — Signature — Month Day Year: 3 3 91

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88684604

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0140 .0042

03/28/2000 "ORIGINAL MANIFEST COPY"

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE.., CERRITOS, CA 90703

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88684665
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110237
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	01/10	DM	02300	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01. b.
c. d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: FRANK E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 03 14 91

GENERATOR

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T. Crinigan
Signature
Month Day Year: 03 14 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

TRANSPORTER

19. Discrepancy Indication Space

FACILITY

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 03 14 91

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88684665

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No. 84704
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88684704
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110236
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAT000422454
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S ORM-A NA 1693 (FLEXOSOLVENT)	001	DM	002105	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
EMERGENCY RESPOND PHONE # 213 404-3434

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: MAX STEVANCS
Signature
Month Day Year: 03 27 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature
Month Day Year: 03 27 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HALTE
Signature
Month Day Year: 3 28 91

GENERATOR — TRANSPORTER — FACILITY

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88684704

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703
4. Generator's Phone 213) 404-3434

A. State Manifest Document Number 88684711
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110237
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	002	DM	000055	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
EMERGENCY RESPOND PHONE NUMBER 213 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Frank E. Hernandez
Signature: Frank E. Hernandez
Month Day Year: 04 01 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 04 01 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HAUTE
Signature:
Month Day Year: 4 1 91

GENERATOR

88684711

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88684801

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983 — Manifest Document No. 88684801
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE ..,CERRITOS, CA 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88684801
B. State Generator's ID:

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID: 110237
D. Transporter's Phone: 213 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:

E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID: CAD042245001
H. Facility's Phone: 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	006	DM	601/180	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
EMERGENCY PHONE NUMBER (213) 404-3434

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year: 10 5 01 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert I Cirinofski — Signature: [signature] — Month Day Year: 10 5 01 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: John HAUTE — Signature: [signature] — Month Day Year: 5 1 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

88684824

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983
Manifest Document No. 84824
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703

4. Generator's Phone (213 404-3434

A. State Manifest Document Number 88684824
B. State Generator's ID

5. Transporter 1 Company Name
OMEGA RECOVERY SERVICES
6. US EPA ID Number CAD 042 245 001
C. State Transporter's ID 110236
D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602
10. US EPA ID Number CAD 042 245 001
G. State Facility's ID CAD042245001
H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	01	07	PM 002100	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01
b.
c.
d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
EMERGENCY PHONE NUMBER 213 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: GARY MITCHELL
Signature: G. R. Mitchell
Month Day Year: 05/16/91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JAVIER HERNANDEZ
Signature: Javier Hernandez
Month Day Year: 05/16/91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON
Signature: N. Jay Solomon
Month Day Year: 05/16/91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88684891

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD 008 252 983
Manifest Document No.: 8 4 8 9 1
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Para Plate
15910 Shoemaker Ave.,Cerritos, CA. 90703
4. Generator's Phone (213) 404-3434

A. State Manifest Document Number: 88684891
B. State Generator's ID:

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD 042 245 001
C. State Transporter's ID: 110237
D. Transporter's Phone: (213) 698-0991

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA. 90602
10. US EPA ID Number: CAD 042 245 001
G. State Facility's ID: CAD042245001
H. Facility's Phone: (213) 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A, N.O.S. , NA 1693 (Perchloroethylene,N-Butyl Alcohol)	15	DM	1160	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
a. - Material to be recycled

K. Handling Codes for Wastes Listed Above
a. 01.
b.
c.
d.

15. Special Handling Instructions and Additional Information
Profile#B10016 *Emergency#(213) 404-3434

16.
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia
Signature: Tony Skratulia
Month Day Year: 05 31 91

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: CHRIS E. MARTINEZ
Signature:
Month Day Year: 05 31 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON.
Signature: N. Jay Solomon
Month Day Year: 05 31 91

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-86) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0012 0029

State of California—Health and Welfare Agency
Form Approved OMB No. 2050—0039 (Expires 9-30-91)
Please print or type. *(Form designed for use on elite (12-pitch typewriter).*

See Instructions on Back of Page 6 and Front of Page 7

Department of Health Services
Toxic Substances Control Division
Sacramento, California

88684913

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD 008 252 983 — Manifest Document No. 84[illegible]

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
PARA PLATE
15910 SHOEMAKER AVE..,CERRITOS, CA 90703

4. Generator's Phone (213) 404-3434

A. State Manifest Document Number 88684913

B. State Generator's ID

5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES

6. US EPA ID Number: CAD 042 245 001

C. State Transporter's ID 110237

D. Transporter's Phone 213 698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
OMEGA RECOVERY SERVICES
12504 E. WHITTIER BLVD
WHITTIER, CA 90602

10. US EPA ID Number: CAD 042 245 001

G. State Facility's ID CAD042245001

H. Facility's Phone 213 698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE ORM-A N.O.S NA 1693 (FLEXOSOLVENT)	001	DM	001/1200	G	State 211,212 / EPA/Other F001,F003
b.					State / EPA/Other
c.					State / EPA/Other
d.					State / EPA/Other

J. Additional Descriptions for Materials Listed Above
A) FOR RECYCLE

K. Handling Codes for Wastes Listed Above
a. 01. b. c. d.

15. Special Handling Instructions and Additional Information
PROFILE NUMBER B 10016
EMERGENCY CONTACT 213 404-3434

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year: 01 01 01 91

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Robert T Cirubello — Signature: [illegible] — Month Day Year: 01 01 01 91

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Tony Skratulia — Signature: Tony Skratulia — Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: N. JAY SOLOMON — Signature: N. Jay Solomon — Month Day Year: 10 16 97 91

GENERATOR — TRANSPORTER — FACILITY

DHS 8022 A (1/88)
EPA 8700—22
(Rev. 9-88) Previous editions are obsolete.

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

0088 .0060