SDMS DOCID # 1150182

Lakewood Oil Service
CAD 009677808 T

BKK Corp
2210 Agusa Ave D
W. Covina
CAD 067786749

Exempt — no 6
get EPA II

2008 as needed from paint sump.

Vapor Degreaser
Vapor 111 Trichlorethan
— used for angle iron cleaning
1 drum / yr.

Sends out patio furniture for powder coating. Small amt. of painting done on premises.

COMPANY NAME: TROPICAL SUN COMPANY	STREET: 12353 WHITTIER	CITY & ZIP: Whittier 90606	DISTRICT: East
OWNER: Pres MALCOM MERRIMAN	PERSON INTERVIEWED & TITLE: ERIC MERRIMAN	PHONE NO. 698-7911 EMERGENCY NO.	NO. EMPLOYEES: 16

L.A. CO. PHL#: 408369	INDUSTRIAL WASTE NO: none	EPA NO.

TYPE OF FACILITY & DESCRIPTION OF OPERATION/PRODUCTS: manufacture metal furniture

SAFETY SHOWER: no
EATING AREA: yes
TOILET & WASHING FACILITIES ADEQUATE: yes
PERSONNEL PROTECTIVE DEVICES ADEQUATE: yes
PLANT SANITATION ADEQUATE: yes

PROCESS	MATERIAL	CONTROL	I.H. HAZARD	HAZARDOUS WASTE TYPE	VOL/LBS.	STORAGE METHOD	DISPOSAL METHOD	MANIFEST IN
Cutting / Bending	→			none				
Painting	paint thinner ~~[illegible]~~ wash wale	respir booth	inhal	liquid ~~[illegible]~~	200g/mg	clarifier	Lakewood Oil Service ~~trash bin~~	009677805

NUMBER OF UNDERGROUND STG TANKS: none
VOLUME & TYPE OF WASTE IN UNDERGROUND TANK:
PRIVATE DISPOSAL SYSTEMS ON PREMISES: YES ___ NO X

ACCESS TO STORM DRAIN INLET ON PREMISES: YES ___ NO X
CHLORINATED HYDROCARBON USED: YES X NO ___
SEWER CONNECTION ON PREMISES: YES X NO ___

REMARKS:

VIOLATIONS:

REFERRAL TO: ACTION: advised SURVEY CONDUCTED BY: B Zile