BNSomers

1263441 - R8 SDMS

SF File Number
11.5

4247700

Drainage pipe* through berm at sump

12/8/92

*Perforated - needs to be replaced

Sweeping seams for patching

12/9/92

Straightening VLDPE prior to welding

12/8/92

Welding Long Seams
12/7/92

Welding Long Seam
12/7/92

Patching a seam
12/9/92

BN Somers
11.5/424700



BN Somers
11.5/424700

BN-Somers 3-0011-410

LTF Construction - 11/92
Retention pond liner
"EEK! It's a mouse"

BN-Somers 3-0011-410

LTF Construction - 11/92
Retention pond liner

BN-Somers 3-0011-410

Retention Pond Liner Installation 11/92

BN Somers
11.5/424700

BN-Somers 3-0011-410

Preliminary Soil Excavation 9/92
- Sanitary lagoon and
RCRA impoundment
pipe excavation.

BN Somers
11.5/4244700

BN-Somers 3-0011-410

Preliminary Soil Excavation 9/92
- Working Tanks

BN-Somers 3-0011-410

LTF Construction - 10/92
Buried drip track
Soil excavation

BN-Somers 3-0011-410

Initial LTF grade stakes 10/92

BN-Somers 3-0011-410

LTF Subgrade - E. berm 10/92

BN-Somers 3-0011-410

LTF Subgrade - SE corner 11/92

BN Somers
11.5/424700



BN Somers
11.5/424700