12.3.8

AGC2F000328

Bob Lowenstein
Fax
575-2959

Quotes: Removal of 26 oil switches at $7426.00 ($286/switch)

So 4 (286 ea) switches = $1144.00 roughly

Charges $2792.00

Markup of cost 44% greater than expected.

PCB XFMR INFO

MAKE SURE TO GET THE REPLACEMENT CAP. IN FOR THE FINISH MILL MOTORS SO WE CAN GET THE CAPS INSTALLED THERE NOW OUT

7426 = X + 264
2792 = X + 44
5634 = 224
Y = 256
264 = 6658
∴ X = 7426 − 6658
X = 750

GET RID OF
PCB CAPS
IN MILL MOTORS

NEW CAPS AVAIL FROM
GE CANADA #1115 EA
10-12 WKS
CONTACT: GE SUPPLY
ED PETERSON
292-6811
AWAITING CONFIRMATION 4/10/91

USEPA SF
1272940