17 4 0030

16957

10/14/92

Beth —

Fred is sending you these pictures from Saad Site as a reenforcement of your conversation yesterday (10/14/92) concerning the source of groundwater contamination

Greg Shaw

FBS



(1) Top three feet of soil/material removed from Franklin Brick trench.

(2) At 5-8 ft moving water was observed flowing, carrying black sludge like oily material with it. The water/sludge material was pumped ~~into~~ off and containerized. However the flow of water continued.

first hole

second hole.

(3) As trenching continued, a second low point was made. The water then flowed to this hole and as the hole was made deeper, flow the the first hole diverted to the second.

3rd hole.

(9) As a third hole was opened the drainage filled with the material of concern

(5) In looking at the trench walls, it was observed that the past levels of the black material had been lowered over time leaving a black residue amongst the soils and rocks.