168C

Film Roll No.: 1 Date: 6/19/90 Time: 1000
Exposure No.: 11 Photographer: JPN
VSI Observations: Entrance to HRI facility with Bldg. A on the right. View - SE

Film Roll No.: 1 Date: 6/19/90 Time: 1010
Exposure No.: 12 Photographer: JPN
VSI Observations: Storage of nonregulated (nonhazardous) waste; empty and reconditioned drums in Bldg. D, north portion. View - NE

R00001776
RCRA Records Center

Film Roll No.: 1 Date: 6/19/90 Time: 1012
Exposure No.: 13 Photographer: JPN
VSI Observations: Sump in elevated tank area, west end of Bldg. D. View - E

Film Roll No.: 1 Date: 6/19/90 Time: 1015
Exposure No.: 14 Photographer: JPN
VSI Observations: Elevated storage tanks in Bldg. D. View - SW

TOP

Film Roll No.: 1 Date: 6/19/90 Time: 1020
Exposure No.: 15 Photographer: JPN
VSI Observations: Sump in sparging area, Bldg. D. View - E

Film Roll No.: 1 Date: 6/19/90 Time: 1025
Exposure No.: 16 Photographer: JPN
VSI Observations: Trench drain sump in truck unloading bay, Process Area. View - W

Film Roll No.: 1 Date: 6/19/90 Time: 1025
Exposure No.: 17 Photographer: JPN
VSI Observations: Storage tanks for flammable wastes, Process Area. View - N



Film Roll No.: 1 Date: 6/19/90 Time: 1025
Exposure No.: 18 Photographer: JPN
VSI Observations: Manifold for tanker truck loading/unloading to Process Area. View - N

Film Roll No.: 1 Date: 6/19/90 Time: 1030
Exposure No.: 19 Photographer: JPN
VSI Observations: Drum staging area south side of Bldg. C. View - W

Film Roll No.: 1 Date: 6/19/90 Time: 1030
Exposure No.: 20 Photographer: JPN
VSI Observations: South central bay, Bldg. C. View - N

TOP

Film Roll No.: 1 Date: 6/19/90 Time: 1040
Exposure No.: 21 Photographer: JPN
VSI Observations: Diked incompatible waste storage area, northeast corner of Bldg. C. View - N

Film Roll No.: 1 Date: 6/19/90 Time: 1040
Exposure No.: 22 Photographer: JPN
VSI Observations: Diked incompatible waste storage area, northcentral portion of Bldg. C. View - N

Film Roll No.: 1 Date: 6/19/90 Time: 1042
Exposure No.: 23 Photographer: JPN
VSI Observations: Incompatible waste storage area, west end of Bldg. C - caustic corrosives. View - SW

Film Roll No.: 1 Date: 6/19/90 Time: 1042
Exposure No.: 24 Photographer: JPN
VSI Observations: Incompatible waste storage area, West end of Bldg. C - acid corrosives. View - NW

Film Roll No.: 1 Date: 6/19/90 Time: 1115
Exposure No.: 25 Photographer: JPN
VSI Observations: Blind sump in Bldg. B. View - E

Film Roll No.: 2 Date: 6/19/90 Time:
Exposure No.: 1 Photographer: JPN
VSI Observations: Blind sump in Bldg. B (duplicate photo). View - E

Film Roll No.: 2 Date: 6/19/90 Time: 1120
Exposure No.: 2 Photographer: JPN
VSI Observations: Two roll-off boxes south of Bldg. D, crushed drum storage. View - N

TOP



Film Roll No.: 2 Date: 6/19/90 Time: 1125
Exposure No.: 3 Photographer: JPN
VSI Observations: Drum crusher between Process Area and Bldg. D. View - N

Film Roll No.: 2 Date: 6/19/90 Time: 1135
Exposure No.: 4 Photographer: JPN
VSI Observations: USPCI gondola for holding (accumulating) dry solids wastes (non-land-banned wastes) with vehicle fueling in left background. View - S

Film Roll No.: 2 Date: 6/19/90 Time: 1315
Exposure No.: 5 Photographer: JPN
VSI Observations: Entrance to HRI facility. View - W

Film Roll No.: 2 Date: 6/19/90 Time: 1315
Exposure No.: 6 Photographer: JPN
VSI Observations: HRI facility sign. View - NW

Film Roll No.: 2 Date: 6/19/90 Time: 1316
Exposure No.: 7 Photographer: JPN
VSI Observations: Derby Refinery property, south & west of HRI property. View - SW

Film Roll No.: 2 Date: 6/19/90 Time: 1316
Exposure No.: 8 Photographer: JPN
VSI Observations: Union Pacific Railroad property, north of HRI property. View - NW

Film Roll No.: 2 Date: 6/19/90 Time: 1330
Exposure No.: 9 Photographer: JPN
VSI Observations: Out-of-service acid repackaging area for Service Chemical Supply Co., Building 17. View - NE

Film Roll No.: 2 Date: 6/19/90 Time: 1345
Exposure No.: 10 Photographer: JPN
VSI Observations: Household waste collection containers and empty containers in Bldg. 18. View - E

Film Roll No.: 2 Date: 6/19/90 Time: 1350
Exposure No.: 11 Photographer: JPN
VSI Observations: Household waste collection, 55-gallon lab packed drums and bagged containers. View - W

Film Roll No.: 2 Date: 6/19/90 Time: 1350
Exposure No.: 12 Photographer: JPN
VSI Observations: Open 55-gallon drums containing household waste collection empty containers. View - N

TOP

Film Roll No.: 2 Date: 6/19/90 Time: 1410
Exposure No.: 13 Photographer: JPN
VSI Observations: Drainageway between Service Chemical Supply Co. property and Union Pacific RR property. (Note surface staining in foreground). View - N

Film Roll No.: 2 Date: 6/19/90 Time: 1415
Exposure No.: 16 Photographer: JPN
VSI Observation: Fence line between SCSC property and drainageway. View - NW to N

Film Roll No.: 2 Date: 6/19/90 Time: 1415
Exposure No.: 17 Photographer: JPN
VSI Observation: Fence line between SCS and drainage way. View - NW to N

Film Roll No.: 2 Date: 6/19/90 Time: 1420
Exposure No.: 18 Photographer: JPN
VSI Observations: Out-of-service muriatic acid storage tank; previously piped into acid repackaging area inside Bldg. 17. Tank now empty. View - E

TOP

Film Roll No.: 2 Date: 6/19/90 Time: 1422
Exposure No.: 19 Photographer: JPN
VSI Observations: Debris-filled former still cooling water sump (Note etching of concrete & bowing of side wall). View - N

Film Roll No.: 2 Date: 6/19/90 Time: 1425
Exposure No.: 20 Photographer: JPN
VSI Observations: NW corner of SCSC property (debris-filled concrete tank area). View - NE

Film Roll No.: 2 Date: 6/19/90 Time: 1410
Exposure No.: 14 Photographer: JPN
VSI Observations: Disassembly of 4 former storage tanks performed by SCSC personnel at northeast corner of SCSC property. View - E

Film Roll No.: 2 Date: 6/19/90 Time: 1415
Exposure No.: 15 Photographer: JPN
VSI Observations: Fence line between SCSC and drainageway.
View - NW to N